### **VOLVO - INSPECTION REPORT**

## Volvo, L90G - Wheel Loaders

#### **Images**





















Comment:

Country: US Date: 05/14/2018 Make: Volvo Serial number: 617643 Matris hours: 5385.8

Dealer: Arnold Machinery Company Inspector: Dave Gibson

Model: L90G Engine S/N: 12055210 Location: Las Vegas Year: 2017 Hours: 5362 Trans S/N: 60053

Comment:

### **General Configuration**

[X] Yes EROPS ] Yes OROPS ] Yes FOPS [X] Yes Steering wheel [ ] Yes Joystick steering [X] Yes Air conditioning [X] Yes Rear camera [X] Yes Standard boom [ ] Yes Reversible fan ] Yes Artic kit [ ] Yes Counter weight handling kit ] Yes Universal attachment plate Comment:

] Yes Auto Lube ] Yes Onboard scale ] Yes Onboard Weight Sys. [X] Yes Auto shift 1 Yes Optishift [X] Yes Boom suspension 1 Yes 3rd function Yes 4th function ] Yes Fuel Heater ] Yes Limited slip axel

[X] Yes Full coverage fenders ] Yes Strobe Light ] Yes Auto Lube System ] Yes Fire Suppression System 1 Yes Mud Flaps **Yes** Recyling arrangement **1 Yes** Forestry arrangement

] Yes Long boom [X] Yes Bucket leveler [X] Yes Quick coupler

# **Operators Station**

Seat and armrest [X] Good Dash and console [X] Good

Floor Board/Mat [X] Good

[X] Good Cab glass

Mirrors [X] Good

Interior light [X] Good Switches [X] Good

Wipers [X] Good

Gauges [X] Good

Hydraulic controls [X] Good

Powertrain controls [X] Good

AC cooling [X] Good

CAB Interior [X] Good

Operators station condition summary

Comment:

### **Outside appearance**

Steps [X] Good Hand rails [X] Good Counterweight / [X] Good

Bumper

Grill [X]Good Hood [X]Good Exhaust stack [X]Good Pre-cleaner bowl [X]Good Front fenders [X]Good Rear fenders [X] Good Fuel tank [X] Good Front frame & welds [X] Good Rear frame & welds [X] Good Sheet metal [X] Good Paint [X] Good

Outside appearance condition summary

paint worn off bucket, paint scarred and chipped on counterweight

Comment: steps bent a little







### Safety condition

Safety decals in place [X] Yes

Operators manual [X] Yes

Safety handles [X] Good

Seat belt	[X] Good
Horn	[X] Good
Back up alarm	[X] Good
Brake hold	[ ] Good [ ] Fair [ ] Poor Remarks:
Turn signals	[X] Good
Hazard lights	[X] Good
ROPS Structure	[X] Good
CAB	[X] Good
Safety condition [summary	
Comment:	
Electrical condition	
Computer	[X] Good
ECM'S	[X] Good
Monitor / Display	[X] Good
Wiring harness's	[X] Good
Key switch	[X] Good
Switches	[X] Good
Lighting	[X] Good
Engine preheater	[X] Good
Batteries / Connections	
Battery disconnect	[X] Good
switch Electrical condition [summary	
Comment: [	
Engine condition	
Oil level OK	[X]Yes
Water in oil	[X] No
Compression in radiator	[X] No
Blow by	[X] No
Engine knocking	[X]No
CE PLATE	[X]Yes
Oil pressure	[X] Good
Oil leaks	[X]No
EPA DECAL	[X]Yes

Turbo charger	[X] Good
Exhaust manifold	[X] Good
Muffler	[X] Good
Fuel injection system	[X] Good
Head gasket	[X] Good
Head	[X] Good
Fan guard	[X] Good
Belts & pulleys	[X] Good
Wiring harness	[X] Good
Starter	[X] Good
Alternator	[X] Good
Seals & gaskets	[X] Good
Engine mounts	[X] Good
Brackets	[X] Good
AC Compressor	[X] Good
Air filters	[X] Good
Engine condition summary	
Comment:	
Cooling system	
Coolant color	Yellow
Radiator	[X] Good
Water pump	[X] Good
Oil cooler	[X] Good
Fan	[X] Good
Fan drive	[X] Good
Hoses	[X] Good
Cooling system summary	
Comment:	
Turnamilari	aliai a
Transmission con	arion
Oil level OK	[X]Yes

Water in oil

Any leaks

[X]No

[X]No

Torque converter	[X] Good
Case	[X] Good
Pump	[X] Good
Hoses	[X] Good
Retarder	[ ] Good [ ] Fair [ ] Poor Remarks:
Shifting forward	[X] Good
Shifting reverse	[X] Good
Transmission summary	
Comment:	
Axels-Final Drives-I	Brakes
Front differential	[X] Good
Rear differential	[X] Good
Differential supports	[X] Good
Drive shafts	[X] Good
UV Joints	[X] Good
Planetaires front	[X] Good
Planetaires rear	[X] Good
Hoses / Lines	[X] Good
Torsion rods	[ ] Good [ ] Fair [ ] Poor Remarks:
Any leaks	[X] No
Holds in park	[ ]Yes [ ]No
Brakes wet	[X]Yes
Holds thru all gears	[X]Yes
Brakes dry	[ ]Yes [ ]No
Brake disk / calipers	[ ] Good [ ] Fair [ ] Poor Remarks:
Brake lines	[X] Good
Seals	[X] Good
Parking brake	[X] Good
Summary [	
Comment:	

# Steering & articulation condition

Steering cylinders	[X] Good
Pumps	[X] Good
Valves	[X] Good
Lines / Hoses	[ X] Good
Secondary steering	[ ] Good [ ] Fair [ ] Poor Remarks:
Steering pins &	[X] Good
bushings	
Steering wheel tilt &	[X] Good
function	
Articulation pins &	[X] Good
bushings	
Summary	
Comment:	
Hydraulics conditi	on
Room cylindors	[ X] Good
Boom cylinders Tilt cylinder	[X] Good [X] Good
Valves	[X] Good
Hoses	[X] Good
Fittings	[X] Good
Tank	[X] Good
Controls	[X] Good
Boom kickout and	[X] Good
bucket level	
Operational Summary	[X] Good
Comment:	
Bucket & other att	tachments
Bucket type / Size	Volvo 102 inch wide
O-valent as	
Coupler type	Volvo
Bucket serial	ID plate is missing
Coupler serial	
Bucket W / Teeth	[X]No
Addtl attachments	
Bolt on smooth	[X]Yes
Bolt on edge	[X] Good
Bucket teeth / Segments	[ ] Good [ ] Fair [ ] Poor Remarks:
Bucket sides	[X] Good
Bucket floor	[X] Good
Bucket bottom	[X] Good

Coupler	[X] Good
Boom / Frame	[X] Good
Boom / Bucket pins & bushings	[X] Good
Summary	
Comment:	
Tires & rims	
Make	Titan
Serial	
% Remaining	100%
Make	Titan
Serial	
% Remaining	100%
Make	Titan
Serial	
% Remaining	100%
Make	Titan
Serial	
% Remaining	100%
Make	
Serial	
% Remaining	
Make	
Serial	
% Remaining	
Recapped	[X] No
Tread cuts	[X] No
Side wall cuts	[X] No
Tire size the same	[X]Yes Remarks:
Overall tire condition	[X] Good
Rims	[X] Good
Lug nuts & studs	[X] Good
Comment:	

## **General Comments**

Legend (5 star rating) [X] 5 Paint general [X] Good

Comment: Optional Paint renewal cost \$3,000.00 only at VCU Center Las Vegas