EC300DL 1164 HRS, 5/N-211084

Volvo Financial Services Pre-Return Inspection Checklist

YES	NO	% Remaining	CAB & BODY	COMMENTS
	VI		Glass Damage	
	V		Seat Damage	
V .			Interior/Exterior damage >\$250	RIP DEAN SCRAtche
V	/		Mechanical/Electrical operational	
/	V		Machine cleaned-interior exterior	TRACKS HAVE MUD
			Bucket free of material	
YES	NO	% Remaining	FRAME	
//			Structurally sound	
V			Pins/bushings > 50%	
VI			Floor plates/chains/screeds > 50%	
\checkmark			Bucket teeth damaged	SHANKS ARE WORN
			Drums damaged	
			Isolator > 50%	
VEC	NO	0/ Demoining	SYSTEMS	
YES	NO	% Remaining		
V			Cooling, heating, lube systems operational	
V			Fluids @ operating levels	
V			Filter caps in place	
V			Batteries hold charge	
V			Filters OK	
			Pavers-all wear items > 50%	
YES	NO	% Remaining	TIRES	
			Matching radials	
			Brakes >50%	
		1	Brakes damaged/cracked	
			Rubber tracks >50%	
		1	ET De L	
YES	NO	% Remaining	MECHANICAL DRIVE	
\checkmark			Operational with no vibrations	
YES	NO	% Remaining	ELECTRIC DRIVE	
			Drive system > 50%	
		1	Harnesses operational, not leaking	
			Gauges, senders, switches operational	
l		1		
YES	NO	% Remaining	UNDERCARRIAGE	
VI			Sprockets, idlers, carriers, track rollers > 50%	
V			Links, bogies, pins/bushings > 50%	
			Track shoes/pads > 50%	

YES	NO	% Remaining	ENGINE	
	V/		Excesive smoke	
1	V		Leaks or blowby	
\checkmark			DPF/Regen operational	

Pre-Return Inspection Checklist-page 2

YES NO	NO	% Remaining	BOOMS			
			Damaged & within mfg. specs	LIFT	EVE ON STIC	L BEN
			Rigging in place		l	
						_
YES	NO	% Remaining	HYDRAULICS			
			Pumps, valve, cylinders fully operational			
	V		Pumps, valve, cylinders leaking			
YES	NO	% Remaining	AIR CONDITIONING			
V			All components fully operational			
YES	NO	% Remaining	RPOS/FPOS			
			Free of any damage or reairs			
			Brakes >50%			
			Brakes damaged/cracked			
			Rubber tracks >50%			