VOLVO - INSPECTION REPORT

Volvo, A40G - Articulated haul trucks

Images















_						
('n.	m	m	Р	n	г

Comment:

Country: US Date: 06/06/2019 Make: Volvo Serial number: 341153

Trans S/N: 1700106540

Dealer: Ascendum Machinery, Inc.

Inspector: Model: A40G Engine S/N: 92939 Location: Asheville Year: 2019 Hours: 6513

Matris hours: 6558.6

Equipped Configuration

[X]Yes Standard Cab
[] Yes Water Tank
[] Yes LED Light
[X] Yes Strobe Light
[] Yes Hydraulic switch control
[X] Yes Hydraulic lever control
[] Yes Auto Lube System
[] Yes Fire Suppression System
[X] Yes Mud Flaps

] Yes Low Profile Cab [X] Yes Standard Body [] Yes Extra Spill Guard 1 Yes Exhaust Body Heat [X] Yes Overhung Tailgate] Yes Underhung Tailgate] Yes Underground ARRG.

[] Yes Scraper ARRG.

] Yes Fuel Heater **] Yes** Full Suspension] Yes Frame Ext.] Yes Onboard Weight Sys. 1 Yes Bed Liner Metal] Yes Bed Liner Plastic [X] Yes Back Up Camera

[] Yes Fast Fuel

RH Front mud flap has a cut. Comment:

Operators Station

Seats and armrest [X] Good

[X] Fair Remarks: Bed Lowering light next to hydraulic lever is cracked. Dash and console

Floor Board/Mat [X] Good

Cab glass [X] Good

Mirrors [X]Good

Interior light [X]Good Switches [X] Good

Wipers [X] Good

Gauges [X] Good

Hydraulic controls [X] Good

Powertrain controls [X] Good

AC cooling [X] Good

CAB Interior [X] Good

Operators station condition summary

Comment:







Outside appearance

Steps	[X] Good
Hand rails	[X] Good
Counterweight /	[X] Good
Bumper	
Grill	[X] Good
Hood	[X] Good
Exhaust stack	[X] Good
Pre-cleaner bowl	[X] Good
Front fenders	[X] Good
Hyd tank	[X] Good
Fuel tank	[X] Good
Def tank	[X] Good
Front frame & welds	[X] Good
Rear frame & welds	[X] Good
Sheet metal	[X] Good
Paint	[X] Fair Remarks: surface rust under tailgate
Outside appearance condition summary	

Safety condition

Back up alarm

Comment:

Safety decals in place [X] Yes

Operators manual [X] Yes

Safety handles [X] Good

Seat belt [X] Good

Horn [X] Good

[X] Good

Brake lights	[X] Good
Turn signals	[X] Good
Hazard lights	[X] Good
ROPS Structure	[X] Good
CAB	[X] Good
Safety condition summary	
Comment:	
Electrical condition	
Computer	[X] Good
ECM'S	[X] Good
Monitor / Display	[X] Good
Wiring harness's	[X] Good
Key switch	[X] Good
Switches	[X] Good
Lighting	[X] Good
Engine preheater	[X] Good
Batteries / Connections	
Battery disconnect	[X] Good
switch	
Electrical condition summary	
Comment:	
Comment.	
Engine condition	
Oil level OK	[X]Yes
Water in oil	[X] No
Compression in radiator	[X] No
Blow by	[X]No
Engine knocking	[X] No
CE PLATE	[X] Yes
Oil pressure	[X] Good
Oil leaks	[X] No
EPA DECAL	[X]Yes
Turbo charger	[X] Good
Exhaust manifold	[X] Good
Muffler	[X] Good

Fuel injection system [X] Good [X]Good Head gasket Head [X]Good Fan guard [X]Good [X]Good Belts & pulleys Wiring harness [X]Good Starter [X]Good Alternator [X]Good Seals & gaskets [X]Good Engine mounts [X]Good **Brackets** [X]Good AC Compressor [X]Good

Engine condition summary

Comment:

Air filters





[X]Good





Cooling system

Coolant color	Red			
Radiator	[X] Good			
Water pump	[X] Good			
Oil cooler	[X] Good			
Fan	[X] Good			
Fan drive	[X] Good			
Hoses	[X] Good			
Cooling system summary				
Comment:				
Commont.	L			



Transmission condition

Oil level OK [X]Yes Water in oil [X]No Any leaks [X]No Torque converter [X]Good Case [X] Good Pump [X]Good Hoses [X]Good Retarder [X]Good Transfer case [X]Good Shifting forward [X] Good [X] Good Shifting reverse Transmission summary



Comment:

Axels-Final Drives-Brakes

Front differential [X] Good

Center differential [X] Good

Rear differential [X] Good

Differential supports [X] Good

Drive shafts [X] Good

UV Joints [X] Good

Planetaires front	[X] Good	
Planetaires center	[X] Good	
Planetaires rear	[X] Good	
Hoses / Lines	[X] Good	
Torsion rods	[X] Good	
Holds in park	[X]Yes	
Brakes wet	[X]Yes	
Holds thru all gears	[X]Yes	
Brakes dry	[X]No	
Brake disk / calipers	[X] Good	
Brake lines	[X] Good	
Seals	[X] Good	
Parking brake	[X] Good	
Summary		
Comment:]
CONTINUE.		1
Steering & articula	tion condition	
Steering cylinders	[X] Good	
Pumps	[X] Good	
Valves	[X] Good	
Lines / Hoses	[X] Good	
Secondary steering	[X] Good	
Steering pins & bushings	[X] Good	
Steering wheel tilt &	[X] Good	
function		
Articulation pins &	[X] Good	
bushings		
Summary		_
0		1
Comment:		ļ
Hydraulics condition	n	_
Bed lift cylinders	[X] Good	
Pumps	[X] Good	
Valves	[X] Good	
Hoses	[X] Fair Remarks: main hydraulic hoses from back of cab to bed have dry rot cracks.	
Fittings	[X] Good	
Tank	[X] Good	
Controls	[X] Good	
Bed float	[X] Good	
Operational condition	[X] Good	
Summary		-

Comment:	
Bed & other attac	chments
Bed type / Size	
Tailgate S / N	
Bed serial	
Addtl attachments	
Spill guard	[] Good [] Fair [] Poor Remarks:
Body	[X] Good
Bed liner	[] Good [] Fair [] Poor Remarks:
Bed sides	[X] Good
Bed floor	[X] Good
Wear plates	[X] Good
Tailgate	[X] Good
Pins & bushings	[X] Good
Summary	
Comment:	
Tires & rims	
Make	michelin
Serial	WE2921G2A
% Remaining	85%
Make	michelin
Serial	WE291G4A
% Remaining	85%
Make	michelin
Serial	WE2920G3A
% Remaining	
	80%
Make	michelin
Serial	IVE2167G6A
% Remaining	80%
Make	michelin
Serial	WE2917G6A
% Remaining	80%
Make	michelin
Serial	WE2943G0A

Recapped	[X]No
Tread cuts	[X]No
Side wall cuts	[X]No
Tire size the same	[X] Yes Remarks: Michelin 29.5 R 25 E3
Overall tire condition	[X] Good
Rims	[X] Good
Lug nuts & studs	[X] Fair Remarks: Missing 14 plastic lug nut caps
Comment:	













General Comments

Legend (5 star rating) Paint general	[]5 []4 []3 []2 []1 []Good []Fair []Poor Remarks:
Comment:	