Lessee: Texas Sterling Construction Co.

Unit: 2014 Volvo L90G

UNIT # 7156 Location: Romco Equipment, Carmine TX



SPECIFICATIONS

VIN	7156
LeaseInspector ID #	7156
Year	2014
Model	Volvo L90G
Location City	Carmine
Location State	TX
General Specifications	
Tires	
Front Tire Size	
Rear Tire Size	
Lt Front Tire Manu	
Lt Front Tread Depth	23
Rt Front Tire Manu	
Rt Front Tread Depth	15
Lt Rear Tire Manu	
Lt Rear Tread Depth	17
Rt Rear Tire Manu	
Rt Rear Tread Depth	12
New Hours	6907
Old Hours	6906

http://leaseinspector.com/Creditor/PrintAsset.asp?120196

Contract: 502-7649108-001

Lessee: Texas Sterling Construction

Unit: 2014 Volvo L90G

UNIT # 7156 Location: Romco Equipment, Carmine TX

ADDITIONAL FEATURES OF THIS VEHICLE

COMMENTS

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes Overall: Fair

http://leaseinspector.com/Creditor/PrintAsset.asp?120196

Total

Lessee: Texas Sterling Construction Unit: 2014 Volvo L90G UNIT # 7156
Co.
Contract: 502-7649108-001 Unit: 2014 Volvo L90G UNIT # 7156
Location: Romco Equipment,
Carmine TX

DEFICIENCY REVIEW

\$0.00

ITEM	QTY PRICE	
 Oil Seep Under Rear Engine, Hose Seeping 	\$0.00	
2. Service Machine if Due- Not Due	\$0.00	
 Clean Machine Inside and Out, Engine- Repaired 	\$0.00	
4. Replace 4 Tires with Matching 50% or Better- Not Repaired	\$0.00	
5. Glove Box Lock Missing- Replaced	\$0.00	
6. Bucket Edge Worn- Replaced	\$0.00	
7. Rear Work Light on in Reverse- Not	\$0.00	

Repaired	
8. 1 Broken Vent Louver- Replaced	\$0.00
9. Missing Radio- Not Replaced	\$0.00
10. Left Front Fender Damaged, Front Piece Cut Off- Not Replaced	\$0.00
11. Cab Cap Missing Hardware- Not Replaced	\$0.00
12. Left Fender Step Bent- Repaired	\$0.00
13. Engine Steps Bent/Damaged- Left Repaired, Right Not Repaired	\$0.00

http://leaseinspector.com/Creditor/PrintAsset.asp?120196

Lessee: Texas Sterling Construction

Unit: 2014 Volvo L90G

UNIT # 7156 Location: Romco Equipment, **Carmine TX**



http://leaseinspector.com/Creditor/PrintAsset.asp?120196

Lessee: Texas Sterling Construction Co. Contract: 502-7649108-001

Unit: 2014 Volvo L90G

UNIT # 7156 Location: Romco Equipment, Carmine TX




http://leaseinspector.com/Creditor/PrintAsset.asp?120196

Lessee: Texas Sterling Construction Co. Contract: 502-7649108-001

Unit: 2014 Volvo L90G

UNIT # 7156 Location: Romco Equipment, Carmine TX



http://leaseinspector.com/Creditor/PrintAsset.asp?120196

Lessee: Texas Sterling Construction Co. Contract: 502-7649108-001

Unit: 2014 Volvo L90G

UNIT # 7156 Location: Romco Equipment, Carmine TX



http://leaseinspector.com/Creditor/PrintAsset.asp?120196

Lessee: Texas Sterling Construction Co. Contract: 502-7649108-001 UNIT # 7156 Location: Romco Equipment, Carmine TX Unit: 2014 Volvo L90G

http://leaseinspector.com/Creditor/PrintAsset.asp?120196

Lessee: Texas Sterling Construction Co. Contract: 502-7649108-001 UNIT # 7156 Location: Romco Equipment, Carmine TX Unit: 2014 Volvo L90G

http://leaseinspector.com/Creditor/PrintAsset.asp?120196

Lessee: Texas Sterling Construction Co. Contract: 502-7649108-001

Unit: 2014 Volvo L90G

UNIT # 7156 Location: Romco Equipment, Carmine TX



http://leaseinspector.com/Creditor/PrintAsset.asp?120196