

Lessee: Saiia Construction LLC  
Contract: 502-7606043-029

Unit: 2015 Volvo EC300EL

UNIT # VCEC300ELE0310133  
Location: Cowin Equipment,  
Birmingham AL



### SPECIFICATIONS

Serial Number	VCEC300ELE0310133
LeaseInspector ID #	310133
Year	2015
Model	Volvo EC300EL
Location City	Birmingham
Location State	AL

3/12/2018

LeaseInspector Off-Lease

Lessee: Saiia Construction LLC  
Contract: 502-7606043-029

Unit: 2015 Volvo EC300EL

UNIT # VCEC300ELE0310133  
Location: Cowin Equipment,  
Birmingham AL

ADDITIONAL FEATURES OF THIS VEHICLE  
COMMENTS

Appraiser Comments:

Creditor Comments:  
Hours: 6052

Public Comments:  
Hours: 6052

Starts/Runs: Yes  
Overall: Fair

Lessee: Saiia Construction LLC  
 Contract: 502-7606043-029

Unit: 2015 Volvo EC300EL

UNIT # VCEC300ELE0310133  
 Location: Cowin Equipment,  
 Birmingham AL

### DEFICIENCY REVIEW

ITEM	QTY	PRICE
1. Boom Pins Have Slightly Movement - Not Repaired		\$0.00
2. Repair Cross Frame Bottom Flange Bent/Weld Cracked - Chain Loops Bent - Not Repaired		\$0.00
3. Clean Machine Inside & Out -Not Done		\$0.00
4. Service Machine If Due - Not Due		\$0.00
5. Air Cleaners Dirty - Replaced		\$0.00
6. 2 Left/2 Right Final Drive Housing Cover Plate Bolts Missing - Repaired		\$0.00
7. Repair Left Side Of Valve Body - Leaking - Not Repaired		\$0.00
8. Repair Distribution Block In Pump Drive Compartment - Leaking/Collecting - Not Repaired		\$0.00
9. Repair Boom Control Joystick Erratic Operation - Repaired		\$0.00
10. Bucket Extender Pin Protruding - Not Repaired		\$0.00
11. Repair Damaged Grease Line At Boom/Stick Joint Area - Repaired		\$0.00
12. Repair Bit Seal Area Leaking - Not Repaired		\$0.00
13. Repair Line Input Area Leaking - Repaired		\$0.00
14. Repair Hydraulic Line Leaking - Repaired		\$0.00
15. Replace Missing Bolt On Cover Panel - Replaced		\$0.00
16. Repair Bolts Used For Pin Stops - Not Repaired		\$0.00
17. Repair Multiple Pads Loose On Both Tracks - 1 Bolt Missing - Not Repaired		\$0.00
18. Replace 1 Left Track Pad - Not Replaced		\$0.00
19. Replace Right Carrier Roller Bolt Missing - Not Repaired		\$0.00
20. Replace Right Front Mirror Missing - Replaced		\$0.00
21. Repair Both Arm Rest Consoles Damaged - Replaced		\$0.00
22. Repair Both Sides Or Car Body Damaged - Not Repaired		\$0.00
23. Repair All Track Steps Bent - Not Repaired		\$0.00
Total		\$0.00

Lessee: Saiia Construction LLC  
Contract: 502-7606043-029

Unit: 2015 Volvo EC300EL

UNIT # VCEC300ELE0310133  
Location: Cowin Equipment,  
Birmingham AL









Lessee: Saiia Construction LLC  
Contract: 502-7606043-029

Unit: 2015 Volvo EC300EL

UNIT # VCEC300ELE0310133  
Location: Cowin Equipment,  
Birmingham AL













Lessee: Saiia Construction LLC  
Contract: 502-7606043-029

Unit: 2015 Volvo EC300EL

UNIT # VCEC300ELE0310133  
Location: Cowin Equipment,  
Birmingham AL





Lessee: Saiia Construction LLC  
Contract: 502-7606043-029

Unit: 2015 Volvo EC300EL

UNIT # VCEC300ELE0310133  
Location: Cowin Equipment,  
Birmingham AL









Lessee: Saiia Construction LLC  
Contract: 502-7606043-029

Unit: 2015 Volvo EC300EL

UNIT # VCEC300ELE0310133  
Location: Cowin Equipment,  
Birmingham AL

