Lessee: JP Contracting
Contract: 502-7543220-025

Unit: 2018 Volvo A45G

UNIT # 342300
Location: ASC Construction Equipment, Buford GA

SPECIFICATIONS

VIN	342300
LeaseInspector ID #	342300
Year	2018
Model	Volvo A45G
Location City	Buford
Location State	GA
General Specifications	
Tires	
Lt Front Tire Manu	Michelin
Lt Front Tread Depth	38
Rt Front Tire Manu	Michelin
Rt Front Tread Depth	32
Lt Rear Tire Manu	Michelin
Lt Rear Tread Depth	41
Rt Rear Tire Manu	Michelin
Rt Rear Tread Depth	44
Lt Rear Rear Tire Manufacture	Michelin
Lt Rear Rear Tread Depth	40
RT Rear Rear Tire Manufacture	Michelin
Rt Rear Rear Tread Depth	40
New Hours	3951
Old Hours	3949

Lessee: JP Contracting
Contract: 502-7543220-025

Unit: 2018 Volvo A45G

UNIT # 342300
Location: ASC Construction Equipment, Buford GA

ADDITIONAL FEATURES OF THIS VEHICLE

COMMENTS

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes
Overall: Fair

Lessee: JP Contracting
Contract: 502-7543220-025

Unit: 2018 Volvo A45G

UNIT # 342300
Location: ASC Construction Equipment, Buford GA

DEFICIENCY REVIEW

ITEM	QTY PRICE
1. Front Skid Plate Missing the Protects Bottom of Engine- Repaired	$0.00
2. Clean Machine Inside, Out, Engine, Undercarriage- Done	$0.00
3. Dealer to Determine is Service is Due- Serviced	$0.00
4. Dealer to Verify Tire Cuts are Cosmetic Only- Verified	$0.00
5. Bed Side Cables Missing- Replaced	$0.00
6. All Tires Cut, 3 Past 50%- 3 Tires Replaced, Cuts Cosmetics	$0.00
7. Blower Motor Switch Damaged- Repaired	$0.00
8. Batteries Dead- Repaired	$0.00
9. Oil Pan Drain Plug Leaks- Repaired	$0.00
10. Oil Low- Repaired	$0.00
11. Low Brake Cooling Oil Lights On- Repaired	$0.00
12. Air Cleaner Dirty- Repaired	$0.00
13. Rear Facing Front Lights Inop- Repaired	$0.00
14. Body Bottom Floor and Rear Edge Damaged- Not Repaired	$0.00
Total	**$0.00**

Lessee: JP Contracting
Contract: 502-7543220-025

Unit: 2018 Volvo A45G

UNIT # 342300
Location: ASC Construction Equipment, Buford GA



Lessee: JP Contracting
Contract: 502-7543220-025

Unit: 2018 Volvo A45G

UNIT # 342300
Location: ASC Construction Equipment, Buford GA

Lessee: JP Contracting
Contract: 502-7543220-025

Unit: 2018 Volvo A45G

UNIT # 342300
Location: ASC Construction Equipment, Buford GA

Lessee: JP Contracting
Contract: 502-7543220-025

Unit: 2018 Volvo A45G

UNIT # 342300
Location: ASC Construction Equipment, Buford GA



Lessee: JP Contracting
Contract: 502-7543220-025

Unit: 2018 Volvo A45G

UNIT # 342300
Location: ASC Construction Equipment, Buford GA