Lessee: JP Contracting
Contract: 502-7543220-018

Unit: 2014 Volvo EC480EL

UNIT # 310057
Location: ASC Construction Equipment, Buford GA

SPECIFICATIONS

VIN	310057
LeaseInspector ID #	310057
Year	2014
Model	Volvo EC480EL
Location City	Buford
Location State	GA
General Specifications	
New Hours	6131
Old Hours	6125

ADDITIONAL FEATURES OF THIS VEHICLE

COMMENTS

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes
Overall: Fair

Lessee: JP Contracting
Contract: 502-7543220-018

Unit: 2014 Volvo EC480EL

UNIT # 310057
Location: ASC Construction Equipment, Buford GA

DEFICIENCY REVIEW

ITEM	QTY PRICE	ITEM	QTY PRICE
1. Clean Machine Inside and Out, Engine, Undercarriage- Not Done	$0.00	40. Dead Batteries- Not Replaced- Repaired Per Email 2/15/19	$0.00
2. Service Machine if Due-Not Repaired- 500 Hour Service Performed Per Email 2/15/19	$0.00	**Total**	**$0.00**
3. Low Coolant- Repaired	$0.00		
4. Fluid Collection Around Valve Cover- Repaired Per Email 2/15/19	$0.00		
5. Fluid Collection Arond EGR Cooler- Not Repaired-Repaired Per Email 2/15/19	$0.00		
6. Engine Oil Collection at Filter Housing- Repaired	$0.00		
7. Broken Cooling Cowl Mount in Engine Compartment- Repaired	$0.00		
8. Right Planet Housing Cover Damaged and Missing Mount Bolt- Replaced	$0.00		
9. 1 Hydraulic Stick Hose Missing, 1 Damaged- Replaced	$0.00		
10. Stick Cylinder Leaking- Repaired	$0.00		
11. Hydraulic Fluid Level Low- Repaired	$0.00		
12. Hydraulic Fluid on Belly Pan- Repaired	$0.00		
13. Hydraulic Fluid Tank Cap Missing- Repaired	$0.00		
14. Several Broken Grease Hoses- Repaired	$0.00		
15. Loose Track Pads-Repaired	$0.00		
16. All Track Frame Steps Gone and Fab Steps Welded On- Not Repaired	$0.00		
17. Bottom Roller Right Side 8-9 Bad- Repaired Per Email 2/15/19	$0.00		
18. Glass Lock Latch on Door Slider Broken- Replaced	$0.00		
19. Missing Engine Enclosure Missing Mount Bolts and Frame Cracks- Bolts Replaced, Frame Cracked	$0.00		
20. Steps at Toolbox Bent- Not Repaired	$0.00		
21. 4 Belly Pans Missing- Repaired	$0.00		
22. Belly Pan Mount Areas and Frame Damaged- Not Repaired	$0.00		
23. Console Switches Not Mounted- Repaired	$0.00		
24. Ignition Switch Muont Broken in Console- Repaired	$0.00		
25. Screen is Blue- Repaired	$0.00		
26. Rear View Camera Mount Damaged- Repaired	$0.00		
27. Tracks Too Tight Link Grinding- Not Repaired	$0.00		
28. Sprockets Very Worn- Not Repaired- Not Required Repaired Per Email 2/15/19	$0.00		
29. Arm Stick and Bucket Missing- Replaced	$0.00		
30. Install Stick - Replaced	$0.00		
31. Bucket Sides Worn- Replaced	$0.00		
32. Bucket Cylinder Repaired	$0.00		
33. Grease Lines Unhooked for Auto Lube at Boom- Repaired	$0.00		

34. Cover Over Master Switch Side of Seat- Repaired	$0.00
35. Clamps Missing from Bucket Cylinder- Replaced	$0.00
36. Bucket/Stick Pins Missing- Replaced	$0.00
37. Nut Loose for Stick Pin- Repaired	$0.00
38. Grease Block at Swing Bearing Broke Fitting- Replaced	$0.00
39. Perfomed A500H Service- Serviced- Not Done	$0.00

Lessee: JP Contracting
Contract: 502-7543220-018

Unit: 2014 Volvo EC480EL

UNIT # 310057
Location: ASC Construction Equipment, Buford GA



Lessee: JP Contracting
Contract: 502-7543220-018

Unit: 2014 Volvo EC480EL

UNIT # 310057
Location: ASC Construction Equipment, Buford GA



Lessee: JP Contracting
Contract: 502-7543220-018

Unit: 2014 Volvo EC480EL

UNIT # 310057
Location: ASC Construction Equipment, Buford GA

Lessee: JP Contracting
Contract: 502-7543220-018

Unit: 2014 Volvo EC480EL

UNIT # 310057
Location: ASC Construction Equipment, Buford GA

Lessee: JP Contracting
Contract: 502-7543220-018

Unit: 2014 Volvo EC480EL

UNIT # 310057
Location: ASC Construction Equipment, Buford GA

Lessee: JP Contracting
Contract: 502-7543220-018

Unit: 2014 Volvo EC480EL

UNIT # 310057
Location: ASC Construction Equipment, Buford GA



Lessee: JP Contracting
Contract: 502-7543220-018

Unit: 2014 Volvo EC480EL

UNIT # 310057
Location: ASC Construction Equipment, Buford GA

Lessee: JP Contracting
Contract: 502-7543220-018

Unit: 2014 Volvo EC480EL

UNIT # 310057
Location: ASC Construction Equipment, Buford GA

Lessee: JP Contracting
Contract: 502-7543220-018

Unit: 2014 Volvo EC480EL

UNIT # 310057
Location: ASC Construction Equipment, Buford GA

Lessee: JP Contracting
Contract: 502-7543220-018

Unit: 2014 Volvo EC480EL

UNIT # 310057
Location: ASC Construction Equipment, Buford GA