

Lessee: Arcilla Mining
Contract: 502-5041768-045

Unit: 2016 Volvo A40G

UNIT # 341223
Location: ASC Construction
Equipment, Cayce SC



SPECIFICATIONS

VIN	341223
LeaseInspector ID #	341223
Year	2016
Model	Volvo A40G
Location City	Cayce
Location State	SC
New Hours	4235
Old Hours	4233

Lessee: Arcilla Mining
Contract: 502-5041768-045

Unit: 2016 Volvo A40G

UNIT # 341223
Location: ASC Construction
Equipment, Cayce SC

ADDITIONAL FEATURES OF THIS VEHICLE
COMMENTS

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes

Overall: Fair

Lessee: Arcilla Mining
Contract: 502-5041768-045

Unit: 2016 Volvo A40G

UNIT # 341223
Location: ASC Construction
Equipment, Cayce SC


DEFICIENCY REVIEW

ITEM	QTY PRICE
1. ArticulationPB Repair Bottom Bushing Damaged- Repaired	\$0.00
2. Tail Gate Replace Missing Bolt and Bend in Gate- Replaced	\$0.00
3. Front Spill Guard Repair Bend/Dent- Not Repaired	\$0.00
4. Armrest Left Damaged Repair- Replaced	\$0.00
5. Repair Leak Left Rear of Engine- Repaired	\$0.00
6. Repair Coolant Level Low- Repaired	\$0.00
7. Repair Leak at Wiring Harness Input- Repaired	\$0.00
8. Repair Exhaust Leak at EGR Cooler- Repaired	\$0.00
9. Repair Leak at Right Rear Lower of Engine- Repaired	\$0.00
10. Tires Cut- Verified	\$0.00
11. Repair Left Damaged- Not Repaired	\$0.00
12. Repair OBD Connector Loose- Repaired	\$0.00
13. Repair Right Air Intake Tube Damaged- Replaced	\$0.00
14. Repair Check SCR System Fault- Repaired	\$0.00
15. Repair Fuel Injection System Warning- Repaired	\$0.00
16. Repair Regen Light On- Repaired	\$0.00
17. Remove Vinyl Stickers- Removed	\$0.00
18. Clean Machine Inside and Out- Cleaned	\$0.00
Total	\$0.00

Lessee: Arcilla Mining
Contract: 502-5041768-045

Unit: 2016 Volvo A40G




UNIT # 341223
Location: ASC Construction
Equipment, Cayce SC



Lessee: Arcilla Mining
Contract: 502-5041768-045

Unit: 2016 Volvo A40G

UNIT # 341223
Location: ASC Construction
Equipment, Cayce SC



Lessee: Arcilla Mining
Contract: 502-5041768-045

Unit: 2016 Volvo A40G

UNIT # 341223
Location: ASC Construction
Equipment, Cayce SC



Lessee: Arcilla Mining
Contract: 502-5041768-045

Unit: 2016 Volvo A40G

UNIT # 341223
Location: ASC Construction
Equipment, Cayce SC

