

Lessee: Romco Equipment
Contract: Romco Equipment

Unit: 2013 Volvo L60G

UNIT # 1603
Location: Romco Equipment Co, LP,
Round Rock TX



SPECIFICATIONS

VIN	1603
LeaseInspector ID #	1603
Year	2013
Model	Volvo L60G
Location City	Round Rock
Location State	TX
Hours Dash	7123
Hours	6734

3/9/2018

LeaseInspector Off-Lease

Lessee: Romco Equipment
Contract: Romco Equipment

Unit: 2013 Volvo L60G

UNIT # 1603
Location: Romco Equipment Co, LP,
Round Rock TX

ADDITIONAL FEATURES OF THIS VEHICLE
COMMENTS

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes
Overall: Fair

Lessee: Romco Equipment
 Contract: Romco Equipment

Unit: 2013 Volvo L60G

UNIT # 1603
 Location: Romco Equipment Co, LP,
 Round Rock TX


DEFICIENCY REVIEW

ITEM	QTY	PRICE
1. Clean Machine Inside and Out- Not Repaired		\$0.00
2. Service Machine if Due- Not Due		\$0.00
3. Coolant Reservoir Lower Tube Seeping- Not Repaired		\$0.00
4. Lighting- All Cal Lights and Radiator Work Light Inop, Strobe Light Inop- Not Repaired		\$0.00
5. Front Frame Cover Missing- Replaced		\$0.00
6. Bucket Edge- Showing Wear- Not Replaced		\$0.00
7. Quick Coupler- Back Cover Damaged- Replaced		\$0.00
8. Glass- Windshield Cetner Left 1 Chip- Not Replaced		\$0.00
9. Mirror- Spot Mirror Right Side Torn Off- Replaced		\$0.00
10. Radiator Grille Dented- Repaired		\$0.00
11. Right Front Fender Damaged- Not Replaced		\$0.00
12. Left Fornt Fender Damaged- Not Replaced		\$0.00
13. Counterweight Front Panels Dented- Not Replaced- Poor Repair		\$0.00
14. Steps All Damaged- Repaired		\$0.00
15. Radio Missing- Not Replaced		\$0.00
16. Rear 2 Mudflaps Torn Off, Hangers Bent- Repaired		\$0.00
17. Right Tail Light Guard Bent- Replaced		\$0.00
18. Right Counterweight Reflector Broken- Replaced		\$0.00
19. Engine Bay Right Side Radiator Brace Missing Bolt- Replaced		\$0.00
Total		\$0.00

Lessee: Romco Equipment
Contract: Romco Equipment

Unit: 2013 Volvo L60G



UNIT # 1603
Location: Romco Equipment Co, LP,
Round Rock TX



Lessee: Romco Equipment
Contract: Romco Equipment

Unit: 2013 Volvo L60G


UNIT # 1603
Location: Romco Equipment Co, LP,
Round Rock TX



Lessee: Romco Equipment
Contract: Romco Equipment

Unit: 2013 Volvo L60G

UNIT # 1603
Location: Romco Equipment Co, LP,
Round Rock TX





Lessee: Romco Equipment
Contract: Romco Equipment

Unit: 2013 Volvo L60G

UNIT # 1603
Location: Romco Equipment Co, LP,
Round Rock TX



Lessee: Romco Equipment
Contract: Romco Equipment

Unit: 2013 Volvo L60G

UNIT # 1603
Location: Romco Equipment Co, LP,
Round Rock TX

