

**Lessee: Tri-State Resources  
Contract: 502-7683849-004**

**Unit: 2015 Volvo A25G**

**UNIT # 740151  
Location: Scott Equipment, Baton  
Rouge LA**



**SPECIFICATIONS**

VIN	740151
LeaseInspector ID #	740151
Year	2015
Model	Volvo A25G
Location City	Baton Rouge
Location State	LA
New Hours	2944
Old Hours	2943

**Lessee: Tri-State Resources**  
**Contract: 502-7683849-004**

**Unit: 2015 Volvo A25G**

**UNIT # 740151**  
**Location: Scott Equipment, Baton Rouge LA**

**ADDITIONAL FEATURES OF THIS VEHICLE**  
**COMMENTS**

**Appraiser Comments:**

**Creditor Comments:**

**Public Comments:**

**Starts/Runs:** Yes

**Overall:** Good

**Lessee: Tri-State Resources**  
**Contract: 502-7683849-004**

**Unit: 2015 Volvo A25G**

**UNIT # 740151**  
**Location: Scott Equipment, Baton Rouge LA**

**DEFICIENCY REVIEW**

**ITEM**

- 1. Glass Windshield Cracked- Replaced
- 2. Top Left Mirror Broken- Replaced
- 3. 1 Broken Vent Louver- Replaced
- 4. Service Light On- Repaired
- 5. Buddy Seat Torn- Repaired
- 6. Service Machine if Due-Done
- 7. Dealer to Verify Tire Cuts are Cosmetic Only- Replaced

**QTY PRICE**

- \$0.00
- \$0.00
- \$0.00
- \$0.00
- \$0.00
- \$0.00
- \$0.00



**Total**

**\$0.00**

Lessee: Tri-State Resources  
Contract: 502-7683849-004

Unit: 2015 Volvo A25G

UNIT # 740151  
Location: Scott Equipment, Baton Rouge LA



Lessee: Tri-State Resources  
Contract: 502-7683849-004

Unit: 2015 Volvo A25G

UNIT # 740151  
Location: Scott Equipment, Baton Rouge LA



**Lessee: Tri-State Resources**  
**Contract: 502-7683849-004**

**Unit: 2015 Volvo A25G**

**UNIT # 740151**  
**Location: Scott Equipment, Baton Rouge LA**

