

2016 Volvo L70H

Serial #: VCE0L70HA0S622454

Arnold Machinery
Twin Falls, ID
208-316-1843

- Air conditioning
- Quick Coupler
- Ride control system
- Front visor
- SMU/Hours: 3257
- Overall: Fair
- External rearview mirrors
- Radio
- Air suspension seat
- Start Run: Yes
- Insp Date: 4/26/2018



2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454

General Appearance

GENERAL:			
Radiator Grille:	Good	Fuel Tank:	Good
Radiator Shroud:	Good	Cab Doors:	Good
Engine Enclosure:	Good	Bumper:	Good
Hood:	Good	Differential supports:	Good
Stack:	Good	+ Counterweight:	Fair
+ Right front fender:	Fair	Scratched /Chipped Paint	
Bent/Torn		Cab:	Good
+ Left front fender:	Fair	Steps:	Good
Bent		Grab Irons/Handrails:	Good
+ Right rear fender:	Fair	Paint:	Good
Bent		Oil Sample Taken:	No
+ Left rear fender:	Fair		
Bent/Torn			
Main Frame:	Good		
Precleaner bowl:	Good		
NOTES:			
.			

2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454

Interior Section

SAFETY ITEMS:			
Glass:	Good	Neutral Start Switch:	Good
Mirrors:	Good	Fire Suppression System:	Good
Seat Belt:	Good	Horn:	Good
+ Back Up Alarm:	Fair	Roll Over Protection:	ROPS
Inop			
Fan Guards:	Good		
NOTES:			
OPERATOR AREA:			
Dash Console:	Good	Seat Cushion:	Good
Meter:	Good	+ Arm Rests:	Fair
Gauges:	Good	Left missing	
Control Pattern Decals:	Good	Floor Boards/Mats:	Good
Switches:	Good	EMS Panel:	Good
Windshield Wipers:	Good	Warnings:	Good
Heater:	Good	Door Latches:	Good
A/C:	Good	Current Parts Manual:	Yes
Interior Lights:	Good	Current Safety Manual:	Yes
		Current O&M Manual:	Yes
NOTES:			

2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454

Power Systems

ENGINE:			
Engine Make Model:	Volvo D6J	Oil Pressure:	Normal
Engine S/N:	11857052	Smoke:	No
Engine Hours:	3257	Smoke Color:	Light
Oil Leaks:	No	TurboCharger:	Good
Blow-by:	No	Fuel Injection System:	Good
Knocking:	No	Governor:	Good
Compression in Radiator:	No	Engine Supports:	Good
Water in Oil:	No	+ Air Cleaners:	Fair
Fluid Level OK?:	Yes	Dirty - Replace	
Anit-Freeze Color:	Pink	Last Scheduled Oil Sample:	N/A
		Last Preventive Maintenance:	N/A
NOTES:			
COOLING SYSTEM:			
Radiator:	Good	Fan:	Good
Coolers:	Good	Fan Drive:	Good
Hoses:	Good	Belts:	Good
Water Pump:	Good	Pulleys:	Good
NOTES:			
ELECTRICAL SYSTEM:			
Batteries:	Good	Wiring:	Good
Battery Cables:	Good	Pre-Heater:	Good
Starter:	Good	Lighting:	Good
Alternator:	Good		
NOTES:			

2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454

Power Systems - Continued

TRANSMISSION:			
Serial #:	2271810775	Controls:	Good
Type:	Power Shift	Seals:	Good
Speeds:	Excellent	Torque Converter:	Good
Transmission Forward:	Good	Temp/Pressure Gauges:	Good
Transmission Reverse:	Good	Is the Transmission Noisy?:	No
Case:	Good		
NOTES:			
STEERING:			
Front axle:	Good	Articulation P & B:	Good
Steering Linkage:	Good	Steering cylinder:	Good
Steering Valve:	Good	Tie rods/ rod ends:	Good
Steering Pump:	Good		
NOTES:			
BRAKE:			
Mechanism:	Wet	Lines:	Good
Brake Type:	Pedal	Compressor:	Good
Performance:	Good	Brake linkage:	Good
Brake drums:	Good	Master cylinder:	Good
Rotors:	Good	Parking brake:	Good
Control Valve:	Good		
NOTES:			
FINAL DRIVE:			
Front Planataries:	Good	Rear Wheel lugs & rims:	Good
Front Differential:	Good	Front Axle bolts:	Good
Rear Planataries:	Good	Rear Axle bolts:	Good
Rear Differential:	Good	Front axle housings:	Good
Front Wheel lugs & rims:	Good	Rear axle housings:	Good
NOTES:			

2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454

Hydraulics

HYDRAULICS:			
Right lift cylinder:	Good	Pumps:	Good
Left lift cylinder:	Good	Valves:	Good
Bucket cylinder:	Good	Control linkage:	Good
Hose lines:	Good	Bucket & hoist kickout:	Good
NOTES:			

2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454

Front Bucket

FRONT BUCKET:			
Bucket Type:	Volvo	Bucket adapters:	Good
Width:	106 Inches	Bucket teeth:	Good
Capacity:	3.7	Arms & cranks:	Good
Bucket bottom:	Good	Loader frame:	Good
Bucket sides:	Good	Loader P & B:	Good
Bucket linkage:	Good	Quick coupler:	Good
Bucket mounts:	Good		
NOTES:			

2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454

Tires

TIRES:					
Front Tire Size:	Left: 20.5R25 - 50%	Right: 20.5R25 - 58%	Rear Tire Size:	Left: 20.5R25 - 58%	Right: 20.5R25 - 58%
Front Tire Brand:	Left: Titan	Right: Titan	Rear Tire Brand:	Left: Titan	Right: Titan
Front Tire Measurement:	Left: 24/32	Right: 28/32	Rear Tire Measurement:	Left: 28/32	Right: 28/32
NOTES:					
Tread Depth Wear Based On 48/32nds New					

2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454

Comments

COMMENTS:
Creditor Comments:
Public Comments:

2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454

Deficiency Review

DEFICIENCY REVIEW:		
ITEM	QTY	PRICE
1. + Air Cleaners Dirty		\$0.00
2. + Right Front Tire Cut/Gouged		\$0.00
3. + Left Rear Tire Cut/Gouged		\$0.00
4. + Right Rear Tire Cut		\$0.00
5. + Backup Alarm Inop		\$0.00
6. + Left Arm Rest Pad Missing		\$0.00
12. service machine if due		\$0.00
13. dealer to verify all tire cuts are cosmetic only		\$0.00
Total		\$0.00

2016 Volvo L70H

(Continued)



Serial #: VCE0L70HA0S622454



2016 Volvo L70H

(Continued)


Serial #: VCE0L70HA0S622454



2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454



2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454



2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454



2016 Volvo L70H

(Continued)


Serial #: VCE0L70HA0S622454



2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454



2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454



Engine net power kW
 Manufacturing year
 Made in

MODEL	D6J	CODE	CFV1115	SERNO	11857052
KW	115,0	HP	154	SPEC	17211876
DISPL	2200	kWred		DISPL	5.702
				CSPEC	120R 010184
					24R 033368

VOLVO MADE IN GERMANY EP MFGDATE 12/2015

2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454



2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454



2016 Volvo L70H

(Continued)

Serial #: VCE0L70HA0S622454

