



FIELD INSPECTION: EXCAVATOR CRAWLER

MACHINE CONFIGURATION - BUILD

	YES	NO	OPTIONS	MAKE	MODEL	SIZE
ENCLOSED ROPS	YES		BOOM			
A/C & HEAT	YES		ARM			
STANDARD BOOM	YES		TRACK PAD		TBG	
QUICK COUPLER		NO	COUPLER			
HYD CWT REMOVAL		NO	ADDITIONAL ATTACHMENTS			
EXTRA CWT'S		NO				
DOZER		NO				
AUX / HYD		NO				
BUCKET	YES		BUCKET	Volvo	HD	66
THUMB		NO	THUMB			

CUSTOMER:	Fisher	MNFR-MAKE:	Volvo	DATE:	6-Mar-17
TERRITORY MANAGER:		MODEL:	EC380EL		
INSPECTOR:	McDaniel	HOUR METER:	4,724	YEAR:	2014
LOCATION:	Orl-Yard	SERIAL# / VIN:	310133		

COMPONENT					COMMENTS - OBSERVATIONS	REPAIR ESTIMATE \$\$\$
	Very Good	Good	Fair (photo)	Poor (photo)		
ENGINE					MFG/MODEL/TIER T4I	
MAINTENANCE/SERVICE			X		DPF, HYD, AIR DRYER NEED SERVICE	
STARTING		X				
FAULT CODES				X	YES= SEE PHOTOS	
EXHAUST SMOKE		X			N/A	
OIL PRESSURE		X				
POWER		X				
BLOW-BY		X				
NOISES		X			N/A	
OIL LEAKS		X				
COOLING SYSTEM		X			DIRTY SEE PHOTOS	

CUSTOMER:	Fisher	MNFR-MAKE:	Volvo	DATE:	6-Mar-17
TERRITORY MANAGER:		MODEL:	EC380EL		
INSPECTOR:	McDaniel	HOUR METER:	4,724	YEAR:	2014
LOCATION:	Orl-Yard	SERIAL# / VIN:	310133		
AIR CLEANER			X	DIRTY SEE PHOTOS	
EXHAUST SYSTEM	X			DPF NEEDS SERVICE SEE PHOTOS	
GAUGES	X				
OTHER: SPECIFY					
ELECTRICAL SYS					
STARTER	X				
ALTERNATOR	X				
BATTERIES	X				
LIGHTS, SIGNALS	X				
WIRING, SWITCHES	X				
OTHER: SPECIFY					
TRAVEL					
TRAVEL MOTOR - RH	X				
TRAVEL MOTOR - LH	X				
STEERING - RH	X				
STEERING - LH	X				
LEAKS				N/A	
NOISES				N/A	
OTHER: SPECIFY					
SWING					
CAR BODY-STRUCTURAL	X				
RING GEAR & PINION	X				
SWING FUNCTION	X				
SWING BRAKE		X			
LEAKS				N/A	
SWING BEARING	X				
OTHER: SPECIFY					
HYDRAULIC SYS					
GENERAL CONDITION	X				
HOIST CYLINDERS	X				
PINS/BUSH-HOIST	X				
ARM CYLINDER	X				

CUSTOMER:	Fisher		MNFR-MAKE:	Volvo	DATE:	6-Mar-17
TERRITORY MANAGER:			MODEL:	EC380EL		
INSPECTOR:	McDaniel		HOUR METER:	4,724	YEAR:	2014
LOCATION:	Orl-Yard		SERIAL# / VIN:	310133		
PINS/BUSH-ARM CYL		X				
BUCKET CYLINDER		X				
PINS/BUSH-BKT CYL			X			
PINS/BUSH-COUPLER						
HYD PUMPS		X				
HYD MOTORS		X				
HYD VALVES		X				
LINES & HOSES		X				
HYD CONTROLS		X				
LEAKS IN GENERAL				N/A		
OTHER: SPECIFY						
FRAME & BODY						
CRACKS/WELDS-FRONT						
CRACKS/WELDS-REAR						
CRACKS/WELDS-BOOM						
RH SHEET METAL		X				
LH SHEET METAL		X				
COUNTERWEIGHT			X	SOME SCRATCHES-SEE PHOTO		
OTHER: SPECIFY						
TRACKS						
GENERAL CONDITION				NORMALL FOR AGE		
SPROCKET - LH				Remaining life %:	60%	
SPROCKET - RH				Remaining life %:	60%	
IDLER - LH				Remaining life %:	70%	
IDLER - RH				Remaining life %:	70%	
PINS & BUSHINGS - LH				Remaining life %:	45%	
PINS & BUSHINGS - RH				Remaining life %:	45%	
TOP ROLLERS -LH				Remaining life %:	60%	
TOP ROLLERS - RH				Remaining life %:	60%	
BOTTOM ROLLERS - LH				Remaining life %:	70%	
BOTTOM ROLLERS - RH				Remaining life %:	70%	
TRACK PADS				Remaining life %:	75%	

CUSTOMER:	Fisher	MNFR-MAKE:	Volvo	DATE:	6-Mar-17
TERRITORY MANAGER:		MODEL:	EC380EL		
INSPECTOR:	McDaniel	HOUR METER:	4,724	YEAR:	2014
LOCATION:	Orl-Yard	SERIAL# / VIN:	310133		
OTHER: SPECIFY					
BUCKET					
GENERAL CONDITION	X				
BOTTOM	X				
CUTTING EDGE					
TEETH		X			
PINS/BUSH-LOWER		X	SOME PLAY		
PINS/BUSH-UPPER		X	SOME PLAY		
WEAR PADS/BARS		X			
OTHER: SPECIFY					
CAB - SHEET METAL					
ROPS CONDITION	X				
WINDSHIELD	X				
ALL OTHER WINDOWS	X				
DOOR CONDITION	X				
OPERATORS MANUAL			N/A		
SEAT COND - OPERATION	X				
SEAT BELT	X				
HEAT & A/C CONDITION	X				
A/C VENT LOUVERS	X				
CONTROLS/TOGGLE SWITCHES	X				
BEACON/STROBE LIGHT	X				
BACK UP ALARM	X				
RADIATOR / GRILL	X				
HOOD / BUMPERS	X				
REAR VIEW CAMERA	X				
RADIO & ANTENNA	X				
CARETRACK ANTENNA	X				
OTHER: SPECIFY					
OPTIONAL EQUIP					
SPECIFY:					
SPECIFY:					

CUSTOMER:	Fisher	MNFR-MAKE:	Volvo	DATE:	6-Mar-17
TERRITORY MANAGER:		MODEL:	EC380EL		
INSPECTOR:	McDaniel	HOUR METER:	4,724	YEAR:	2014
LOCATION:	Orl-Yard	SERIAL# / VIN:	310133		
SPECIFY:					
SPECIFY:					
SPECIFY:					
SPECIFY:					
"X" OVERAL RATING		X			
TOTAL ESTIMATED MACHINE REPAIRS =					\$0
OBSERVATIONS - ADDITIONAL COMMENTS					
NORMALL WEAR AND TEAR FOR AGE AND HOURS, BOOM PIN HAS SOME PLAY					