

Lessee: Turner Contracting
Contract: 502-7572506-029

Unit: 2015 Volvo A40G

UNIT # 0872
Location: Romco, Fort Worth TX



SPECIFICATIONS

VIN	0872
LeaseInspector ID #	0872
Year	2015
Model	Volvo A40G
Location City	Fort Worth
Location State	TX
General Specifications	
Tires	
Lt Front Tread Depth	47
Rt Front Tread Depth	45
Lt Rear Tread Depth	44
Rt Rear Tread Depth	43
Left Rear Rear Tire Depth	42
Right Rear Rear Tire Depth	40
New Hours	4477
Old Hours	4471

Lessee: Turner Contracting
Contract: 502-7572506-029

Unit: 2015 Volvo A40G

UNIT # 0872
Location: Romco, Fort Worth TX

**ADDITIONAL FEATURES OF THIS
VEHICLE
COMMENTS**

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes

Overall: Fair

Lessee: Turner Contracting
Contract: 502-7572506-029

Unit: 2015 Volvo A40G

UNIT # 0872
Location: Romco, Fort Worth TX



DEFICIENCY REVIEW

ITEM	QTY PRICE
1. 2 Tires Not Matching-	\$0.00
2. Matris Failed to Upload-	\$0.00
3. Low Hydraulic Oil- Repaired	\$0.00
4. Front Spill Guard Punctured- Not Repaired	\$0.00
5. Dealer to Verify Tire Cuts are Cosmetic Only-	\$0.00
6. A/C Vent Upper Right Side Missing- Replaced	\$0.00
7. Ignition Broken- Repaired	\$0.00
8. Grille Cracked- Repaired	\$0.00
9. Engine Enclosure Broken/Cracked- Repaired	\$0.00
10. Left Front Fender Cracked- Repaired	\$0.00
11. Clean Machine Inside, Out, Undercarriage, Engine- Not Done	\$0.00
12. Service Machine if Due-	\$0.00
Total	\$0.00

Lessee: Turner Contracting
Contract: 502-7572506-029

Unit: 2015 Volvo A40G

UNIT # 0872
Location: Romco, Fort Worth TX



Lessee: Turner Contracting
Contract: 502-7572506-029

Unit: 2015 Volvo A40G

UNIT # 0872
Location: Romco, Fort Worth TX



Lessee: Turner Contracting
Contract: 502-7572506-029

Unit: 2015 Volvo A40G

UNIT # 0872
Location: Romco, Fort Worth TX



Lessee: Turner Contracting
Contract: 502-7572506-029

Unit: 2015 Volvo A40G

UNIT # 0872
Location: Romco, Fort Worth TX

