# **VOLVO - INSPECTION REPORT**

# Volvo, A40g - Articulated haul trucks

Images





#### Comment: Country: US Dealer: Arnold Machinery Company Location: Las vegas Date: 10/03/2019 Inspector: Mike seifert Year: 2015 Make: Volvo Model: A40g Hours: 5729 Serial number: 340942 Engine S/N: 089923 Matris hours: 5729 Trans S/N: 1700106122 Comment: **Equipped Configuration** [ ] Yes Scraper ARRG. [X] Yes Standard Cab ] Yes Fuel Heater ſ [] Yes Water Tank ] Yes Low Profile Cab ] Yes Full Suspension ] Yes LED Light [X] Yes Standard Body ] Yes Frame Ext. [X] Yes Strobe Light ] Yes Extra Spill Guard [X] Yes Onboard Weight Sys. [ ] Yes Hydraulic switch control 1 Yes Exhaust Body Heat [X] Yes Bed Liner Metal ] Yes Bed Liner Plastic [X] Yes Hydraulic lever control [X] Yes Overhung Tailgate ] Yes Auto Lube System ] Yes Underhung Tailgate [X] Yes Back Up Camera 1 ] Yes Fire Suppression System ] Yes Underground ARRG. [ ] Yes Fast Fuel ſ [X] Yes Mud Flaps Comment: **Operators Station** Seats and armrest [X] Good [X] Fair Remarks: Ashtray cover missing Dash and console Floor Board/Mat [X] Good Cab glass [X] Good Mirrors [X] Good

Interior light [X] Good

Switches	[X] Good
Wipers	[X] Good
Gauges	[X] Good
Hydraulic controls	[X] Good
Powertrain controls	[X] Good
AC cooling	[X] Good
CAB Interior	[X] Good
Operators station condition summary	overall good condition
Comment:	

#### Outside appearance

0	
Steps	[X] Good
Hand rails	[X] Good
Counterweight /	[X] Good
Bumper	
Grill	[X] Good
Hood	[X] Good
Exhaust stack	[X] Good
Pre-cleaner bowl	[X] Good
Front fenders	[X] Fair Remarks: Needs mud flaps
Hyd tank	[X] Good
Fuel tank	[X] Good
Def tank	[X] Good
Front frame & welds	[X] Good
Rear frame & welds	[X] Good
Sheet metal	[X] Good
Paint	[X] Good
Outside appearance	Overall good condition
condition summary	
Comment:	

## Safety condition

Safety decals in place	[X]Yes
Operators manual	[X]Yes
Safety handles	[X] Good
Seat belt	[X] Good
Horn	[X] Good
Back up alarm	[X] Good

Brake lights	[X] Good
Turn signals	[X] Good
Hazard lights	[X] Good
ROPS Structure	[X] Good
CAB	[X] Good
Safety condition summary	Overall good condition
Comment:	

#### **Electrical condition**

Computer	[X] Good
ECM'S	[X] Good
Monitor / Display	[X] Good
Wiring harness's	[X] Good
Key switch	[X] Good
Switches	[X] Good
Lighting	[X] Good
Engine preheater	[X] Good
Batteries / Connection	ns [X] Good
Battery disconnect	[X] Good
switch	
Electrical condition	Overall good condition
summary	
Comment:	

# Engine condition

Oil level OK	[X]Yes
Water in oil	[ X ] No
Compression in radiator	[ X ] No
Blow by	[ X ] No
Engine knocking	[ X ] No
CE PLATE	[X]Yes
Oil pressure	[X]Good
Oil leaks	[X]Yes
EPA DECAL	[X]Yes
Turbo charger	[X] Good
Exhaust manifold	[X] Good
Muffler	[X] Good

Fuel injection system	[X] Good
Head gasket	[X] Good
Head	[X] Good
Fan guard	[X] Good
Belts & pulleys	[X] Good
Wiring harness	[X] Good
Starter	[X] Good
Alternator	[X] Good
Seals & gaskets	[X] Good
Engine mounts	[X] Good
Brackets	[X] Good
AC Compressor	[X] Good
Air filters	[X] Good
Engine condition summary	Overall good condition
Comment:	

# Cooling system

Coolant color	Yellow
Radiator	[X] Good
Water pump	[X] Good
Oil cooler	[X] Good
Fan	[X] Good
Fan drive	[X] Good
Hoses	[X] Good
Cooling system summary	Overall good condition
Comment:	

## Transmission condition

Oil level OK	[ X ] No
Water in oil	[ X ] No
Any leaks	[ X ] No
Torque converter	[X] Good
Case	[X] Good
Pump	[X] Good

Hoses	[X] Good
Retarder	[X] Good
Transfer case	[X] Good
Shifting forward	[X] Good
Shifting reverse	[X] Good
Transmission summary	175 psi @ idle 225psi in dive
Comment:	

#### **Axels-Final Drives-Brakes**

Front differential	[X] Good
Center differential	[X] Good
Rear differential	[X] Good
Differential supports	[X] Good
Drive shafts	[X] Good
UV Joints	[X] Good
Planetaires front	[X] Good
Planetaires center	[X] Good
Planetaires rear	[X] Good
Hoses / Lines	[X] Good
Torsion rods	[X] Good
Holds in park	[X]Yes
Brakes wet	[X]Yes
Holds thru all gears	[X]Yes
Brakes dry	[ X ] No
Brake disk / calipers	[ ] Good [ ] Fair [ ] Poor Remarks:
Brake lines	[X] Good
Seals	[X] Good
Parking brake	[X] Good
Summary	Overall good condition
Comment:	

# Steering & articulation condition

Steering cylinders	[X] Good
Pumps	[X] Good
Valves	[X] Good

Lines / Hoses	[X] Good
Secondary steering	[X] Good
Steering pins &	[X] Good
bushings	
Steering wheel tilt &	[X] Good
function	
Articulation pins &	[X] Good
bushings	
Summary	Normal wear on bushings
Comment:	

# Hydraulics condition

Bed lift cylinders	[X] Good
Pumps	[X] Fair Remarks:
Valves	[X] Good
Hoses	[X] Good
Fittings	[X] Good
Tank	[X] Good
Controls	[X] Good
Bed float	[X] Good
Operational condition	[X] Good
Summary	Overall good condition
Comment:	

### Bed & other attachments

Bed type / Size	
Tailgate S / N	
Bed serial	
Addtl attachments	
Spill guard	[X] Good
Body	[X] Good
Bed liner	[X] Good
Bed sides	[X] Fair Remarks: Small dent
Bed floor	[X] Good
Wear plates	[X] Good
Tailgate	[X] Fair Remarks: Has dents
Pins & bushings	[X] Good
Summary	Overall good condition
Comment:	

Make	Michelin
Serial	Yct0116a3a. 54/32
% Remaining	
Make	Michelin
Serial	Gpe3674g2a. 25/32
% Remaining	
Make	Michelin
Serial	Cvz1525v8b. 29/32
% Remaining	
Make	Michelin
Serial	Fvf1390t3a. 5/32
% Remaining	
Make	Michelin
Serial	Cpe1822g4. 27/32
% Remaining	
Make	Michelin
Serial	Cpe1818b8 25/32
% Remaining	
Recapped	[ X ] No
Tread cuts	[X] Yes Remarks: Some
Side wall cuts	[X] Yes Remarks: Some
Tire size the same	[X] Yes Remarks: 29.5R25
Overall tire condition	[X] Fair Remarks: Front tires new
Rims	[X] Good
Lug nuts & studs	[X] Good
Comment:	

#### **General Comments**

Legend (5 star rating)	[ ]5 [ ]4 [ ]3 [ ]2 [ ]1
Paint general	[ ]Good [ ]Fair [ ]Poor Remarks:
Comment:	