

# VOLVO - INSPECTION REPORT

## Volvo, A40g - Articulated haul trucks

### Images



Comment:

Country: US  
Date: 05/28/2019  
Make: Volvo  
Serial number: 340469  
Trans S/N: 1700105332

Dealer: Arnold Machinery Company  
Inspector: Mike seifert  
Model: A40g  
Engine S/N: 083940

Location: Las vegas  
Year: 2014  
Hours: 4186  
Matris hours: 4217

Comment:

### Equipped Configuration

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> <b>Yes</b> Standard Cab            | <input type="checkbox"/> <b>Yes</b> Scraper ARR.G.               | <input type="checkbox"/> <b>Yes</b> Fuel Heater                    |
| <input type="checkbox"/> <b>Yes</b> Water Tank                         | <input type="checkbox"/> <b>Yes</b> Low Profile Cab              | <input type="checkbox"/> <b>Yes</b> Full Suspension                |
| <input type="checkbox"/> <b>Yes</b> LED Light                          | <input checked="" type="checkbox"/> <b>Yes</b> Standard Body     | <input type="checkbox"/> <b>Yes</b> Frame Ext.                     |
| <input checked="" type="checkbox"/> <b>Yes</b> Strobe Light            | <input checked="" type="checkbox"/> <b>Yes</b> Extra Spill Guard | <input checked="" type="checkbox"/> <b>Yes</b> Onboard Weight Sys. |
| <input type="checkbox"/> <b>Yes</b> Hydraulic switch control           | <input type="checkbox"/> <b>Yes</b> Exhaust Body Heat            | <input checked="" type="checkbox"/> <b>Yes</b> Bed Liner Metal     |
| <input checked="" type="checkbox"/> <b>Yes</b> Hydraulic lever control | <input checked="" type="checkbox"/> <b>Yes</b> Overhung Tailgate | <input type="checkbox"/> <b>Yes</b> Bed Liner Plastic              |
| <input type="checkbox"/> <b>Yes</b> Auto Lube System                   | <input type="checkbox"/> <b>Yes</b> Underhung Tailgate           | <input checked="" type="checkbox"/> <b>Yes</b> Back Up Camera      |
| <input type="checkbox"/> <b>Yes</b> Fire Suppression System            | <input type="checkbox"/> <b>Yes</b> Underground ARR.G.           | <input type="checkbox"/> <b>Yes</b> Fast Fuel                      |
| <input checked="" type="checkbox"/> <b>Yes</b> Mud Flaps               |  |  |

Comment:

### Operators Station

- |                   |  |
|-------------------|--|
| Seats and armrest | <input checked="" type="checkbox"/> Good |
| Dash and console  | <input checked="" type="checkbox"/> Good |
| Floor Board/Mat   | <input checked="" type="checkbox"/> Good |
| Cab glass         | <input checked="" type="checkbox"/> Good |
| Mirrors           | <input checked="" type="checkbox"/> Good |
| Interior light    | <input checked="" type="checkbox"/> Good |
| Switches          | <input checked="" type="checkbox"/> Good |
| Wipers            | <input checked="" type="checkbox"/> Good |
| Gauges            | <input checked="" type="checkbox"/> Good |

Hydraulic controls [ X ] Good

Powertrain controls [ X ] Good

AC cooling [ X ] Good

CAB Interior [ X ] Good

Operators station  
condition summary

Comment:

### Outside appearance

---

Steps [ X ] Good

Hand rails [ X ] Good

Counterweight / [ X ] Good

Bumper

Grill [ X ] Good

Hood [ X ] Good

Exhaust stack [ X ] Good

Pre-cleaner bowl [ X ] Good

Front fenders [ X ] Good

Hyd tank [ X ] Fair Remarks:

Fuel tank [ X ] Good

Def tank [ X ] Good

Front frame & welds [ X ] Good

Rear frame & welds [ X ] Good

Sheet metal [ X ] Good

Paint [ X ] Good

Outside appearance  
condition summary

Comment:

### Safety condition

---

Safety decals in place [ X ] Yes

Operators manual [ X ] Yes

Safety handles [ X ] Good

Seat belt [ X ] Good

Horn [ X ] Good

Back up alarm [ X ] Good

Brake lights [ X ] Good

Turn signals [ X ] Good

Hazard lights [ X ] Good

ROPS Structure [ X ] Good

CAB [ X ] Good

Safety condition  
summary

Comment:

### Electrical condition

---

Computer [ X ] Good

ECM'S [ X ] Good

Monitor / Display [ X ] Good

Wiring harness's [ X ] Good

Key switch [ X ] Good

Switches [ X ] Good

Lighting [ X ] Good

Engine preheater [ X ] Good

Batteries / Connections [ X ] Good

Battery disconnect [ X ] Good

switch

Electrical condition  
summary

Comment:

### Engine condition

---

Oil level OK [ X ] Yes

Water in oil [ X ] No

Compression in  
radiator [ X ] No

Blow by [ X ] No

Engine knocking [ X ] No

CE PLATE [ X ] Yes

Oil pressure [ X ] Good

Oil leaks [ X ] Yes

EPA DECAL [ X ] Yes

Turbo charger [ X ] Good

Exhaust manifold [ X ] Good

Muffler [ X ] Good

Fuel injection system [ X ] Good

Head gasket [ X ] Good

Head [ X ] Good

Fan guard [ X ] Good  
Belts & pulleys [ X ] Good  
Wiring harness [ X ] Good  
Starter [ X ] Good  
Alternator [ X ] Good  
Seals & gaskets [ X ] Good  
Engine mounts [ X ] Good  
Brackets [ X ] Good  
AC Compressor [ X ] Good  
Air filters [ X ] Good

Engine condition  
summary

Comment:

### Cooling system

---

Coolant color

Radiator [ X ] Good

Water pump [ X ] Good

Oil cooler [ X ] Good

Fan [ X ] Good

Fan drive [ X ] Good

Hoses [ X ] Good

Cooling system  
summary

Comment:

### Transmission condition

---

Oil level OK [ X ] Yes

Water in oil [ X ] No

Any leaks [ X ] Yes

Torque converter [ X ] Good

Case [ X ] Good

Pump [ X ] Good

Hoses [ X ] Good

Retarder [ X ] Good

Transfer case [ X ] Good

Shifting forward [ X ] Good

Shifting reverse [ X ] Good

Transmission summary

Comment:

### **Axels-Final Drives-Brakes**

---

Front differential [ X ] Good

Center differential [ X ] Good

Rear differential [ X ] Good

Differential supports [ X ] Good

Drive shafts [ X ] Good

UV Joints [ X ] Good

Planetaires front [ X ] Good

Planetaires center [ X ] Good

Planetaires rear [ X ] Good

Hoses / Lines [ X ] Good

Torsion rods [ X ] Good

Holds in park [ X ] Yes

Brakes wet [ X ] Yes

Holds thru all gears [ X ] Yes

Brakes dry [ X ] No

Brake disk / calipers [ X ] Good

Brake lines [ X ] Good

Seals [ X ] Good

Parking brake [ X ] Good

Summary

Comment:

### **Steering & articulation condition**

---

Steering cylinders [ X ] Good

Pumps [ X ] Good

Valves [ X ] Good

Lines / Hoses [ X ] Good

Secondary steering [ X ] Good

Steering pins & bushings [ X ] Good

Steering wheel tilt & function [ X ] Good

Articulation pins & bushings [ X ] Good

Summary

Comment:

### Hydraulics condition

---

Bed lift cylinders [ X ] Good

Pumps [ X ] Good

Valves [ X ] Good

Hoses [ X ] Good

Fittings [ X ] Good

Tank [ X ] Good

Controls [ X ] Good

Bed float [ X ] Good

Operational condition [ X ] Good

Summary

Comment:

### Bed & other attachments

---

Bed type / Size

Tailgate S / N

Bed serial

Addtl attachments

Spill guard [ X ] Good

Body [ X ] Good

Bed liner [ X ] Good

Bed sides [ X ] Good

Bed floor [ X ] Good

Wear plates [ X ] Good

Tailgate [ X ] Good

Pins & bushings [ X ] Fair Remarks:

Summary

Comment:

### Tires & rims

---

Make

Serial

% Remaining

Make	<input type="text" value="Bridgestone"/>
Serial	<input type="text" value="Rubbed off. 44/32"/>
% Remaining	<input type="text"/>
Make	<input type="text" value="Bridgestone"/>
Serial	<input type="text" value="B4a382482. 45/32"/>
% Remaining	<input type="text"/>
Make	<input type="text" value="Bridgestone"/>
Serial	<input type="text" value="F5u382461. 41/32"/>
% Remaining	<input type="text"/>
Make	<input type="text" value="Bridgestone"/>
Serial	<input type="text" value="F1n382957. 47/32"/>
% Remaining	<input type="text"/>
Make	<input type="text" value="Bridgestone"/>
Serial	<input type="text" value="W8a004109. 58/32"/>
% Remaining	<input type="text"/>
Recapped	<input checked="" type="checkbox"/> No
Tread cuts	<input checked="" type="checkbox"/> Yes Remarks: <input type="text" value="Some"/>
Side wall cuts	<input checked="" type="checkbox"/> Yes Remarks: <input type="text"/>
Tire size the same	<input checked="" type="checkbox"/> Yes Remarks: <input type="text"/>
Overall tire condition	<input checked="" type="checkbox"/> Good
Rims	<input checked="" type="checkbox"/> Good
Lug nuts & studs	<input checked="" type="checkbox"/> Good
Comment:	<input type="text"/>

**General Comments**

Legend (5 star rating)  5  4  3  2  1

Paint general  Good  Fair  Poor Remarks:

Comment: