Unit: 2017 Volvo L350F

Lessee: Mathy Construction Company Contract: 502-7613822-053 UNIT # 1909 Location: Aring Equipment, Eau Claire WI



SPECIFICATIONS

VIN 1909
LeaseInspector ID # 1909
Year 2017
Model Volvo L350F
Location City Eau Claire
Location State WI

General Specifications

New Hours 3663 Old Hours 3654 Lessee: Mathy Construction Unit: 2017 Volvo L350F UNIT # 1909

Company Location: Aring Equipment, Eau
Contract: 502-7613822-053 Claire WI

ADDITIONAL FEATURES OF THIS VEHICLE COMMENTS

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes Overall: Fair

Unit: 2017 Volvo L350F **Lessee: Mathy Construction** Company

Contract: 502-7613822-053

UNIT # 1909 Location: Aring Equipment, Eau Claire WI

DEFICIENCY REVIEW

ITEM	QTY PRICE
1. Right Side Forward Lower Step Assembly Bent- Repaired	\$0.00
2. Clean Machine Inside, Out, Engine, Undercarriage- Done	\$0.00
3. Dealer to Verify Tire Cuts are Cosmetic Only- Verfied	\$0.00
4. Dealer to Determine is Serivce is Due- Verified	\$0.00
5. Air Cleaners Dirty- Not Repaired	\$0.00
6. Engine Oil Level High- Repaired	\$0.00
7. Collection at Left Side Rear Corner of Engine- Repaired	\$0.00
8. Radiator Dirty- Repaired	\$0.00
9. Coolers Dirty- Repaired	\$0.00
10. Light Beacon on Roof Inop- Repaired	\$0.00
11. Front Tires Sidewalls Cut- Not Repaired	\$0.00
Total	\$0.00

UNIT # 1909

Lessee: Mathy Construction Unit: 2017 Volvo L350F

Company Location: Aring Equipment, Eau
Contract: 502-7613822-053 Claire WI



Lessee: Mathy Construction Company Contract: 502-7613822-053

Unit: 2017 Volvo L350F **UNIT # 1909** Location: Aring Equipment, Eau Claire WI



11/20/2019 LeaseInspector Off-Lease

> Lessee: Mathy Construction Company Contract: 502-7613822-053 Unit: 2017 Volvo L350F



UNIT # 1909

Unit: 2017 Volvo L350F

Lessee: Mathy Construction Company Contract: 502-7613822-053 Location: Aring Equipment, Eau Claire WI





UNIT # 1909









