Serial #: 342084

ASC Construction Equipment Buford, GA 678-318-9500

- Rear vision system
- Air ride seat
- Air conditioning
- Rotating beacon
- Tailgate
- SMU/Hours: 4637
- Overall: Fair

- Radio
- Differential locks
- Computer display
- Mudflaps
- Engine jake brake
- Start Run: Yes
- Insp Date: 8/22/2019





NO PICTURE AVAILABLE NO PICTURE AVAILABLE

(Continued)

General Appearance

Radiator G	rille:	Poor	Precleaner b	oowl:	Good
Radiator S	hroud:	Not Available	Fuel Tank:		Fair
Engine Enclosure:		Good	Cab Doors:		Good
Hood:		Good	Bumper:		Fair
Stack:		Good	Cab:		Good
Right front	fender:	Good	Steps:		Good
Left front fender:		Good	Grab Irons/H	landrails:	Good
Rear frame:		Good	Paint:		Good
Front frame: Good		Good	Oil Sample 1	Гаken:	No
LEGEND OF	CONDITIONS:		,		
Excellent -	New condition.	No Repairs Necessary.	Poor -	Obvious we necessary.	ar and/or damage. Repairs
Good -	No apparent wear or damage, Functions/Operates Not Applicable - Does not apply to correctly. No Repairs Necessary.			pply to this unit	
Fair -		mage apparent. Functions, but			

(Continued)

Interior Section

Glass:	Good	Neutral Start Switch:	Good	
Mirrors:	Good	Fire Suppression System:	Not Available	
Seat Belt:	Poor	Horn:	Good	
Back Up Alarm:	Good			
Fan Guards:	Good			
NOTES:		*		
OPERATOR AREA:				
Dash Console:	Good	Seat Cushion:	Good	
Meter:	Good	Arm Rests:	Poor	
Gauges:	Good	Floor Boards/Mats:	Good	
Control Pattern Decals:	Good	EMS Panel:	Good	
Switches:	Good	Warnings:	Good	
Windshield Wipers:	Good	Door Latches:	Good	
Heater:	Good	Current Parts Manual:	Yes	
A/C:	Good	Current Safety Manual:	Yes	
Interior Lights:	Good	Current O&M Manual:	Yes	

(Continued)

Power Systems

Engine Make Model:	Volvo D13J	Oil Pressure:	Normal
Engine S/N:	-	Smoke:	No
Engine Hours:	4637	Smoke Color:	Not Applicable
Oil Leaks:	Not Applicable	TurboCharger:	Not Available
Blow-by:	Not Applicable	Fuel Injection System:	Not Available
Knocking:	No	Governor:	Not Available
Compression in Radiator:	Not Applicable	Engine Supports:	Not Available
Water in Oil:	Not Applicable	Air Cleaners:	Not Available
Fluid Level OK?:	Not Applicable		
Anit-Freeze Color:	-		
NOTES:			
COOLING SYSTEM:			
Radiator:	Not Available	Fan:	Not Available
Coolers:	Not Available	Fan Drive:	Not Available
Hoses:	Not Available	Belts:	Not Available
Water Pump:	Not Available	Pulleys:	Not Available
NOTES:			
ELECTRICAL SYSTEM:			
Batteries:	Good	Wiring:	Good
Battery Cables:	Good	Pre-Heater:	Good
Starter:	Good	Lighting:	Good
	Not Available	ı	

2017 Volvo A40G (Continued)

Power Systems - Continued

Transmission Serial #:	-	Seals:	Good
Transmission Type:	Auto	Torque Converter:	Good
Transmission Speeds:	F9 R3	Temp/Pressure Gauges:	Good
Transmission Forward:	Good	Transmission Fluid:	Good
Transmission Reverse:	Good	Is the Transmission Noisy?:	No
Case:	Good	Transmission Retarder:	No
Controls:	Good		
NOTES:			
STEERING:			
Steering Linkage:	Good	Left steering cylinder:	Good
Steering Valve:	Good	Right steering cylinder:	Good
Steering Pump:	Good	Steering joints:	Good
Articulation P & B:	Good		
NOTES:			
BRAKE:			
Mechanism:	Wet	Lines:	Good
Type:	Pedal	Compressor:	Good
Perfomance:	Good	Brake linkage:	Good
Brake drums:	Not Available	Master cylinder:	Not Available
Rotors:	Not Available	Parking brake:	Good
Control Valve:	Good		
NOTES:			
DRIVE TRAIN:			
Front axle:	Good	Rear axle housing:	Good
Front differential:	Good	U-Joints:	Good
Rear axles:	Good	Front suspension:	Good
Rear differentials:	Good	Rear suspension:	Good
Front wheel lugs & rims:	Good	Front a-stay:	Good
Rear wheel lugs & rims:	Good	Rear a-stay:	Good
Front axle bolts:	Good		
Rear axle bolts:	Good		
Front axle housing:	Good		

(Continued)

Hydraulics

Right dump cylinder:	Good	Valves:	Good	
Left dump cylinder:	Good	Control linkage:	Good	
Hose lines:	Good	Reservoir:	Good	
Pumps:	Good	Dump cycle test:	Good	

(Continued)

Dump Body

Body type:	Dump	Body pins and bushings:	Good	
Body bottom:	Good	Body liner:	Not Available	
Body sides:	Good	Tail gate adapter:	Good	
Rubber pads:	Good	Tail gate:	Good	
Body mounts:	Good	Front spill guard:	Good	

(Continued)

Tires

TIRES:					
Front Tire Size:	Left: 26.5R25 - 84%	Right: 26.5R25 - 84%	Rear Tire Size 1:	Left: 26.5R25 - 84%	Right: 26.5R25 - 84%
Front Tire Brand:	Left: Maxam	Right: Maxam	Rear Tire Brand 1:	Left: Maxam	Right: Maxam
Front Tire Radial or Bias:	Left: Radial	Right: Radial	Rear Tire Radial or Bias:	Left: Radial	Right: Radial
Front Tire Measurement:	Left: 43/32	Right: 43/32	Rear Tire Measurement 1:	Left: 43/32	Right: 43/32
			Rear Tire Size 2:	Left: 26.5R25 - 84%	Right: 26.5R25 - 84%
			Rear Tire Brand 2:	Left: Maxam	Right: Maxam
			Rear Tire Radial or Bias:	Left: Radial	Right: Radial
			Rear Tire Measurement 2:	Left: 43/32	Right: 43/32
NOTES: Tread Depth Wear Based Or	n 51/32nds New				

(Continued)

Comments

COMMENTS:			
Public Comments:			

(Continued)

Reconditioning

DE	DEFICIENCY REVIEW:		
	ITEM	QTY PRICE	
1.	+ Unable to Open Hood	\$0.00	
2.	+ 2 Tail Gate Rubber Pads Damaged	\$0.00	
3.	+ Jump Seat Belt Does Not Retract	\$0.00	
4.	+ Rear Camera Blury	\$0.00	
5.	+ Left Armrest Damaged	\$0.00	
7.	+ Lighter Missing	\$0.00	
12.	dealer to determine if service is due	\$0.00	
То	tal	\$0.00	


(Continued)



(Continued)



(Continued)



(Continued)

