

VOLVO - INSPECTION REPORT

Volvo, L70g - Wheel Loaders

Images



Comment:

Country: US
Date: 04/03/2019
Make: Volvo
Serial number: 614613
Matris hours: 2884

Dealer: Arnold Machinery Company
Inspector: Mike seifert situk
Model: L70g
Engine S/N: 11741215

Location: Las Vegas
Year: 2015
Hours: 2884
Trans S/N: 16706

Comment:

General Configuration

- | | | |
|--|---|---|
| <input checked="" type="checkbox"/> Yes EROPS | <input type="checkbox"/> Yes Auto Lube | <input checked="" type="checkbox"/> Yes Full coverage fenders |
| <input type="checkbox"/> Yes OROPS | <input type="checkbox"/> Yes Onboard scale | <input type="checkbox"/> Yes Strobe Light |
| <input type="checkbox"/> Yes FOPS | <input type="checkbox"/> Yes Onboard Weight Sys. | <input type="checkbox"/> Yes Auto Lube System |
| <input type="checkbox"/> Yes Steering wheel | <input checked="" type="checkbox"/> Yes Auto shift | <input type="checkbox"/> Yes Fire Suppression System |
| <input type="checkbox"/> Yes Joystick steering | <input checked="" type="checkbox"/> Yes Optishift | <input type="checkbox"/> Yes Mud Flaps |
| <input checked="" type="checkbox"/> Yes Air conditioning | <input checked="" type="checkbox"/> Yes Boom suspension | <input type="checkbox"/> Yes Recycling arrangement |
| <input checked="" type="checkbox"/> Yes Rear camera | <input type="checkbox"/> Yes 3rd function | <input type="checkbox"/> Yes Forestry arrangement |
| <input checked="" type="checkbox"/> Yes Standard boom | <input type="checkbox"/> Yes 4th function | <input type="checkbox"/> Yes Long boom |
| <input checked="" type="checkbox"/> Yes Reversible fan | <input type="checkbox"/> Yes Fuel Heater | <input checked="" type="checkbox"/> Yes Bucket leveler |
| <input type="checkbox"/> Yes Artic kit | <input type="checkbox"/> Yes Limited slip axel | <input checked="" type="checkbox"/> Yes Quick coupler |
| <input type="checkbox"/> Yes Counter weight handling kit | <input type="checkbox"/> Yes Universal attachment plate | |

Comment:

Operators Station

- | | |
|------------------|--|
| Seat and armrest | <input checked="" type="checkbox"/> Good |
| Dash and console | <input checked="" type="checkbox"/> Good |
| Floor Board/Mat | <input checked="" type="checkbox"/> Good |
| Cab glass | <input checked="" type="checkbox"/> Good |
| Mirrors | <input checked="" type="checkbox"/> Good |
| Interior light | <input checked="" type="checkbox"/> Good |

Switches [X] Good
Wipers [X] Good
Gauges [X] Good
Hydraulic controls [X] Good
Powertrain controls [X] Good
AC cooling [X] Good
CAB Interior [X] Good

Operators station
condition summary

Comment:

Outside appearance

Steps [X] Good
Hand rails [X] Good
Counterweight /
Bumper [X] Good
Grill [X] Good
Hood [X] Good
Exhaust stack [X] Good
Pre-cleaner bowl [X] Good
Front fenders [X] Good
Rear fenders [X] Good
Fuel tank [X] Good
Front frame & welds [X] Good
Rear frame & welds [X] Good
Sheet metal [X] Good
Paint [X] Good

Outside appearance
condition summary

Clean ~ Normal Wear & Tear

Comment:

Safety condition

Safety decals in place [X] No
Operators manual [X] No
Safety handles [X] Good
Seat belt [X] Good
Horn [X] Good
Back up alarm [X] Good
Brake hold [X] Good
Turn signals [X] Good
Hazard lights [X] Good

ROPS Structure [X] Good

CAB [X] Good

Safety condition
summary

Comment:

Electrical condition

Computer [X] Good

ECM'S [X] Good

Monitor / Display [X] Good

Wiring harness's [X] Good

Key switch [X] Good

Switches [X] Good

Lighting [X] Good

Engine preheater [X] Good

Batteries / Connections [X] Good

Battery disconnect [X] Good

switch

Electrical condition
summary

Comment:

Engine condition

Oil level OK [X] Yes

Water in oil [X] No

Compression in
radiator [X] No

Blow by [X] No

Engine knocking [X] No

CE PLATE [X] Yes

Oil pressure [X] Good

Oil leaks [X] No

EPA DECAL [X] Yes

Turbo charger [X] Good

Exhaust manifold [X] Good

Muffler [X] Good

Fuel injection system [X] Good

Head gasket [X] Good

Head [X] Good

Fan guard [X] Good
Belts & pulleys [X] Good
Wiring harness [X] Good
Starter [X] Good
Alternator [X] Good
Seals & gaskets [X] Good
Engine mounts [X] Good
Brackets [X] Good
AC Compressor [X] Good
Air filters [X] Good

Engine condition
summary

Comment:

Cooling system

Coolant color

Radiator [X] Good

Water pump [X] Good

Oil cooler [X] Good

Fan [X] Good

Fan drive [X] Good

Hoses [X] Good

Cooling system
summary

Comment:

Transmission condition

Oil level OK [X] Yes

Water in oil [X] No

Any leaks [X] No

Torque converter [X] Good

Case [X] Good

Pump [X] Good

Hoses [X] Good

Retarder [X] Good

Shifting forward [X] Good

Shifting reverse [X] Good

Transmission summary

Comment:

Axels-Final Drives-Brakes

Front differential [X] Good

Rear differential [X] Good

Differential supports [X] Good

Drive shafts [X] Good

UV Joints [X] Good

Planetaires front [X] Good

Planetaires rear [X] Good

Hoses / Lines [X] Good

Torsion rods [X] Good

Any leaks [X] No

Holds in park [X] Yes

Brakes wet [X] No

Holds thru all gears [X] Yes

Brakes dry [X] Yes

Brake disk / calipers [X] Good

Brake lines [X] Good

Seals [X] Good

Parking brake [X] Good

Summary

Comment:

Steering & articulation condition

Steering cylinders [X] Good

Pumps [X] Good

Valves [X] Good

Lines / Hoses [X] Good

Secondary steering [X] Good

Steering pins & bushings [X] Fair Remarks:

Steering wheel tilt & function [X] Good

Articulation pins & bushings [X] Fair Remarks:

Summary

Comment:

Hydraulics condition

Boom cylinders [X] Good

Tilt cylinder [X] Good

Valves [X] Good

Hoses [X] Good

Fittings [X] Good

Tank [X] Good

Controls [X] Good

Boom kickout and bucket level [X] Good

Operational Summary

Comment:

Bucket & other attachments

Bucket type / Size

Coupler type

Bucket serial

Coupler serial

Bucket W / Teeth [X] No

Addtl attachments

Bolt on smooth [X] No

Bolt on edge [X] Fair Remarks:

Bucket teeth / Segments [X] Good

Bucket sides [X] Good

Bucket floor [X] Good

Bucket bottom [X] Good

Coupler [X] Good

Boom / Frame [X] Good

Boom / Bucket pins & bushings [X] Good

Summary

Comment:

Tires & rims

Make

Serial

% Remaining

Make

Serial

% Remaining

Make

Serial

% Remaining

Make

Serial

% Remaining

Make

Serial

% Remaining

Make

Serial

% Remaining

Recapped No

Tread cuts No

Side wall cuts No

Tire size the same Yes Remarks:

Overall tire condition Fair Remarks:

Rims Good

Lug nuts & studs Good

Comment:

General Comments

Legend (5 star rating) 5 4 3 2 1

Paint general Good Fair Poor Remarks:

Comment: