#### 2017 Volvo A40G

Atlantic Waste Landfill Waverly, VA 301-395-0291

- Rear vision system
- Air ride seat
- Air conditioning
- Rotating beacon
- Body exhaust heating kit
- Engine jake brake
- SMU/Hours: 1882
- Overall: Fair

- Radio
- Differential locks

**Serial #:** 341665

- Computer display
- Mudflaps
- Tailgate

Start Run: Yes

• Insp Date: 6/5/2019









2017 Volvo A40G (Continued)

# **General Appearance**

GENER/	AL:					
Radiator Grille:		Good	Precleaner bowl:		Good	
Radiator S	hroud:	Good	Fuel Tank:		Good	
Engine En	closure:	Good	Cab Doors:		Good	
Hood:		Good	Bumper:		Good	
Stack:		Good	Cab:		Good	
Right front	fender:	Good	Steps:		Good	
Left front f	ender:	Good	Grab Irons/Ha	ndrails:	Good	
Rear frame	<b>)</b> :	Good	Paint:		Good	
Front fram	e:	Good	Oil Sample Taken:		No	
LEGEND O	F CONDITIONS:					
Excellent - New condition. No Repairs Necessary.		Poor -	Obvious wea	ar and/or damage. Repairs		
Good -	No apparent wear or damage, Functions/Operates correctly. No Repairs Necessary.		Not Applicable	- Does not ap	ply to this unit	
Fair -	Wear and/or damage apparent. Functions, but not correctly. Repairs recommended.					
NOTES:						

2017 Volvo A40G

(Continued)

#### **Interior Section**

Glass:	Good	Neutral Start Switch:	Good	
Mirrors:	Good	Fire Suppression System:	Not Available	
Seat Belt:	Good	Horn:	Good	
Back Up Alarm:	Good			
Fan Guards:	Good			
NOTES:		-		
ODEDATOR AREA.				
OPERATOR AREA:				
Dash Console:	Good	Seat Cushion:	Good	
Meter:	Good	Arm Rests:	Good	
Gauges:	Good	Floor Boards/Mats:	Good	
Control Pattern Decals:	Good	EMS Panel:	Good	
Switches:	Good	Warnings:	Good	
Windshield Wipers:	Good	Door Latches:	Good	
Heater:	Good	Current Parts Manual:	No	
	Good	Current Safety Manual:	No	
A/C:		Current O&M Manual:	Yes	

2017 Volvo A40G

(Continued)

#### **Power Systems**

ENGINE:				
Engine Make Model:	Volvo D16J	Oil Pressure:	Normal	
Engine S/N:	101072	Smoke:	No	
Engine Hours:	1882	Smoke Color:	Not Applicable	
Oil Leaks:	No	TurboCharger:	Good	
Blow-by:	No	Fuel Injection System:	Good	
Knocking:	No	Governor:	Good	
Compression in Radiator:	No	Engine Supports:	Good	
Water in Oil:	No	Air Cleaners:	Good	
Fluid Level OK?:	Yes			
Anit-Freeze Color:	Yellow			
NOTES:		•		
COOLING SYSTEM:				
Radiator:	Good	Fan:	Good	
Coolers:	Good	Fan Drive:	Good	
Hoses:	Good	Belts:	Good	
Water Pump:	Good	Pulleys:	Good	
NOTES:				
ELECTRICAL SYSTEM				
Batteries:	Good	Wiring:	Good	•
Battery Cables:	Good	Pre-Heater:	Good	
Starter:	Good	Lighting:	Good	
Alternator:	Good			
NOTES:		·		

2017 Volvo A40G (Continued)

# **Power Systems - Continued**

TRANSMISSION:			
Transmission Serial #:	-	Seals:	Good
Transmission Type:	Auto	Torque Converter:	Good
Transmission Speeds:	9	Temp/Pressure Gauges:	Good
Transmission Forward:	Good	Transmission Fluid:	Good
Transmission Reverse:	Good	Is the Transmission Noisy?:	No
Case:	Good	Transmission Retarder:	Yes
Controls:	Good		
NOTES:			
STEERING:			
Steering Linkage:	Good	Left steering cylinder:	Good
Steering Valve:	Good	Right steering cylinder:	Good
Steering Pump:	Good	Steering joints:	Good
Articulation P & B:	Good		
NOTES:		•	
BRAKE:			
Mechanism:	Wet	Lines:	Good
Type:	Pedal	Compressor:	Good
Perfomance:	Good	Brake linkage:	Good
Brake drums:	Good	Master cylinder:	Good
Rotors:	Good	Parking brake:	Good
Control Valve:	Good		
NOTES:			
DRIVE TRAIN:			
Front axle:	Good	Rear axle housing:	Good
Front differential:	Good	U-Joints:	Good
Rear axles:	Good	Front suspension:	Good
Rear differentials:	Good	Rear suspension:	Good
Front wheel lugs & rims:	Good	Front a-stay:	Good
Rear wheel lugs & rims:	Good	Rear a-stay:	Good
Front axle bolts:	Good		
Rear axle bolts:	Good		
	Good	į –	

2017 Volvo A40G

(Continued)

# **Hydraulics**

HYDRAULICS:				
Right dump cylinder:	Good	Valves:	Good	
Left dump cylinder:	Good	Control linkage:	Good	
Hose lines:	Good	Reservoir:	Good	
Pumps:	Good	Dump cycle test:	Poor	
NOTES:		•		

2017 Volvo A40G

(Continued)

# **Dump Body**

DUMP BODY:			
Body type:	Bulk	Body pins and bushings:	Good
Body bottom:	Good	Body liner:	Not Available
Body sides:	Good	Tail gate adapter:	Good
Rubber pads:	Good	Tail gate:	Good
Body mounts:	Good	Front spill guard:	Good
NOTES:			

2017 Volvo A40G

(Continued)

#### **Tires**

TIRES:								
Front Tire Size:	<b>Left:</b> 29.5R25 - 58%	<b>Right:</b> 29.5R25 - 70%	Rear	Tire	Size 1:		<b>Left:</b> 29.5R25 - 60%	Right: 29.5R25 - 49%
Front Tire Brand: Left:	Bridgestone Rig	ght: Bridgestone	Rear	Tire	Brand 1:	Left:	Bridgestone Rig	ght: Bridgestone
Front Tire Radial or Bias:	Left: Radial	Right: Radial	Rear	Tire	Radial or Bia	ıs:	Left: Radial	Right: Radial
Front Tire Measurement:	Left: 32/32	Right: 39/32	Rear	Tire	Measuremen	it 1:	Left: 33/32	Right: 27/32
			Rear	Tire	Size 2:		<b>Left:</b> 29.5R25 - 65%	<b>Right:</b> 29.5R25 - 43%
			Rear	Tire	Brand 2:	Left:	Bridgestone Rig	ght: Bridgestone
			Rear	Tire	Radial or Bia	ıs:	Left: Radial	Right: Radial
			Rear	Tire	Measuremen	ıt 2:	Left: 36/32	Right: 24/32
NOTES: Tread Depth Wear Based O	n 55/32nds Nev	v						

2017 Volvo A40G

(Continued)

#### **Comments**

COMMENTS:		
Public Comments:		


2017 Volvo A40G

(Continued)


# Reconditioning

DEFICIENCY REVIEW:					
ITEM	QTY PRICE				
1. + Both Right Rear Tires Past 50%	\$0.00				
2. + Service Due According To Filters	\$0.00				
3. + Clean Machine	\$0.00				
4. + All Tires Sidewalls Cut/Gouges					
Total					


2017 Volvo A40G




2017 Volvo A40G



2017 Volvo A40G



2017 Volvo A40G



2017 Volvo A40G

