Unit: 2012 Volvo EC250EL

Lessee: Landmark Construction Contract: 502-5013298-052

UNIT # 310023 Location: ASC Construction Equipment, North Charleston SC



SPECIFICATIONS

310023 310023 2012 Volvo EC250EL North Charleston SC Lessee: Landmark Construction Contract: 502-5013298-052 Unit: 2012 Volvo EC250EL

ADDITIONAL FEATURES OF THIS VEHICLE

COMMENTS

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes Overall: Fair

Unit: 2012 Volvo EC250EL

DEFICIENCY REVIEW

Lessee: Landmark Construction Contract: 502-5013298-052

ITEM	QTY PRICE
1. Seat Belt Cover Broken- Repaired	\$0.00
2. Safety Switch Handle Broken- Repaired	\$0.00
3. Track Pads Worn Past 50%- Repaired	\$0.00
4. 3 Carrier Rollers Worn Past 50%- Not Repaired	\$0.00
5. Service Machine if Due- Not Repaired	\$0.00
6. Coolant Low- Repaired	\$0.00
7. Boom Lights Inop- Repaired	\$0.00
8. Bucket Cylinder Leaking- Repaired	\$0.00
Total	\$0.00

Lessee: Landmark Construction Contract: 502-5013298-052

Unit: 2012 Volvo EC250EL

UNIT # 310023 Location: ASC Construction Equipment, North Charleston SC



LeaseInspector Off-Lease

Unit: 2012 Volvo EC250EL


Lessee: Landmark Construction Contract: 502-5013298-052



Lessee: Landmark Construction Contract: 502-5013298-052

Unit: 2012 Volvo EC250EL

UNIT # 310023 Location: ASC Construction Equipment, North Charleston SC



Unit: 2012 Volvo EC250EL

Lessee: Landmark Construction Contract: 502-5013298-052

UNIT # 310023 Location: ASC Construction Equipment, North Charleston SC









