

**Lessee: Flagler Construction  
Equipment  
Contract: Flagler**

**Unit: 2015 Volvo A40G**

**UNIT # 0459  
Location: Flagler Construction  
Equipment, Tampa FL**



**SPECIFICATIONS**

VIN	0459
LeaseInspector ID #	0459
Year	2015
Model	Volvo A40G
Location City	Tampa
Location State	FL
<b>General Specifications</b>	
New Hours	5152
Old Hours	5150

**Lessee: Flagler Construction  
Equipment  
Contract: Flagler**

**Unit: 2015 Volvo A40G**

**UNIT # 0459  
Location: Flagler Construction  
Equipment, Tampa FL**

**ADDITIONAL FEATURES OF THIS  
VEHICLE  
COMMENTS**

**Appraiser Comments:**

**Creditor Comments:**

**Public Comments:**

**Starts/Runs:** Yes

**Overall:** Fair

**Lessee: Flagler Construction  
Equipment  
Contract: Flagler**

**Unit: 2015 Volvo A40G**

**UNIT # 0459  
Location: Flagler Construction  
Equipment, Tampa FL**



**DEFICIENCY REVIEW**

<b>ITEM</b>	<b>QTY</b>	<b>PRICE</b>
1. Clean Machine- Done		\$0.00
2. Fumigate- Repaired		\$0.00
3. Clean Machine Inside, Out, Engine, Undercarriage- Done		\$0.00
4. Dealer to Verify Tire Cuts are Cosmetic Only- Verified		\$0.00
5. Service Machine if Due- Up to Date		\$0.00
6. Electric Over Hydraulic Hood System Inop- Repaired		\$0.00
7. Engien Oil Seep at Engine Harness Left Side- Repaired		\$0.00
8. Engine Oil Seep Left Side of Engine- Repaired		\$0.00
9. Engine Oil Seep Left Bottom of Engine- Not Repaired		\$0.00
10. Brake Fluid Level Below Min Line- Repaired		\$0.00
11. 4 Tail Gate Pads Missing- Not Replaced		\$0.00
12. All Tire Cuts/Dry Rot- Verified		\$0.00
13. Ashtray Front Missing- Replaced		\$0.00
<b>Total</b>		<b>\$0.00</b>

Lessee: Flagler Construction  
Equipment  
Contract: Flagler

Unit: 2015 Volvo A40G

UNIT # 0459  
Location: Flagler Construction  
Equipment, Tampa FL



Lessee: Flagler Construction  
Equipment  
Contract: Flagler

Unit: 2015 Volvo A40G

UNIT # 0459  
Location: Flagler Construction  
Equipment, Tampa FL

