

Lessee: Oak Valley Hardwoods
Contract: 502-7609681-007

Unit: 2015 Volvo L110H

UNIT # 10261
Location: Ascendum Machinery, Mills
River NC



VIN	10261
LeaseInspector ID #	10261
Year	2015
Model	Volvo L110H
Location City	Mills River
Location State	NC
General Specifications	
New Hours	5669
Old Hours	5666

Lessee: Oak Valley Hardwoods
Contract: 502-7609681-007

Unit: 2015 Volvo L110H

UNIT # 10261
Location: Ascendum Machinery, Mills
River NC

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes

Overall: Fair

**Lessee: Oak Valley Hardwoods
Contract: 502-7609681-007**

Unit: 2015 Volvo L110H


**UNIT # 10261
Location: Ascendum Machinery, Mills
River NC**

ITEM	QTY PRICE
1. Right Rear Console Lid Lock Cylinder Missing- Replaced	\$0.00
2. Ignition Cylinder- Tumbler Loose- Repaired	\$0.00
3. All Mudflaps Missing, Damaged, Brackets Damaged- Replaced	\$0.00
4. Left Step Brackets Bent- Repaired	\$0.00
5. Clean Machine Inside, Out, Engine, Undercarriage- Done	\$0.00
6. Dealer to Verify Tire Cuts are Cosmetic Only- Not Repaired	\$0.00
7. Dealer to Determine if Service is Due- Repaired	\$0.00
8. Hood Damaged- Repaired	\$0.00
9. Right Front Fender Damaged- Repaired	\$0.00
10. Left Front Fender Damaged- Repaired	\$0.00
11. Right Rear Fender Damaged- Repaired	\$0.00
12. Right Hanging Step Brackets Bent- Repaired	\$0.00
13. Right Lift Cylinder Leaking- Repaired	\$0.00
14. Left Lift Cylinder Leaking- Repaired	\$0.00
15. Leak by Hydraulic Tank- Not Repaired	\$0.00
16. All Tire Cuts, Gouged- Left Front Tire Past 50%- Not Repaired	\$0.00
17. Replace Left Door Glass- Replaced	\$0.00
18. Reinstall Left Glass Slider- Repaired	\$0.00
19. Dash Display Inop- Repaired	\$0.00
20. Leak at Pan Gasket Area- Repaired	\$0.00
21. Front Crank Seal Area Leaks- Repaired	\$0.00
22. Air Cleaner Dirty- Replaced	\$0.00
Total	\$0.00

Lessee: Oak Valley Hardwoods
Contract: 502-7609681-007

Unit: 2015 Volvo L110H

UNIT # 10261
Location: Ascendum Machinery, Mills
River NC



Lessee: Oak Valley Hardwoods
Contract: 502-7609681-007

Unit: 2015 Volvo L110H


UNIT # 10261
Location: Ascendum Machinery, Mills
River NC



Lessee: Oak Valley Hardwoods
Contract: 502-7609681-007

Unit: 2015 Volvo L110H

UNIT # 10261
Location: Ascendum Machinery, Mills
River NC



Lessee: Oak Valley Hardwoods
Contract: 502-7609681-007

Unit: 2015 Volvo L110H

UNIT # 10261
Location: Ascendum Machinery, Mills
River NC



Lessee: Oak Valley Hardwoods
Contract: 502-7609681-007

Unit: 2015 Volvo L110H


UNIT # 10261
Location: Ascendum Machinery, Mills
River NC



Lessee: Oak Valley Hardwoods
Contract: 502-7609681-007

Unit: 2015 Volvo L110H

UNIT # 10261
Location: Ascendum Machinery, Mills
River NC



Lessee: Oak Valley Hardwoods
Contract: 502-7609681-007

Unit: 2015 Volvo L110H

UNIT # 10261
Location: Ascendum Machinery, Mills
River NC



Lessee: Oak Valley Hardwoods
Contract: 502-7609681-007

Unit: 2015 Volvo L110H

UNIT # 10261
Location: Ascendum Machinery, Mills
River NC



Lessee: Oak Valley Hardwoods
Contract: 502-7609681-007

Unit: 2015 Volvo L110H

UNIT # 10261
Location: Ascendum Machinery, Mills
River NC



Lessee: Oak Valley Hardwoods
Contract: 502-7609681-007

Unit: 2015 Volvo L110H

UNIT # 10261
Location: Ascendum Machinery, Mills
River NC

