

VOLVO - INSPECTION REPORT

Volvo, L60g - Wheel Loaders

Images



Comment:

Country: US
Date: 12/18/2018
Make: Volvo
Serial number: 1603
Matris hours: 7179

Dealer: Arnold Machinery Company
Inspector: mike seifert
Model: L60g
Engine S/N: 11375324

Location: Las vegas
Year: 2013
Hours: 7144
Trans S/N: 12084

Comment:

General Configuration

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Yes EROPS | <input type="checkbox"/> Yes Auto Lube | <input checked="" type="checkbox"/> Yes Full coverage fenders |
| <input checked="" type="checkbox"/> Yes OROPS | <input type="checkbox"/> Yes Onboard scale | <input checked="" type="checkbox"/> Yes Strobe Light |
| <input checked="" type="checkbox"/> Yes FOPS | <input type="checkbox"/> Yes Onboard Weight Sys. | <input type="checkbox"/> Yes Auto Lube System |
| <input checked="" type="checkbox"/> Yes Steering wheel | <input checked="" type="checkbox"/> Yes Auto shift | <input type="checkbox"/> Yes Fire Suppression System |
| <input type="checkbox"/> Yes Joystick steering | <input checked="" type="checkbox"/> Yes Optishift | <input checked="" type="checkbox"/> Yes Mud Flaps |
| <input checked="" type="checkbox"/> Yes Air conditioning | <input checked="" type="checkbox"/> Yes Boom suspension | <input type="checkbox"/> Yes Recycling arrangement |
| <input checked="" type="checkbox"/> Yes Rear camera | <input type="checkbox"/> Yes 3rd function | <input type="checkbox"/> Yes Forestry arrangement |
| <input checked="" type="checkbox"/> Yes Standard boom | <input type="checkbox"/> Yes 4th function | <input type="checkbox"/> Yes Long boom |
| <input checked="" type="checkbox"/> Yes Reversible fan | <input type="checkbox"/> Yes Fuel Heater | <input checked="" type="checkbox"/> Yes Bucket leveler |
| <input type="checkbox"/> Yes Artic kit | <input type="checkbox"/> Yes Limited slip axel | <input checked="" type="checkbox"/> Yes Quick coupler |
| <input type="checkbox"/> Yes Counter weight handling kit | <input checked="" type="checkbox"/> Yes Universal attachment plate | |

Comment:

Operators Station

- | | |
|------------------|--|
| Seat and armrest | <input checked="" type="checkbox"/> Good |
| Dash and console | <input checked="" type="checkbox"/> Good |
| Floor Board/Mat | <input checked="" type="checkbox"/> Good |
| Cab glass | <input checked="" type="checkbox"/> Good |
| Mirrors | <input checked="" type="checkbox"/> Good |
| Interior light | <input checked="" type="checkbox"/> Good |

| | |
|-------------------------------------|---|
| Switches | [X] Good |
| Wipers | [X] Good |
| Gauges | [X] Good |
| Hydraulic controls | [X] Good |
| Powertrain controls | [X] Good |
| AC cooling | [X] Good |
| CAB Interior | [X] Fair Remarks: <input type="text" value="Stereo missing cut wires"/> |
| Operators station condition summary | <input type="text"/> |
| Comment: | <input type="text"/> |

Outside appearance

| | |
|--------------------------------------|---|
| Steps | [X] Good |
| Hand rails | [X] Good |
| Counterweight / | [X] Good |
| Bumper | |
| Grill | [X] Good |
| Hood | [X] Good |
| Exhaust stack | [X] Good |
| Pre-cleaner bowl | [X] Good |
| Front fenders | [X] Fair Remarks: <input type="text" value="Need replaced and frame straightened"/> |
| Rear fenders | [X] Fair Remarks: <input type="text" value="Right hand rear has rear in needs new"/> |
| Fuel tank | [X] Good |
| Front frame & welds | [X] Good |
| Rear frame & welds | [X] Good |
| Sheet metal | [X] Fair Remarks: <input type="text" value="Operators platform broken welds and bent"/> |
| Paint | [X] Good |
| Outside appearance condition summary | <input type="text"/> |
| Comment: | <input type="text"/> |



Safety condition

| | |
|------------------------|------------|
| Safety decals in place | [X] Yes |
| Operators manual | [X] Yes |
| Safety handles | [X] Good |

Seat belt [X] Good
Horn [X] Good
Back up alarm [X] Good
Brake hold [X] Good
Turn signals [X] Good
Hazard lights [X] Good
ROPS Structure [X] Good
CAB [X] Good

Safety condition
summary

Comment:



Electrical condition

Computer [X] Good
ECM'S [X] Good
Monitor / Display [X] Good
Wiring harness's [X] Good
Key switch [X] Good
Switches [X] Good
Lighting [X] Good
Engine preheater [X] Good
Batteries / Connections [X] Good
Battery disconnect [X] Good

switch

Electrical condition
summary

Comment:

Engine condition

Oil level OK [X] Yes
Water in oil [X] No
Compression in
radiator [X] No
Blow by [X] No
Engine knocking [X] No
CE PLATE [] Yes [] No

| | |
|--------------------------|--|
| Oil pressure | [X] Good |
| Oil leaks | [X] No |
| EPA DECAL | [X] Yes |
| Turbo charger | [X] Good |
| Exhaust manifold | [X] Good |
| Muffler | [X] Good |
| Fuel injection system | [X] Good |
| Head gasket | [X] Good |
| Head | [X] Good |
| Fan guard | [X] Fair Remarks: <input type="text" value="Pushed in at emblem"/> |
| Belts & pulleys | [X] Good |
| Wiring harness | [X] Good |
| Starter | [X] Good |
| Alternator | [X] Good |
| Seals & gaskets | [X] Good |
| Engine mounts | [X] Good |
| Brackets | [X] Good |
| AC Compressor | [X] Good |
| Air filters | [X] Good |
| Engine condition summary | <input type="text"/> |
| Comment: | <input type="text"/> |

Cooling system

| | |
|------------------------|--------------------------------------|
| Coolant color | <input type="text" value="Yellows"/> |
| Radiator | [X] Good |
| Water pump | [X] Good |
| Oil cooler | [X] Good |
| Fan | [X] Good |
| Fan drive | [X] Good |
| Hoses | [X] Good |
| Cooling system summary | <input type="text"/> |
| Comment: | <input type="text"/> |

Transmission condition

Oil level OK [X] Yes
Water in oil [X] No
Any leaks [X] No
Torque converter [X] Good
Case [X] Good
Pump [X] Good
Hoses [X] Good
Retarder [X] Good
Shifting forward [X] Good
Shifting reverse [X] Good

Transmission summary

Comment:

Axels-Final Drives-Brakes

Front differential [X] Good
Rear differential [X] Good
Differential supports [X] Good
Drive shafts [X] Good
UV Joints [X] Good
Planetaires front [X] Good
Planetaires rear [X] Good
Hoses / Lines [X] Good
Torsion rods [X] Good
Any leaks [X] No
Holds in park [X] Yes
Brakes wet [X] Yes
Holds thru all gears [X] Yes
Brakes dry [X] No

Brake disk / calipers [] Good [] Fair [] Poor Remarks:

Brake lines [X] Good
Seals [X] Good
Parking brake [X] Good

Summary

Comment:

Steering & articulation condition

Steering cylinders [X] Good
Pumps [X] Good
Valves [X] Good
Lines / Hoses [X] Good
Secondary steering [X] Good
Steering pins & bushings [X] Good
Steering wheel tilt & function [X] Good
Articulation pins & bushings [X] Good
Summary

Comment:

Hydraulics condition

Boom cylinders [X] Good
Tilt cylinder [X] Good
Valves [X] Good
Hoses [X] Good
Fittings [X] Good
Tank [X] Good
Controls [X] Good
Boom kickout and bucket level [X] Good
Operational [X] Good
Summary

Comment:

Bucket & other attachments

Bucket type / Size
Coupler type
Bucket serial
Coupler serial
Bucket W / Teeth [X] No
Addtl attachments
Bolt on smooth [X] Yes
Bolt on edge [X] Good
Bucket teeth / Segments [] Good [] Fair [] Poor Remarks:
Bucket sides [X] Good
Bucket floor [X] Good
Bucket bottom [X] Good

Coupler Good

Boom / Frame Good

Boom / Bucket pins & bushings Good

Summary

Comment:

Tires & rims

Make

Serial

% Remaining

Make

Serial

% Remaining

Make

Serial

% Remaining

Make

Serial

% Remaining

Make

Serial

% Remaining

Make

Serial

% Remaining

Recapped No

Tread cuts Yes Remarks:

Side wall cuts Yes Remarks:

Tire size the same Yes Remarks:

Overall tire condition Fair Remarks:

Rims Good

Lug nuts & studs Good

Comment:

General Comments

Legend (5 star rating) 5

Paint general Good

Comment: