

Volvo Financial Services Pre-Return Inspection Checklist

DD 120B 287098

YES	NO	% Remaining	CAB & BODY	COMMENTS
		NA	Glass Damage	
	✓		Seat Damage	
✓			Interior/Exterior damage >\$250	
			Mechanical/Electrical operational	
	✓		Machine cleaned-interior exterior	
		NA	Bucket free of material	

YES	NO	% Remaining	FRAME	COMMENTS
✓			Structurally sound	
✓			Pins/bushings > 50%	
✓			Floor plates/chains/screeds > 50%	
		NA	Bucket teeth damaged	
	✓		Drums damaged	
✓			Isolator > 50%	

YES	NO	% Remaining	SYSTEMS	COMMENTS
✓			Cooling, heating, lube systems operational	
✓			Fluids @ operating levels	
✓			Filter caps in place	
✓			Batteries hold charge	
✓			Filters OK	
	✓		Pavers-all wear items > 50%	DRUM SCRAPER

YES	NO	% Remaining	TIRES	COMMENTS
		NA	Matching radials	
		NA	Brakes >50%	
		NA	Brakes damaged/cracked	
		NA	Rubber tracks >50%	

YES	NO	% Remaining	MECHANICAL DRIVE	COMMENTS
		NA	Operational with no vibrations	

YES	NO	% Remaining	ELECTRIC DRIVE	COMMENTS
		NA	Drive system > 50%	
		NA	Harnesses operational, not leaking	
		NA	Gauges, senders, switches operational	

YES	NO	% Remaining	UNDERCARRIAGE	COMMENTS
✓			Sprockets, idlers, carriers, track rollers > 50%	
✓			Links, bogies, pins/bushings > 50%	
✓			Track shoes/pads > 50%	

YES	NO	% Remaining	ENGINE	COMMENTS
	✓		Excessive smoke	
	✓		Leaks or blowby	
✓			DPF/Regen operational	

Pre-Return Inspection Checklist-page 2

DB120B 287098

YES	NO	% Remaining	BOOMS	COMMENTS
		NA	Damaged & within mfg. specs	
		NA	Rigging in place	
YES	NO	% Remaining	HYDRAULICS	COMMENTS
✓			Pumps, valve, cylinders fully operational	
✓			Pumps, valve, cylinders leaking	
YES	NO	% Remaining	AIR CONDITIONING	COMMENTS
		NA	All components fully operational	
YES	NO	% Remaining	RPOS/FPOS	COMMENTS
✓			Free of any damage or repairs	
		NA	Brakes >50%	
		NA	Brakes damaged/cracked	
		NA	Rubber tracks >50%	

Equipment Inspection Form

Type: **Compactor**

Please provide the following information for your equipment.

General Information

Customer Full Name:

Equipment Name:

Location Description:

Current Postal Code:

Country:

Equipment Application:

Serial Number:

IC Number:

Equipment Category:

Make:

Model:

Year:

Matris Hours:

Inspector Name:

Operating Hours:

Requested Price (in USD):

Comments:

Features

EROPS:

Yes No

Air Conditioning:

Yes No

ROPS:

Yes No

Heat:

Yes No

Scraper:

Yes No

Hydraulic Options -

Auxiliary?

Yes No

Quick Coupler:

Other Options:

Yes No

Other Options comments:

Attachments:

Yes No

Attachments comments:

Windshield:

Yes No

Features Appearance:

5 - Excellent

4

3

2

1 - Poor

Summary:

Appearance

Body Condition:

N/A Good Fair Repair

Comments:

Paint:

Good Fair Repair

Comments:

Decals:

N/A Good Fair Repair

Comments:

Lights/ Mirrors:

N/A Good Fair Repair

Comments:

Latches:

N/A Good Fair Repair

Comments:

Fluid Fill Caps:

Good Fair Repair

Comments:

Water Tanks:

Good Fair Repair

Comments:

Seats:

Good Fair Repair

Comments:

Overall Appearance:

5 - Excellent

4

3

2

1 - Poor

Summary:

center Rear upper light

sensor

RIP & SCRAPER UP

Eng. Hood pull down STRAP
NEEDS TO BE REPAIRED

Drum SCRAPER WORN OUT FRONT & REAR
NEED TO CK FRONT DRUM FOR LEAK AFTER WASHING UNIT

Run Test

Hours:

Good Fair Repair

Comments:

Battery/ Starting:

Good Fair Repair

Comments:

Gauges:

Good Fair Repair

Comments:

Water System:

Good Fair Repair

Comments:

SUN SCREEN

Controls:

Good Fair Repair

Comments:

Switches:

Good Fair Repair

Comments:

Console Swivel:

Good Fair Repair

Comments:

Swivel/ Articulated Joint:

Good Fair Repair

Comments:

Overall Run Test:

5 - Excellent

4

3

2

1 - Poor

Summary:

Safety

Safety Decals:

N/A Good Repair

Comments:

SEARCH UP

Seatbelts:

N/A Good Repair

Comments:

WEIGHT RESTRICT

Rails:

Good Fair Repair

Comments:

Park Brake:

Good Fair Repair

Comments:

Locking Bar:

N/A Good Repair

Comments:

PIN

Operators Manual/ Handbook:

N/A Good Repair

Comments:

NOT WITH UNIT

ROPS Damage:

N/A Good Fair Repair

Comments:

Back-up Alarm:

N/A Good Fair Repair

Comments:

Horn:

N/A Good Fair Repair

Comments:

Overall Safety:

5 - Excellent

4

3

2

1 - Poor

Summary:

MISSING FIRE EXTINGUISHER

Hydraulics Condition

Hydraulics:

Good Fair Repair

Comments:

Cylinders:

Good Fair Repair

Comments:

Hose/Lines:

Good Fair Repair

Comments:

Pumps/Valves:

Good Fair Repair

Comments:

Isolators:

Good Fair Repair

Comments:

Hydraulic Blocks:

Good Fair Repair

Comments:

Steering:

Good Fair Repair

Comments:

Drum Seats:

Good Fair Repair

Comments:

Oil Cooler:

Good Fair Repair

Comments:

Drive Motor Type:

Overall Hydraulics:

5 - Excellent

4

3

2

1 - Poor

Summary:

Engine Condition

Engine Oil Level:
 Good Fair Repair

Comments:

Visible Leaks:
 Good Fair Repair

Comments:

Filters:
 Good Fair Repair

Comments:

Blow-By:
 Yes No

Belts:
 Good Fair Repair

Comments:

Linkage:
 Good Fair Repair

Comments:

Last Serviced Hours:

Last Serviced Date:

Exhaust Cap:
 Good Fair Repair

Comments:

Wiring/Harness:
 Good Fair Repair

Comments:

Fuses:
 Good Fair Repair

Comments:

Fan Shroud:
 Good Fair Repair

Comments:

Radiator Condition:
 Good Fair Repair

Comments:

Hose/Lines:
 Good Fair Repair

Comments:

Antifreeze:
 < 32F > 32F Replace

Comments:

Engine Shut Down:
 Good Fair Repair

Comments:

Engine Smoke Color:
 Normal Black Blue White

Comments:

Overall Engine Condition:

- 5 - Excellent
- 4
- 3
- 2
- 1 - Poor

Summary:

Overall Condition

Overall Condition:

- 5 - Excellent
- 4
- 3
- 2
- 1 - Poor

Summary:

NEED SOME REPAIRS

