

**Lessee: Tidwell Construction**  
**Contract: 502-7525542-003**

**Unit: 2018 Volvo EC220EL**

**UNIT # 310602**  
**Location: ASC Construction**  
**Equipment, Buford GA**



VIN	310602
LeaseInspector ID #	310602
Year	2018
Model	Volvo EC220EL
Location City	Buford
Location State	GA
<b>General Specifications</b>	
New Hours	764
Old Hours	752

**Lessee: Tidwell Construction**  
**Contract: 502-7525542-003**

**Unit: 2018 Volvo EC220EL**

**UNIT # 310602**  
**Location: ASC Construction**  
**Equipment, Buford GA**

**Appraiser Comments:**

**Creditor Comments:**

**Public Comments:**

**Starts/Runs:** Yes

**Overall:** Fair

**Lessee: Tidwell Construction**  
**Contract: 502-7525542-003**

**Unit: 2018 Volvo EC220EL**

**UNIT # 310602**  
**Location: ASC Construction**  
**Equipment, Buford GA**

<b>ITEM</b>	<b>QTY PRICE</b>
1. Clean Machine Inside, Out, Engine, Undercarriage- Done	\$0.00
2. Dealer to Determine if Service is Due- Not Due	\$0.00
3. Air Cleaner Dirty- Replaced	\$0.00
4. Bucket PIns Worn Not Correct Locking Bolts- Not Replaced	\$0.00
5. Glass Missing Lower Front Window- Replaced	\$0.00
6. Left Mirror Cracked- Replaced	\$0.00
7. Wiper Switch Broken- Replaced	\$0.00
8. Windshield Wipers Inop- Repaired	\$0.00
9. Left Side Engine Enclosure Scratched, Right Side Dented- Left Not Replaced, Right Replaced	\$0.00
10. Right Rear Bumper Dent- Not Repaired	\$0.00
11. 2 Dented Track Steps- 1 Replaced	\$0.00
<b>Total</b>	<b>\$0.00</b>

Lessee: Tidwell Construction  
Contract: 502-7525542-003

Unit: 2018 Volvo EC220EL

UNIT # 310602  
Location: ASC Construction  
Equipment, Buford GA



Lessee: Tidwell Construction  
Contract: 502-7525542-003

Unit: 2018 Volvo EC220EL

UNIT # 310602  
Location: ASC Construction  
Equipment, Buford GA



Lessee: Tidwell Construction  
Contract: 502-7525542-003

Unit: 2018 Volvo EC220EL

UNIT # 310602  
Location: ASC Construction  
Equipment, Buford GA

