2018 Volvo A45G

Alta Equipment Byron Center, MI 616-878-7450

- Rear vision system
- Air ride seat
- Air conditioning
- Rotating beacon
- Body exhaust heating

 | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust heating | Body exhaust hea
- Engine jake brake
- SMU/Hours: 2551
- Overall: Fair

- Radio
- Differential locks

Serial #: 342418

- Computer display
- Mudflaps
- Tailgate

• Start Run: Yes

• Insp Date: 3/27/2020









General Appearance

Radiator (Grille:	Good	Precleaner bo	wl:	Good
Radiator S	Shroud:	Good	Fuel Tank:		Good
Engine En	closure:	Good	Cab Doors:		Good
Hood:		Good	Bumper:		Good
Stack:		Good	Cab:		Good
Right fron	t fender:	Fair	Steps:		Fair
Left front	fender:	Good	Grab Irons/Ha	ndrails:	Good
Rear fram	e:	Good	Paint:		Good
Front fram	ne:	Good	Oil Sample Tal	ken:	No
LEGEND C	F CONDITION	S:			
Excellent -	- New condition	n. No Repairs Necessary.	Poor -	Obvious wea	ar and/or damage. Repairs
Good -		wear or damage, perates correctly. No Repairs	Not Applicable -	- Does not ap	ply to this unit
Fair -		damage apparent. Functions, ectly. Repairs recommended.			

Interior Section

Glass:	Good	Neutral Start Switch:	Good	
Mirrors:	Good	Fire Suppression System:	Good	
Seat Belt:	Good	Horn:	Good	
Back Up Alarm:	Good			
Fan Guards:	Good			
NOTES:				
Dash Console:	Good	Seat Cushion:	Good	
Meter:	Good	Arm Rests:	Good	
Gauges:	Good	Floor Boards/Mats:	Good	
Control Pattern Decals:	Good	EMS Panel:	Good	
	Good	Warnings:	Good	
Switches:	01	Door Latches:	Good	
	Good			
Windshield Wipers:	Good	Current Parts Manual:	No	
Switches: Windshield Wipers: Heater: A/C:		Current Parts Manual: Current Safety Manual:	No Yes	

Power Systems

Engine Make Model:	Volvo D16J	Oil Pressure:	Normal
Engine S/N:	112141A	Smoke:	No
Engine Hours:	2551	Smoke Color:	Not Applicable
Oil Leaks:	No	TurboCharger:	Good
Blow-by:	No	Fuel Injection System:	Good
Knocking:	No	Governor:	Good
Compression in Radiator:	No	Engine Supports:	Good
Water in Oil:	No	Air Cleaners:	Good
Fluid Level OK?:	No		
Anit-Freeze Color:	Yellow		
Radiator:	Good	Fan:	Good
Coolers:	Good	Fan Drive:	Good
Coolers: Hoses:	Good Good	Fan Drive: Belts:	Good Good
Coolers: Hoses: Water Pump:	Good	Fan Drive:	Good
Coolers: Hoses:	Good Good	Fan Drive: Belts:	Good Good
Coolers: Hoses: Water Pump: NOTES:	Good Good	Fan Drive: Belts:	Good Good
Coolers: Hoses: Water Pump: NOTES: Batteries:	Good Good Good	Fan Drive: Belts: Pulleys:	Good Good Good
Coolers: Hoses: Water Pump:	Good Good Good	Fan Drive: Belts: Pulleys: Wiring:	Good Good Good

Power Systems - Continued

Transmission Serial #:	-	Seals:	Good
Transmission Type:	Auto	Torque Converter:	Good
Transmission Speeds:	9 F 3 R	Temp/Pressure Gauges:	Good
Transmission Forward:	Good	Transmission Fluid:	Good
Transmission Reverse:	Good	Is the Transmission Noisy?:	No
Case:	Good	Transmission Retarder:	Yes
Controls:	Good		
NOTES:		,	
Steering Linkage:	Good	Left steering cylinder:	Good
Steering Valve:	Good	Right steering cylinder:	Good
Steering Pump:	Good	Steering joints:	Good
Articulation P & B:	Good		
NOTES:			
Mechanism:	Wet	Lines:	Good
Туре:	Pedal	Compressor:	Good
Perfomance:	Good	Brake linkage:	Good
Brake drums:	Good	Master cylinder:	Good
Rotors:	Good	Parking brake:	Good
Control Valve:	Good		
NOTES:			
Front axle:	Good	Rear axle housing:	Good
Front differential:	Good	U-Joints:	Good
Rear axles:	Good	Front suspension:	Good
Rear differentials:	Good	Rear suspension:	Good
Front wheel lugs & rims:	Good	Front a-stay:	Good
Rear wheel lugs & rims:	Good	Rear a-stay:	Good
Front axle bolts:	Good		
Rear axle bolts:	Good		
Front axle housing:	Good		
NOTES:			

2018 Volvo A45G (Continued)

Serial #: 342418

Hydraulics

Right dump cylinder:	Good	Valves:	Good	
•				
Left dump cylinder:	Good	Control linkage:	Good	
Hose lines:	Good	Reservoir:	Good	
Pumps:	Good	Dump cycle test:	Good	
NOTES:		*		

Dump Body

Body type:	General Purpose	Body pins and bushings:	Good
Body bottom:	Good	Body liner:	Not Available
Body sides:	Good	Tail gate adapter:	Good
Rubber pads:	Good	Tail gate:	Good
Body mounts:	Good	Front spill guard:	Good

Tires

ront Tire Size:	94%	- Right: 29.5R25 - 98%	Rear	Tire	Size 1:	96%	- Right: 29.5R25 - 98%
ront Tire Brand: Left	: Bridgestone Ri	ght: Bridgestone	Rear	Tire	Brand 1: Le	ft: BridgestoneRi	ght: Bridgestone
ront Tire Radial or Bias:	Left: Radial	Right: Radial	Rear	Tire	Radial or Bias:	Left: Radial	Right: Radial
ront Tire Measurement:	Left: 52/32	Right: 54/32	Rear	Tire	Measurement 1:	Left: 53/32	Right: 54/32
			Rear	Tire	Size 2:	Left: 29.5R25 96%	- Right: 29.5R25 - 96%
			Rear	Tire	Brand 2: Le	ft: BridgestoneRi	ght: Bridgestone
			Rear	Tire	Radial or Bias:	Left: Radial	Right: Radial
			Rear	Tire	Measurement 2:	Left: 53/32	Right: 53/32

Comments

Reconditioning

	ITEM QTY	PRICE
1.	+ Low Coolant	\$0.00
2.	+ Front Spill Guard Down for Transport	\$0.00
3.	+ Left Front Steer Tire Cut	\$0.00
4.	+ Right Front Fender Bolt Missing	\$0.00
5.	+ Bottom Left and Middle Steps Bent	\$0.00
6.	+ Hyd Fluid Low	\$0.00
7.	+ Clean Machine	\$0.00
To	otal	\$0.00





























