

SPECIFICATIONS

VIN	1549
LeaseInspector ID #	1549
Year	2016
Model	Volvo A40G
Location City	Jacksonville
Location State	FL
General Specifications	
New Hours	6960
Old Hours	6953

ADDITIONAL FEATURES OF THIS VEHICLE COMMENTS

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes Overall: Fair

DEFICIENCY REVIEW

ITEM	QTY PRICE
1. Clean Machine Inside and Out, Engine and Undercarriage- Not Repaired	\$0.00
2. Service Machine if Due- Up to Date	\$0.00
3. Valve Cover Leaks- Not Repaired	\$0.00
4. Rear Main Seal Leaks- Not Repaired	\$0.00
5. Head Gasket Leaks- Not Repaired	\$0.00
6. Air Cleaner Dirty- Not Replaced	\$0.00
7. Clean Heat Exchangers- Repaired	\$0.00
8. Batteries- Had to Jump- Repaired	\$0.00
9. Beacon Light Inop, Switch Missing- Replaced	\$0.00
10. Fire Extinguisher Missing- Not Replaced	\$0.00
11. Clean Material from Bed- Not Repaired	\$0.00
12. 3 Dash Panels Broken, Damaged- Not Repaired	\$0.00
13. Top of Dash Panel Damaged- Not Replaced	\$0.00
14. Rear Drive- Front Differential Replaced	\$0.00
15. Fuse Panel Cover Damaged- Replaced	\$0.00
16. Radiator Grille Latch Broken- Hard to Open- Replaced	\$0.00
17. Oil Leak on Right Side Frame Under Bed- Repaired	\$0.00
Total	\$0.00











