Unit: 2012 Volvo EC220DL

UNIT # 210093 Location: ASC Construction Equipment, Cayce SC



### **SPECIFICATIONS**

VIN	210093
LeaseInspector ID #	210093
Year	2012
Model	Volvo EC220DL
Location City	Cayce
Location State	SC
New Hours	4707
Old Hours	4706

LeaseInspector Off-Lease

Unit: 2012 Volvo EC220DL

UNIT # 210093 Location: ASC Construction Equipment, Cayce SC

Lessee: Coogler Construction Contract: 502-7629728-010

**ADDITIONAL FEATURES OF THIS VEHICLE** 

COMMENTS

**Appraiser Comments:** 

**Creditor Comments:** 

**Public Comments:** 


Starts/Runs: Yes Overall: Fair

## Unit: 2012 Volvo EC220DL

# Lessee: Coogler Construction Contract: 502-7629728-010


	DEFICIENCY RE
ITEM	OTY PRICE
1. Underneath Quick Access Panel Missing- Repaired	\$0.00
2. Clean Machine Inside and Out- Done	\$0.00
<ol> <li>Bent Track Show Right Side- Not Repaired</li> </ol>	\$0.00
4. Front Windshield Damaged- Repaired	\$0.00
5. All Mirrors and Brackets Missing- Replaced	\$0.00
6. Windshield Wipers Inop- Repaired	\$0.00
7. Heater Inop- Not Repaired	\$0.00
8. A/C Inop- Not Repaired	\$0.00
9. Motor is Apart- Cracked Head- Repaired	\$0.00
10. Fuel Injector Removed- Repaired	\$0.00
11. Fuel Tank Full of Coolant- Repaired	\$0.00
12. Radiator Dirty- Repaired	\$0.00
13. Cooler Fins Damaged- Not Repaired	\$0.00
14. Replace Batteries- Replaced	\$0.00
15. Lighting Inop- Repaired	\$0.00
16. Bucket Cylinder Leaks- Repaired	\$0.00
Total	\$0.00

Unit: 2012 Volvo EC220DL



### Unit: 2012 Volvo EC220DL


UNIT # 210093 Location: ASC Construction Equipment, Cayce SC



## Unit: 2012 Volvo EC220DL



### Unit: 2012 Volvo EC220DL



Unit: 2012 Volvo EC220DL

UNIT # 210093 Location: ASC Construction Equipment, Cayce SC

