VOLVO - INSPECTION REPORT

Volvo, Ec220e - Track Excavators

Comment:

Dealer: Arnold Machinery Company Country: US Location: Las vegas Date: 09/10/2020 Inspector: Mike seifert Year: 2017 Make: Volvo Model: Ec220e Hours: 2444 Serial number: 310579 Engine S/N: 12005480 Matris hours: 2452 Comment: **Equipped Configuration** [X] Yes EROPS [] Yes Cab risers [X] Yes Proportional joystick controls [] Yes Joystick controls [X] Yes Air conditioning **1 Yes** Cab riser hydraulic [X] Yes Thumb - Manual] Yes Stick short [X] Yes Standard car body [X] Yes Stick medium 1 Yes Hydraulic retractable UC 1 Yes Thumb hydraulic [X] Yes Auxiliary hydraulics] Yes 2 Piece boom] Yes Counterweight removal sys.] Yes Long reach arrangement] Yes Hose rupture valves [X] Yes Long undercarriage] Yes Drill arrangement [X]Yes Boom float] Yes Quick coupler manual] Yes Recycling arrangement] Yes Attachment circuits] Yes Quick coupler hydraulic] Yes Demolition arrangement] Yes Leveling blade] Yes Auto Lube] Yes Mass excavator arrangement] Yes Cushion boom cylinder [X] Yes Travel pedal] Yes Forestry arrangement This machine has a dafo fire suppression system Comment: **Images** Comment: **Operators Station** [X] Fair Remarks: Small burn hole in seat Seat and armrest Dash and console [X] Good Floor Board/Mat [X] Good Cab glass [X] Good Mirrors [X] Fair Remarks: Some rust on brackets Interior light [X] Good Switches [X] Good Wipers [X] Good Gauges [X] Good Hydraulic controls [X] Good Powertrain controls [X] Good [X] Good AC cooling [X] Fair Remarks: Small cracks in counsels **CAB** Interior Operators station condition summary

Outside appearanc	е	
Steps	[X] Fair Remarks:	
Hand rails	[X] Fair Remarks:	Rusted hardware
Counterweight /	[X] Fair Remarks:	Scratched and gouged
Bumper		
Grill	[X] Fair Remarks:	Creased
Hood	[X] Fair Remarks:	Small scratches rust on hardware
Exhaust stack	[X] Good	
Pre-cleaner bowl	[X] Good	
Front fenders	[X] Fair Remarks:	Dented
Hyd tank	[X] Good	
Fuel tank	[X] Good	
Car body	[X] Fair Remarks:	Dented and creases
Fenders	[X] Fair Remarks:	
OEM Welds	[X] Good	
Sheet metal	[X] Fair Remarks:	Rear doors creases
Paint	[X] Fair Remarks:	Needs
Outside appearance condition summary		
Comment:		
Safety condition		
Safety decals in place	[X]Yes	
Operators manual	[X]Yes	
Safety handles	[X] Good	
Seat belt	[X] Good	
Horn	[X] Good	
Back up alarm	[X] Good	
Brake hold	[X] Good	
ROPS Structure	[X] Good	
Guarding	[X] Fair Remarks:	Pan good still has bent channel front can't be bent back due to bent car body
CAB	[X] Good	
Safety condition summary		
Comment:		

Electrical condition

Computer	[X] Good
ECM'S	[X] Good
Monitor / Display	[X] Good
Wiring harness's	[X] Good
Key switch	[X] Good
Switches	[X] Good
Lighting	[X] Good
Engine preheater	[X] Good
Batteries / Connection	ns [X] Good
Battery disconnect	[X] Good
switch	
Electrical condition	
summary	
Comment:	

Engine condition

Oil level OK	[X]Yes
Water in oil	[X] No
Compression	[X]Yes
Blow by	[X] No
Engine knocking	[X] No
CE PLATE	[X]Yes
Oil pressure	[X]Good
Oil leaks	[X] No
EPA DECAL	[X]Yes
Turbo charger	[X] Good
Exhaust manifold	[X] Good
Muffler	[X] Good
Fuel injection system	[X] Good
Head gasket	[X] Good
Head	[X] Good
Fan guard	[X] Good
Belts & pulleys	[X] Good
Wiring harness	[X] Good
Starter	[X] Good
Alternator	[X] Good
Seals & gaskets	[X] Good

Engine mounts	[X] Good
Brackets	[X] Good
AC Compressor	[X] Good
Air filters	[X] Good
Engine condition summary	
Comment:	
Cooling system	
Coolant color	Yellow
Radiator	[X] Good
Water pump	[X] Good
Oil cooler	[X] Good
Fan	[X] Fair Remarks: Still has small dent in shroud
Fan drive	[X] Good
Hoses	[X] Good
Cooling system summary	
Comment:	
Hydraulics condition	on
Boom cylinders	[X] Good
Stick cylinders	[X] Good
Bucket cylinders	[X] Good
Blade cylinders	[] Good [] Fair [] Poor Remarks:
Thumb cylinders	[] Good [] Fair [] Poor Remarks:
Pumps	[X] Good
Valves	[X] Good
Hoses	[X] Good
Fittings	[X] Fair Remarks: Small amount of rust
Tank	[X] Good
Swing bearing	[X] Good
Swing gear	[X] Good
Swing motor	[X] Good
Hydraulic swivel	[X] Good
Travel motors	[X] Good
Pump drive	[X] Good
Planetaries left	[X] Good
Planetaries right	[X] Good
Controls	[X] Good
Overall condition	[X] Good

Comment:			
Boom & arm con	odition		
Lower stick pins	[X] Good		
Upper stick pins	[X] Good		
Stick condition	[X] Fair Remarks: Some scratches		
Stick length	3.5m		
Boom length	5.7m		
Lower boom pins	[X] Good		
Upper boom pins	[X] Good		
Boom condition	[X] Fair Remarks: Some scratches		
Summary			
Comment:			
Bucket & other a	ttachments		
Bucket type / Size	Pemberton thumb		
Coupler type			
Bucket serial	Egr3001806-2/3-1017		
Coupler serial			
Bucket W / Teeth	[]Yes []No		
Addtl attachments	Thumb		
Bolt on smooth	[]Yes []No		
Bolt on edge	[] Good [] Fair [] Poor Remarks:		
Bucket mounts	[] Good [] Fair [] Poor Remarks:		
Duelot to oth	[] Cood [] Feir [] Door Demoder		
Bucket teeth / Segments	[] Good [] Fair [] Poor Remarks:		
Bucket sides	[] Good [] Fair [] Poor Remarks:		
Bucket floor	[] Good [] Fair [] Poor Remarks:		
Bucket bottom	[]Good []Fair []Poor Remarks:		
Coupler	[] Good [] Fair [] Poor Remarks:		
Boom / Frame	[] Good [] Fair [] Poor Remarks:		

Boom / Bucket pins & bushings	[X] Good
Summary	
Comment:	
Undercarriage con	dition
Roller frame right	[X] Good
Roller frame left	[X] Good
Track adjusters	[X] Good
Overall condition	[X] Fair Remarks: 7 slightly bent grousers
Links left	
Links left	55%
Internal pin wear left	
Internal pin wear left	60%
External pin wear left	
External pin wear left	65%
Trackshoe/ Grouser left	
Trackshoe/ Grouser left	60%
Front Idler left	
Front Idler left	80%
Sprockets left	
Sprockets left	60%
Front Carrier Rollers left	
Front Carrier Rollers left	65%
Center Carrier Rollers left	
Center Carrier Rollers left	
Rear Carrier Rollers left	
Rear Carrier Rollers left	65%
Links right	
Links right	60%

Internal pin wear right			
Internal pin wear right	60%		
internal pin wear right	00%		
External pin wear right			
External pin wear right	65%		
Trackshoe/ Grouser right			
Trackshoe/ Grouser right	80%		
Front Idler right			
Front Idler right	80%		
Sprockets right			
Sprockets right	60%		
Front Carrier Rollers right			
Front Carrier Rollers right	65%		
Center Carrier Rollers right			
Center Carrier Rollers right			
Rear Carrier Rollers right			
Rear Carrier Rollers right	65%		
Bottom rollers S or D	S		
Undercarriage brand	Volvo		
Link part number			
Pins & bushings turned	No		
Comment:			
Bottom rollers S or	r D		
Bottom rollers S	or D left (mm)	Bottom rollers S or D left (%)	Bottom rollers S or D right (mm)
Bottom rollers S	mm S or D right (%)	70% Bottom rollers S or D left (mm)	Bottom rollers S or D left (%)
70% Bottom rollers S		Bottom rollers S or D right (%)	70% Bottom rollers S or D left (mm)
Bottom rollers	mm	70% Bottom rollers S or D right (mm)	mm Bottom rollers S or D right (%)
70%		mm	70%
Bottom rollers S	mm	Bottom rollers S or D left (%) 70%	Bottom rollers S or D right (mm) mm
Bottom rollers S 70%		Bottom rollers S or D left (mm) mm	Bottom rollers S or D left (%) 65%
Bottom rollers S		Bottom rollers S or D right (%)	Bottom rollers S or D left (mm)
Dottom rollors	mm S or D loft (%)	65% Bottom rollers S or D right (mm)	mm Rottom rollors S or D right (%)
Bottom rollers 5	3 01 D leit (70)	Bottom rollers 5 or D right (mm)	Bottom rollers S or D right (%) 70%
Bottom rollers S	G or D left (mm)	Bottom rollers S or D left (%)	Bottom rollers S or D right (mm)
	mm` ´	70%	mm

Bottom rollers S of 70%		Bottom rollers S or D left (mm)	Bottom rollers S or D left (%) 65%
Bottom rollers S o	r D right (mm)	Bottom rollers S or D right (%)	Bottom rollers S or D left (mm)
	mm	70%	mm
Bottom rollers S	or D left (%)	Bottom rollers S or D right (mm)	Bottom rollers S or D right (%)
70%		mm	65%
Bottom rollers S of	or D left (mm)	Bottom rollers S or D left (%)	Bottom rollers S or D right (mm)
	mm	70%	mm
Bottom rollers S of 70% Comment:			
Legend (5 star rating) Paint general		B []2 []1 · []Poor Remarks:	
Comment:			