VOLVO - INSPECTION REPORT

Volvo, A45G - Articulated haul trucks

Country: US Date: 09/21/2020 Make: Volvo Serial number: 342416 Dealer: Hoffman Equipment Inspector: Mark Model: A45G

Location: Deptford Year: 2018 Hours: 2317

Engine S/N: 112079 Matris hours: Trans S/N: 1700109632 Comment: **Equipped Configuration** [] Yes Scraper ARRG. [X] Yes Standard Cab] Yes Fuel Heater] Yes Low Profile Cab] Yes Water Tank] Yes Full Suspension **1 Yes** LED Light [X] Yes Standard Body 1 Yes Frame Ext. [X] Yes Strobe Light [X] Yes Extra Spill Guard] Yes Onboard Weight Sys. [X] Yes Hydraulic switch control] Yes Bed Liner Metal [X] Yes Exhaust Body Heat [X] Yes Overhung Tailgate] Yes Bed Liner Plastic [X] Yes Hydraulic lever control [] Yes Auto Lube System] Yes Underhung Tailgate [X] Yes Back Up Camera] Yes Fire Suppression System] Yes Underground ARRG. [] Yes Fast Fuel [X] Yes Mud Flaps Comment: **Images** Comment: **Operators Station** Seats and armrest [X] Good Dash and console [X] Good Floor Board/Mat [X] Good Cab glass [X] Good Mirrors [X] Good Interior light [X] Good Switches [X] Good Wipers [X] Good Gauges [X] Good Hydraulic controls [X] Good Powertrain controls [X] Good AC cooling [X] Good **CAB** Interior [X]Good Operators station condition summary Comment:

Outside appearance

Steps	[X] Good
Hand rails	[X] Good
Counterweight /	[X] Good
Bumper	
Grill	[X] Good
Hood	[X] Good
Exhaust stack	[X] Good
Pre-cleaner bowl	[X] Good
Front fenders	[X] Good
Hyd tank	[X] Good
Fuel tank	[X] Good
Def tank	[X] Good
Front frame & welds	[X] Good
Rear frame & welds	[X] Good
Sheet metal	[X] Good
Paint	[X] Good
Outside appearance condition summary	
Condition Summary	
Comment:	

Safety condition

[X]Yes Safety decals in place Operators manual [X]Yes Safety handles [X]Good Seat belt [X]Good Horn [X]Good Back up alarm [X]Good Brake lights [X]Good [X]Good Turn signals Hazard lights [X]Good **ROPS Structure** [X]Good CAB [X]Good Safety condition summary

Electrical condition

Comment:

Computer [X] Good
ECM'S [X] Good
Monitor / Display [X] Good
Wiring harness's [X] Good
Key switch [X] Good
Switches [X] Good

Lighting	[X] Good
Engine preheater	[X] Good
Batteries / Connections	
Battery disconnect switch	[X] Good
Electrical condition summary	
cumuly	
Comment:	
Engine condition	
Engine condition	LWIV
Oil level OK	[X]Yes
Water in oil	[X]No
Compression in radiator	[X]No
Blow by	[X] No
Engine knocking	[X]No
CE PLATE	[X]Yes
Oil pressure	[X] Good
Oil leaks	[X]No
EPA DECAL	[X]Yes
Turbo charger	[X] Good
Exhaust manifold	[X] Good
Muffler	[X] Good
Fuel injection system	[X] Good
Head gasket	[X] Good
Head	[X] Good
Fan guard	[X] Good
Belts & pulleys	[X] Good
Wiring harness	[X] Good
Starter	[X] Good
Alternator	[X] Good
Seals & gaskets	[X] Good
Engine mounts	[X] Good
Brackets	[X] Good
AC Compressor	[X] Good
Air filters	[X] Good
Engine condition summary	
Comment:	

Cooling system	
Coolant color	Yellow
Radiator	[X] Good
Water pump	[X] Good
Oil cooler	[X] Good
Fan	[X] Good
Fan drive	[X] Good
Hoses	[X] Good
Cooling system summary	
Comment:	
Transmission con	dition
Oil level OK	[X]Yes
Water in oil	[X] No
Any leaks	[X]No
Torque converter	[X] Good
Case	[X] Good
Pump	[X] Good
Hoses	[X] Good
Retarder	[X] Good
Transfer case	[X] Good
Shifting forward	[X] Good
Shifting reverse	[X] Good
Transmission summar	У
Comment:	
Axels-Final Drives	-Brakes
Front differential	[X] Good
Center differential	[X] Good
Rear differential	[X] Good
Differential supports	[X] Good
Drive shafts	[X] Good
UV Joints	[X] Good

Planetaires front	[X] Good
Planetaires center	[X] Good
Planetaires rear	[X] Good
Hoses / Lines	[X] Good
Torsion rods	[X] Good
Holds in park	[X]Yes
Brakes wet	[X]Yes
Holds thru all gears	[X]Yes
Brakes dry	[X] No
Brake disk / calipers	[X] Good
Brake lines	[X] Good
Seals	[X] Good
Parking brake	[X] Good
Summary	
Comment:	
Comment.	
Steering & articular Steering cylinders Pumps	[X] Good
Valves	[X] Good
Lines / Hoses	[X] Good
Secondary steering	[X] Fair Remarks: No secondary steering
Steering pins &	[X] Good
bushings Steering wheel tilt & function	[X] Good
Articulation pins & bushings	[X] Good
Summary	
Comment:	
Hydraulics condition	on
Bed lift cylinders	[X] Good
Pumps	[X] Good
Valves	[X] Good
Hoses	[X] Good
Fittings	[X] Good
Tank	[X] Good
Controls	[X] Good
Bed float	[/] 5000
Ded float	[X] Good
Operational condition Summary	

Comment:		
Bed & other attach	chments	_
Bed type / Size		
Tailgate S / N	N/A	
Bed serial	N/A	
Addtl attachments	None	٦
Spill guard	[X] Good	_
Body	[X] Good	
Bed liner	[X] Fair Remarks:	
Bed sides	[X] Good	
Bed floor	[X] Good	
Wear plates	[X] Fair Remarks:	I
Tailgate	[X] Good	
Pins & bushings	[X] Good	
Summary		
Comment:		
Tires & rims		
Make	Bridgestone V Steel 29.5 R25	
Serial	F7J483108 40/32 new 60	
% Remaining	65%	
Make	Bridgestone V Steel 29.5 R25	
Serial	F7J481014 40/32 new 60	
% Remaining		
	65%	
Make	Bridgestone V Steel 29.5 R25	
Serial	F7J481010 40/32 new 60	
% Remaining	65%	
Make	Bridgestone V Steel 29.5 R25	
Serial	F7J383163 40/32 new 60	
% Remaining	65%	
Make	Bridgestone V Steel 29.5 R25	
Serial	F7J485559 40/32 new 60	
% Remaining	65%	
Make	Bridgestone V Steel 29.5 R25	
Serial	F7J485109 40/32 new 60	
0/ Daws-!!		
% Remaining	65%	

Recapped	[X]No	
Tread cuts	[X] No	
Side wall cuts	[X] No	
Tire size the same	[X] Yes Remarks:	
Overall tire condition	[X] Good	
Rims	[X] Good	
Lug nuts & studs	[X] Good	
Comment:		
General Comments		
Legend (5 star rating) Paint general	[]5 []4 []3 []2 []1 []Good []Fair []Poor Remarks:	
Comment:		