

SPECIFICATIONS

VIN	341370
LeaseInspector ID #	341370
Year	2017
Model	Volvo A40G
Location City	Cayce
Location State	SC
General Specifications	
Tires	
Lt Rear Tread Depth	28
Rt Rear Tread Depth	32
Left Rear Rear Tread Depth	26
Right Rear Rear Tread Depth	27
New Hours	4066
Old Hours	4064

ADDITIONAL FEATURES OF THIS VEHICLE COMMENTS

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes Overall: Fair

DEFICIENCY REVIEW

ITEM	QTY PRICE
1. Hydraulic Oil Low- Repaired	\$0.00
2. Service Machine if Due- Serviced	\$0.00
3. Clean Machine- Done	\$0.00
4. Coolant Level Low- Not Repaired	\$0.00
5. 3 Rear Tires Past 50%- Not Replaced	\$0.00
6. Machine Appears to be Due for Service- Serviced	\$0.00
Total	\$0.00















