

SPECIFICATIONS

VIN	342157
LeaseInspector ID #	342157
Year	2017
Model	Volvo A40G
Location City	Cayce
Location State	SC
General Specifications	
New Hours	4725
Old Hours	4725

ADDITIONAL FEATURES OF THIS VEHICLE COMMENTS

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes Overall: Fair

DEFICIENCY REVIEW

ITEM	QTY PRICE
1. A/C Switch Cracked- Replaced	\$0.00
2. 1 Armrest Missing- Replaced	\$0.00
3. Right Front Fender Paint Worn- Not Repaired	\$0.00
4. Clean Machine Inside, Out, Engine, Undercarriage- Not Done	\$0.00
5. Dealer to Determine is Service is Due- Not Repaired	\$0.00
6. Air Cleaner Dirty- Replaced	\$0.00
7. Left Rear of Engine Block Collection- Not Repaired	\$0.00
8. Roof Light Inop- Repaired	\$0.00
Total	\$0.00





