

**Lessee: Superior Construction  
Company  
Contract: 502-7674819-028**

**Unit: 2016 Volvo L90H**

**UNIT # 623686  
Location: Flagler Construction  
Equipment, Jacksonville FL**



### **SPECIFICATIONS**

VIN	623686
LeaseInspector ID #	623686
Year	2016
Model	Volvo L90H
Location City	Jacksonville
Location State	FL
<b>General Specifications</b>	
New Hours	1802
Old Hours	1797

**Lessee: Superior Construction  
Company  
Contract: 502-7674819-028**

**Unit: 2016 Volvo L90H**

**UNIT # 623686  
Location: Flagler Construction  
Equipment, Jacksonville FL**

**ADDITIONAL FEATURES OF THIS VEHICLE  
COMMENTS**

**Appraiser Comments:**

**Creditor Comments:**

**Public Comments:**

**Starts/Runs:** Yes  
**Overall:** Fair

**Lessee: Superior Construction  
Company  
Contract: 502-7674819-028**

**Unit: 2016 Volvo L90H**

**UNIT # 623686  
Location: Flagler Construction  
Equipment, Jacksonville FL**



**DEFICIENCY REVIEW**

<b>ITEM</b>	<b>QTY PRICE</b>
1. Clean Machine Inside, Out, Engine, Undercarriage- Done	\$0.00
2. Dealer to Determine if Service is Due- Done	\$0.00
3. Dealer to Verify Tire Cuts are Cosmetic Only- Repaired	\$0.00
4. Dead Batteries - Had to Jump Start- Repaired	\$0.00
5. Bucket Cutting Edge Worn- Repaired	\$0.00
6. Right Front Tire has Sidewall Cut- Repaired	\$0.00
<b>Total</b>	<b>\$0.00</b>

**Lessee: Superior Construction Company**  
**Contract: 502-7674819-028**

**Unit: 2016 Volvo L90H**

**UNIT # 623686**  
**Location: Flagler Construction Equipment, Jacksonville FL**



**Lessee: Superior Construction  
Company  
Contract: 502-7674819-028**

**Unit: 2016 Volvo L90H**

**UNIT # 623686  
Location: Flagler Construction  
Equipment, Jacksonville FL**



**Lessee: Superior Construction  
Company  
Contract: 502-7674819-028**

**Unit: 2016 Volvo L90H**

**UNIT # 623686  
Location: Flagler Construction  
Equipment, Jacksonville FL**

