Unit: 2017 Volvo A40G

Lessee: Southern Ionics Minerals Contract: 502-7693331-004 UNIT # 2037 Location: Flagler Construction Equipment, Jacksonville FL



SPECIFICATIONS

Serial Number 2037
LeaseInspector ID # 2037
Year 2017
Model Volvo A40G
Location City Jacksonville

Location State F

Unit: 2017 Volvo A40G UNIT # 2037 Location: Flagler Construction Equipment, Jacksonville FL

ADDITIONAL FEATURES OF THIS VEHICLE COMMENTS

Appraiser Comments:

Creditor Comments:

Hours: 4763

Public Comments:

Hours: 4763

Starts/Runs: Yes Overall: Fair


Unit: 2017 Volvo A40G

UNIT # 2037 Location: Flagler Construction Equipment, Jacksonville FL

DEFICIENCY REVIEW

ITEM	QTY PRICE
1. Transmission Inop - Repaired	\$0.00
2. Repair to Stay Runing - Repaired	\$0.00
3. Dealer to Determine if Service is Due - Per Contact, Up-to-Date	\$0.00
4. Clean Machine Inside, Out, Engine, Undercarriage - Not Complete	\$0.00
5. Bed Full of Dirt - Less Dirt	\$0.00
6. Right Rear Tire Cut - Not Replaced	\$0.00
7. Batteries Dead - Repaired	\$0.00
8. Brake Fluid Low - Not Repaired	\$0.00
9. Differential Leaking - Repaired	\$0.00
10. Hoses Above Center Differential Seeping - Repaired	\$0.00
11. Bed Safetly Lock Pin Missing - Replaced	\$0.00
12. Dash Console Damaged, 1 Cracked Panel - Replaced	\$0.00
13. 3 Damaged Switches - Replaced	\$0.00
14. HVAC Controls Damaged - Replaced	\$0.00
15. 5 Switch Blanks Missing - Replaced	\$0.00
16. Cigarette Light Missing - Replaced	\$0.00
17. Ashtray Light Missing - Replaced	\$0.00
Total	\$0.00

Unit: 2017 Volvo A40G



Unit: 2017 Volvo A40G



Unit: 2017 Volvo A40G



Unit: 2017 Volvo A40G

