VOLVO - INSPECTION REPORT

Volvo, A40G - Articulated haul trucks

Images















Comment:			
Country: US	Dealer: Arnold Machinery Company	Location: Las Vegas	

Date: 06/26/2019 Make: Volvo Serial number: 341073 Trans S/N: 1700106429 Inspector: Model: A40G Engine S/N: 091970 Location: Las Vegas Year: 2015 Hours: 5693 Matris hours:

Comment:

Equipped Configuration

[X] Yes Standard Cab	[] Yes Scraper ARRG.	[] Yes Fuel Heater
[] Yes Water Tank	[] Yes Low Profile Cab	[] Yes Full Suspension
[] Yes LED Light	[X]Yes Standard Body	[] Yes Frame Ext.
[X] Yes Strobe Light	[] Yes Extra Spill Guard	[X] Yes Onboard Weight Sys.
[] Yes Hydraulic switch control	[] Yes Exhaust Body Heat	[] Yes Bed Liner Metal
[X] Yes Hydraulic lever control	[X] Yes Overhung Tailgate	[] Yes Bed Liner Plastic
[] Yes Auto Lube System	[] Yes Underhung Tailgate	[X]Yes Back Up Camera
[] Yes Fire Suppression System] Yes Underground ARRG.	[] Yes Fast Fuel
[X] Yes Mud Flaps		
Comment:		

Operators Station

Seats and armrest [X] Good Dash and console [X] Good Floor Board/Mat [X]Good Cab glass [X]Good Mirrors [X]Good Interior light [X]Good Switches [X]Good Wipers [X] Good [X]Good Gauges

Hydraulic controls	[X] Good
Powertrain controls	[X] Good
AC cooling	[X] Good
CAB Interior	[X] Good
Operators station condition summary	Missing operators manual
Comment:	
Outside appearand	ce
Steps	[X] Good
Hand rails	[X] Good
Counterweight /	[X] Good
Bumper	
Grill	[X] Good
Hood	[X] Good
Exhaust stack	[X] Good
Pre-cleaner bowl	[X] Good
Front fenders	[X] Good
Hyd tank	[X] Good
Fuel tank	[X] Good
Def tank	[X] Good
Front frame & welds	[X] Good
Rear frame & welds	[X] Good
Sheet metal	[X] Good
Paint	[X] Good
Outside appearance condition summary	
Comment:	
Safety condition	
Safety decals in place	[X]Yes
Operators manual	[X] No
Safety handles	[X] Good
Seat belt	[X] Good
Horn	[X] Good
Back up alarm	[X] Good

[X]Good

[X] Good

[X] Good

Brake lights

Turn signals

Hazard lights

ROPS Structure	[X] Good
CAB	[X] Good
Safety condition summary	
Comment:	
Electrical condition	l
Computer	[X] Good
ECM'S	[X] Good
Monitor / Display	[X] Good
Wiring harness's	[X] Good
Key switch	[X] Good
Switches	[X] Good
Lighting	[X] Good
Engine preheater	[X] Good
Batteries / Connections	
Battery disconnect	[X] Good
switch Electrical condition	
summary	
Comment:	
Engine condition	
Oil level OK	[X]Yes
Water in oil	[X]No
Compression in radiator	[X] No
Blow by	[X]No
Engine knocking	[X] No
CE PLATE	[X]Yes
Oil pressure	[X] Good
Oil leaks	[X]Yes
EPA DECAL	[X]Yes
Turbo charger	[X] Good
Exhaust manifold	[X] Good
Muffler	[X] Good
Fuel injection system	[X] Good
Head gasket	[X] Good

[X] Good

Head

Fan guard	[X] Good
Belts & pulleys	[X] Good
Wiring harness	[X] Good
Starter	[X] Good
Alternator	[X] Good
Seals & gaskets	[X] Good
Engine mounts	[X] Good
Brackets	[X] Good
AC Compressor	[X] Good
Air filters	[X] Good
Engine condition summary	Oil press. 67 psi
Comment:	
Comment.	
Cooling system	
Coolant color	Green
Radiator	[X] Good
Water pump	[X] Good
Oil cooler	[X] Good
Fan	[X] Good
Fan drive	[X] Good
Hoses	[X] Good
Cooling system summary	
Comment:	
Transmission cor	ndition
Oil level OK	[X]Yes
Water in oil	[X] No
Any leaks	[X] No
Torque converter	[X] Good
Case	[X] Good
Pump	[X] Good
Hoses	[X] Good
Retarder	[X] Good
Transfer case	[X] Good

Shifting forward	[X] Good
Shifting reverse	[X] Good
Transmission summar	у
Comment:	
Axels-Final Drives	-Brakes
Front differential	[X] Good
Center differential	[X] Good
Rear differential	[X] Good
Differential supports	[X] Good
Drive shafts	[X] Good
UV Joints	[X] Good
Planetaires front	[X] Good
Planetaires center	[X] Good
Planetaires rear	[X] Good
Hoses / Lines	[X] Good
Torsion rods	[X] Good
Holds in park	[X]Yes
Brakes wet	[X]Yes
Holds thru all gears	[X]Yes
Brakes dry	[X]No
Brake disk / calipers	[X] Good
Brake lines	[X] Good
Seals	[X] Good
Parking brake	[X] Good
Summary	
Comment:	
Steering & articula	ation condition
Steering cylinders Pumps Valves	[X] Good [X] Good [X] Good
Lines / Hoses	[X] Good
Secondary steering	[X] Good
Steering pins &	[X] Fair Remarks: Slightly worn still operable

bushings

Steering wheel tilt & function	[X] Good
Articulation pins &	[X] Fair Remarks: Slightly worn still operable
bushings	
Summary	
Comment:	
Hydraulics condition	on
Bed lift cylinders	[X] Good
Pumps	[X] Good
Valves	[X] Good
Hoses	[X] Good
Fittings	[X] Good
Tank	[X] Good
Controls	[X] Good
Bed float	[X] Good
Operational condition	[X] Good
Summary	
Comment:	
5 10 41 41 11	
Bed & other attach	iments
Bed type / Size	
Tailgate S / N	
Tallgate 37 IV	
Bed serial	
A -1-141 -4414-	
Addtl attachments	
Spill guard	[X] Fair Remarks: No spillguard
Body	[X] Good
Bed liner	[X] Good
Bed sides	[X] Good
Bed floor	[X] Good
Wear plates	[X] Good
Tailgate	[X] Good
Pins & bushings	[X] Good
Summary	[7,] 5555
•	
Comment:	
Tires & rims	
Make	Michelin L1
Serial	EPU 4427G7A 55/32
% Remaining	

Make	Michelin L2
Serial	EPU 4431G3A 55/32
% Remaining	
Make	Michelin L3
Serial	EPU 2000G4A 55/32
% Remaining	
Make	Michelin R1
Serial	EPU 4432G2A 54/32
% Remaining	
Make	Michelin R2
Serial	EPU 4430G4A 54/32
% Remaining	
Make	Michelin R3
Serial	EPU 4426G8A 55/32
% Remaining	
Recapped	[X] No
Tread cuts	[X] No
Side wall cuts	[X] No
Tire size the same	[X] Yes Remarks: 29.5R25
Overall tire condition	[X] Good
Rims	[X] Good
Lug nuts & studs	[X] Good
Comment:	
General Comments	s
Legend (5 star rating) Paint general	[]5 []4 []3 []2 []1 []Good []Fair []Poor Remarks:
Comment:	