

2016 Volvo A25G

Serial #: 0243

Imerys Refractory Minerals
Andersonville, GA
229-815-6118

- Rear vision system
- Air ride seat
- Computer display
- Mudflaps
- SMU/Hours: 5775
- Overall: Fair
- Radio
- Differential locks
- Rotating beacon
- Tailgate
- Start Run: Yes
- Insp Date: 3/10/2020



General Appearance

<table style="width: 100%; border-collapse: collapse;"> <tr><td>Radiator Grille:</td><td>Good</td></tr> <tr><td>Radiator Shroud:</td><td>Good</td></tr> <tr><td>Engine Enclosure:</td><td>Good</td></tr> <tr><td>Hood:</td><td>Good</td></tr> <tr><td>Stack:</td><td>Good</td></tr> <tr><td>Right front fender:</td><td>Good</td></tr> <tr><td>Left front fender:</td><td>Good</td></tr> <tr><td>Rear frame:</td><td>Good</td></tr> <tr><td>Front frame:</td><td>Good</td></tr> </table>	Radiator Grille:	Good	Radiator Shroud:	Good	Engine Enclosure:	Good	Hood:	Good	Stack:	Good	Right front fender:	Good	Left front fender:	Good	Rear frame:	Good	Front frame:	Good	<table style="width: 100%; border-collapse: collapse;"> <tr><td>Precleaner bowl:</td><td>Good</td></tr> <tr><td>Fuel Tank:</td><td>Good</td></tr> <tr><td>Cab Doors:</td><td>Good</td></tr> <tr><td>Bumper:</td><td>Good</td></tr> <tr><td>Cab:</td><td>Good</td></tr> <tr><td>Steps:</td><td>Fair</td></tr> <tr><td>Grab Irons/Handrails:</td><td>Good</td></tr> <tr><td>Paint:</td><td>Good</td></tr> <tr><td>Oil Sample Taken:</td><td>No</td></tr> </table>	Precleaner bowl:	Good	Fuel Tank:	Good	Cab Doors:	Good	Bumper:	Good	Cab:	Good	Steps:	Fair	Grab Irons/Handrails:	Good	Paint:	Good	Oil Sample Taken:	No
Radiator Grille:	Good																																				
Radiator Shroud:	Good																																				
Engine Enclosure:	Good																																				
Hood:	Good																																				
Stack:	Good																																				
Right front fender:	Good																																				
Left front fender:	Good																																				
Rear frame:	Good																																				
Front frame:	Good																																				
Precleaner bowl:	Good																																				
Fuel Tank:	Good																																				
Cab Doors:	Good																																				
Bumper:	Good																																				
Cab:	Good																																				
Steps:	Fair																																				
Grab Irons/Handrails:	Good																																				
Paint:	Good																																				
Oil Sample Taken:	No																																				
LEGEND OF CONDITIONS:																																					
<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%; vertical-align: top;"> <p>Excellent - New condition. No Repairs Necessary.</p> <p>Good - No apparent wear or damage, Functions/Operates correctly. No Repairs Necessary.</p> <p>Fair - Wear and/or damage apparent. Functions, but not correctly. Repairs recommended.</p> </td> <td style="width: 50%; vertical-align: top;"> <p>Poor - Obvious wear and/or damage. Repairs necessary.</p> <p>Not Applicable - Does not apply to this unit</p> </td> </tr> </table>		<p>Excellent - New condition. No Repairs Necessary.</p> <p>Good - No apparent wear or damage, Functions/Operates correctly. No Repairs Necessary.</p> <p>Fair - Wear and/or damage apparent. Functions, but not correctly. Repairs recommended.</p>	<p>Poor - Obvious wear and/or damage. Repairs necessary.</p> <p>Not Applicable - Does not apply to this unit</p>																																		
<p>Excellent - New condition. No Repairs Necessary.</p> <p>Good - No apparent wear or damage, Functions/Operates correctly. No Repairs Necessary.</p> <p>Fair - Wear and/or damage apparent. Functions, but not correctly. Repairs recommended.</p>	<p>Poor - Obvious wear and/or damage. Repairs necessary.</p> <p>Not Applicable - Does not apply to this unit</p>																																				
NOTES:																																					

Interior Section

Glass: Good	Neutral Start Switch: Good
Mirrors: Good	Fire Suppression System: Not Available
Seat Belt: Good	Horn: Good
Back Up Alarm: Good	
Fan Guards: Good	
NOTES:	
Dash Console: Good	
Meter: Good	Seat Cushion: Good
Gauges: Good	Arm Rests: Good
Control Pattern Decals: Good	Floor Boards/Mats: Good
Switches: Good	EMS Panel: Good
Windshield Wipers: Good	Warnings: Good
Heater: Good	Door Latches: Good
A/C: Good	Current Parts Manual: Yes
Interior Lights: Good	Current Safety Manual: Yes
	Current O&M Manual: Yes
NOTES:	

Power Systems

Engine Make Model: Volvo N/A Engine S/N: N/A Engine Hours: 5775 Oil Leaks: No Blow-by: No Knocking: No Compression in Radiator: No Water in Oil: No Fluid Level OK?: Yes Anit-Freeze Color: Gold	Oil Pressure: Normal Smoke: No Smoke Color: Not Applicable TurboCharger: Good Fuel Injection System: Good Governor: Good Engine Supports: Good Air Cleaners: Good
NOTES:	
Radiator: Good Coolers: Good Hoses: Good Water Pump: Good	Fan: Good Fan Drive: Good Belts: Good Pulleys: Good
NOTES:	
Batteries: Good Battery Cables: Good Starter: Good Alternator: Good	Wiring: Good Pre-Heater: Good Lighting: Good
NOTES:	

Power Systems - Continued

Transmission Serial #: N/A Transmission Type: Auto Transmission Speeds: 9 Transmission Forward: Good Transmission Reverse: Good Case: Good Controls: Good	Seals: Good Torque Converter: Not Available Temp/Pressure Gauges: Good Transmission Fluid: Good Is the Transmission Noisy?: No Transmission Retarder: Yes
NOTES:	
Steering Linkage: Good Steering Valve: Good Steering Pump: Good Articulation P & B: Good	Left steering cylinder: Good Right steering cylinder: Good Steering joints: Good
NOTES:	
Mechanism: Wet Type: Pedal Performance: Good Brake drums: Not Available Rotors: Good Control Valve: Good	Lines: Good Compressor: Good Brake linkage: Good Master cylinder: Not Available Parking brake: Good
NOTES:	
Front axle: Good Front differential: Good Rear axles: Good Rear differentials: Fair Front wheel lugs & rims: Good Rear wheel lugs & rims: Good Front axle bolts: Good Rear axle bolts: Good Front axle housing: Good	Rear axle housing: Good U-Joints: Good Front suspension: Good Rear suspension: Good Front a-stay: Good Rear a-stay: Good
NOTES:	

2016 Volvo A25G

(Continued)

Serial #: 0243

Hydraulics

Right dump cylinder:	Good	Valves:	Good
Left dump cylinder:	Good	Control linkage:	Good
Hose lines:	Good	Reservoir:	Good
Pumps:	Good	Dump cycle test:	Good
NOTES:			

2016 Volvo A25G

(Continued)

Serial #: 0243

Dump Body

Body type:	Standard	Body pins and bushings:	Good
Body bottom:	Good	Body liner:	Good
Body sides:	Good	Tail gate adapter:	Good
Rubber pads:	Good	Tail gate:	Good
Body mounts:	Good	Front spill guard:	Good
NOTES:			

Tires

Front Tire Size:	Left: 23.5R25 71%	Right: 23.5R25 - 75%	Rear Tire Size 1:	Left: 23.5R25 80%	Right: 23.5R25 - 77%
Front Tire Brand:	Left: Michelin	Right: Michelin	Rear Tire Brand 1:	Left: Michelin	Right: Michelin
Front Tire Radial or Bias:	Left:	Right:	Rear Tire Radial or Bias:	Left:	Right:
Front Tire Measurement:	Left: 32/32	Right: 34/32	Rear Tire Measurement 1:	Left: 36/32	Right: 35/32
			Rear Tire Size 2:	Left: 23.5R25 71%	Right: 23.5R25 - 75%
			Rear Tire Brand 2:	Left: Michelin	Right: Michelin
			Rear Tire Radial or Bias:	Left:	Right:
			Rear Tire Measurement 2:	Left: 32/32	Right: 34/32
NOTES: Tread Depth Wear Based On 45/32nds New					

2016 Volvo A25G

(Continued)

Serial #: 0243

Comments

Public Comments:

2016 Volvo A25G

(Continued)

Serial #: 0243

Reconditioning

ITEM	QTY	PRICE
1. De-Identify		\$0.00
2. Rear Differential Seal - Collection - Verified OK		\$0.00
3. Repair Ride Along Seat		\$0.00
4. Repair 1 Step - Bent		\$0.00
5. Dealer to Determine if Service is Due- Done		\$0.00
Total		\$0.00

2016 Volvo A25G

(Continued)

Serial #: 0243



2016 Volvo A25G

(Continued)

Serial #: 0243



2016 Volvo A25G

(Continued)

Serial #: 0243



2016 Volvo A25G

(Continued)

Serial #: 0243



2016 Volvo A25G

(Continued)

Serial #: 0243

