

Lessee: George B. Wittmer
Associates
Contract: 502-7612587-003

Unit: 2014 Volvo L110H

UNIT # 10163
Location: Flagler Construction,
Jacksonville FL



VIN	10163
LeaseInspector ID #	10163
Year	2014
Model	Volvo L110H
Location City	Jacksonville
Location State	FL
General Specifications	
New Hours	6531
Old Hours	6529

**Lessee: George B. Wittmer
Associates
Contract: 502-7612587-003**

Unit: 2014 Volvo L110H

**UNIT # 10163
Location: Flagler Construction,
Jacksonville FL**

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes

Overall: Fair

**Lessee: George B. Wittmer
Associates
Contract: 502-7612587-003**

Unit: 2014 Volvo L110H

**UNIT # 10163
Location: Flagler Construction,
Jacksonville FL**

ITEM	QTY PRICE
1. Grille Emblem Missing - Done	\$0.00
2. Sticker Missing Right Side of Hood - Done	\$0.00
3. Cutting Edges Worn - Done	\$0.00
4. Air Cleaner Dirty- Replaced	\$0.00
5. Unable to Rear matris, System Issues- Repaired	\$0.00
6. Left Tail Light Lens Cracked- Replaced	\$0.00
7. Right Front Directional Light Inop- Repaired	\$0.00
8. Both Articulation Stops Damaged- Replaced	\$0.00
9. Rear Planetaries Seep/Buildup on Left Inner Housing Area-Repaired	\$0.00
10. All Wheel Lugs and Rims Corroded- Replaced	\$0.00
11. Right Rear Lugnut Covers Missing- Replaced	\$0.00
12. Tilt Cylinder Line Covering Peeling Off- Replaced	\$0.00
13. Quick Connect Line Mount Brackets Bent- Repaired	\$0.00
14. Quick Coupler Will Not Release Completely- Repaired	\$0.00
15. All Tires Sidewall, Tread Cuts, Cracked 2 Past 50%-Replaced	\$0.00
16. Windshield Wipers Out of Time- Repaired	\$0.00
17. 2 Vent Louvers Damaged- Replaced	\$0.00
18. Radiator Grille Bent, Dented- Replaced	\$0.00
19. Radiator Shroud Damaged- Replaced	\$0.00
20. Engine Enclosure Right Side Cracked, Left Side Scratched- Right Replaced, Left Refinished	\$0.00
21. Both Rear Steps Damaged- Left Replaced, Right Replaced	\$0.00
22. Right Front Mudflap Missing- Replaced	\$0.00
23. Left Rear Mudflap Missing- Replaced	\$0.00
24. Radiator Grille Access Latch Inop- Repaired	\$0.00
25. Clean Machine Inside, Out, Engine, Undercarriage- Done	\$0.00
26. Dealer to Determine is Service is Due- Up to Date	\$0.00
27. Dealer to Verify Tire Cuts are Cosmetic Only- Verified	\$0.00
Total	\$0.00

Lessee: George B. Wittmer
Associates
Contract: 502-7612587-003

Unit: 2014 Volvo L110H



UNIT # 10163
Location: Flagler Construction,
Jacksonville FL



Lessee: George B. Wittmer
Associates
Contract: 502-7612587-003

Unit: 2014 Volvo L110H

UNIT # 10163
Location: Flagler Construction,
Jacksonville FL



Lessee: George B. Wittmer
Associates
Contract: 502-7612587-003

Unit: 2014 Volvo L110H


UNIT # 10163
Location: Flagler Construction,
Jacksonville FL



Lessee: George B. Wittmer
Associates
Contract: 502-7612587-003

Unit: 2014 Volvo L110H


UNIT # 10163
Location: Flagler Construction,
Jacksonville FL



Lessee: George B. Wittmer
Associates
Contract: 502-7612587-003

Unit: 2014 Volvo L110H

UNIT # 10163
Location: Flagler Construction,
Jacksonville FL



**Lessee: George B. Wittmer
Associates
Contract: 502-7612587-003**

Unit: 2014 Volvo L110H

**UNIT # 10163
Location: Flagler Construction,
Jacksonville FL**

