VOLVO - INSPECTION REPORT

Volvo, L90G - Wheel Loaders

Images





















Comment:

Country: US Date: 05/15/2018 Make: Volvo Serial number: 617610 Matris hours: 4730.4 Dealer: Arnold Machinery Company Inspector: Dave Gibson Model: L90G

Engine S/N: 11659929

Location: Las Vegas Year: 2014 Hours: 4704 Trans S/N: 15482

Comment:

General Configuration

[X]Yes EROPS
[]Yes OROPS
[]Yes FOPS
[X]Yes Steering wheel
[]Yes Joystick steering
[X]Yes Air conditioning
[X]Yes Rear camera
[X]Yes Standard boom
[]Yes Reversible fan
[]Yes Artic kit
[]Yes Counter weight handling kit

[] Yes Auto Lube
[] Yes Onboard scale
[] Yes Onboard Weight Sys.
[X] Yes Auto shift
[] Yes Optishift
[X] Yes Boom suspension
[] Yes 3rd function
[] Yes 4th function
[] Yes Fuel Heater
[] Yes Limited slip axel

] Yes Universal attachment plate

[X]Yes Full coverage fenders
[]Yes Strobe Light
[]Yes Auto Lube System
[]Yes Fire Suppression System
[X]Yes Mud Flaps
[X]Yes Recyling arrangement

Yes Forestry arrangement
Yes Long boom
Yes Bucket leveler
Yes Quick coupler

Operators Station

Comment:

Seat and armrest [X] Good

Dash and console [X] Good

Floor Board/Mat [X] Good

Cab glass [X] Good

Mirrors [X] Good

Interior light [X] Good

Switches	[X] Good
Wipers	[X] Good
	[X] Good
Gauges	
Hydraulic controls	[X] Good
Powertrain controls	[X] Good
AC cooling	[X] Good
CAB Interior	[X] Good
	[7] 0000
Operators station condition summary	
Comments	
Comment:	
Outside appearand	<u>ce</u>
Steps	[X] Good
Hand rails	[X] Good
Counterweight /	[X] Good
Bumper	
Grill	[X] Good
Hood	[X] Good
Exhaust stack	[X] Good
Pre-cleaner bowl	[X] Good
Front fenders	[X] Good
Rear fenders	[X] Good
Fuel tank	[X] Good
Front frame & welds	[X] Good
Rear frame & welds	[X] Good
Sheet metal	[X] Good
Paint	[X] Good
Outside appearance condition summary	
Comment:	
Comment.	
Safety condition	
Safety decals in place	
Operators manual	[X]Yes
Safety handles	[X] Good
Seat belt	[X] Good
Horn	[X] Good
Back up alarm	[X] Good
Brake hold	[X] Good
Turn signals	[X] Good
Hazard lights	[X] Good

ROPS Structure	[X] Good
CAB	[X] Good
Safety condition summary	
Comment:	
Electrical condition	1
Computer	[X] Good
ECM'S	[X] Good
Monitor / Display	[X] Good
Wiring harness's	[X] Good
Key switch	[X] Good
Switches Lighting	[X] Good
Engine preheater	[X] Good
Batteries / Connections	
Battery disconnect	[X] Good
switch	
Electrical condition summary	
Comment:	
Engine condition	
Oil level OK	[X]Yes
Water in oil	[X] No
Compression in radiator	[X] No
Blow by	[X] No
Engine knocking	[X] No
CE PLATE	[X]Yes
Oil pressure	[X] Good
Oil leaks	[X] No
EPA DECAL	[X]Yes
Turbo charger	[X] Good
Exhaust manifold	[X] Good
Muffler	[X] Good
Fuel injection system	
	[X] Good

[X] Good

Head

Fan guard	[X] Good
Belts & pulleys	[X] Good
Wiring harness	[X] Good
Starter	[X] Good
Alternator	[X] Good
Seals & gaskets	[X] Good
Engine mounts	[X] Good
Brackets	[X] Good
AC Compressor	[X] Good
Air filters	[X] Good
Engine condition summary	
Comment:	
Cooling system	
Coolant color	Yellow
Radiator	[X] Good
Water pump	[X] Good
Oil cooler	[X] Good
Fan	[X] Good
Fan drive	[X] Good
Hoses	[X] Good
Cooling system summary	
Comment:	
Transmission cond	dition
Oil level OK	[X]Yes
Water in oil	[X]No
Any leaks	[X]No
Torque converter	[X] Good
Case	[X] Good

Pump

[X] Good

Hoses	[X] Good	
Retarder	[] Good [] Fair [] Poor Remarks:	
Shifting forward	[X] Good	
Shifting reverse	[X] Good	
Transmission summar	у	
_		
Comment:		
Axels-Final Drives	-Brakes	
Front differential	[X] Good	
Rear differential	[X] Good	
Differential supports	[X] Good	
Drive shafts	[X] Good	
UV Joints	[X] Good	
Planetaires front	[X] Good	
Planetaires rear	[X] Good	
Hoses / Lines	[X] Good	
Torsion rods	[] Good [] Fair [] Poor Remarks:	
Any leaks	[X]No	
Holds in park	[]Yes []No	
Brakes wet	[X]Yes	
Holds thru all gears	[X]Yes	
Brakes dry	[X]No	
Brake disk / calipers	[] Good [] Fair [] Poor Remarks:	
Brake lines	[X] Good	
Seals	[X] Good	
Parking brake	[X] Good	
Summary		
Comment:		
Steering & articulation condition		
Steering cylinders Pumps	[X] Good [X] Good	
Pumps Valves	[X] Good	
V G1 V C G	[7] 5000	

Valves

Lines / Hoses	[X] Good
Secondary steering	[] Good [] Fair [] Poor Remarks:
Steering pins &	[X] Good
bushings	
Steering wheel tilt &	[X] Good
function	
Articulation pins &	[X] Good
bushings	
Summary	
Comment:	
Hydraulics conditi	ion
i iyaraanoo oorian.	
Boom cylinders	[X] Good
Tilt cylinder	[X] Good
Valves	[X] Good
Hoses	[X] Good
Fittings	[X] Good
Tank Controls	[X] Good [X] Good
Boom kickout and	[X] Good
bucket level	[7] 5000
Operational	[X] Good
Summary	[//] 6664
Comment:	
Bucket & other at	tachments
Bucket type / Size	
Bucket type / Size	Volvo. 102 inch wide.
Coupler type	Volvo
Bucket serial	
Coupler serial	
Bucket W / Teeth	[X] No
Addtl attachments	
Bolt on smooth	[X]Yes
Bolt on edge	[X] Good
Bucket teeth / Segments	[] Good [] Fair [] Poor Remarks:
Bucket sides	[X] Good
Bucket floor	[X] Good
Bucket bottom	[X] Good
Packer porroll	[A] 0000

Coupler	[X] Good
Boom / Frame	[X] Good
Boom / Bucket pins & bushings	[X] Good
Summary	
Comment:	
Tires & rims	
Make	Maxam
Serial	
% Remaining	85%
Make	Maxam
Serial	
% Remaining	85%
Make	Maxam
Serial	
% Remaining	85%
Make	Maxam
Serial	
% Remaining	85%
Make	
Serial	
% Remaining	
Make	
Serial	
% Remaining	
Recapped	[X] No
Tread cuts	[X] No
Side wall cuts	[X] No
Tire size the same	[X] Yes Remarks:
Overall tire condition	[X] Good
Rims	[X] Good
Lug nuts & studs	[X] Good
Comment:	

General Comments

Legend (5 star rating)	[X]5
Paint general	[X] Good
Comment:	