

2017 Volvo L110H

Serial #: 1282

Arnold Machinery
Idaho Falls, ID
208-523-0822

- Air conditioning
- Joystick control
- Radio
- SMU/Hours: 2262
- Overall: Fair
- Auxiliary hydraulics
- Quick Coupler
- Air suspension seat
- Start Run: Yes
- Insp Date: 10/24/2019



General Appearance

GENERAL:			
Radiator Grille:	Good	Fuel Tank:	Good
Radiator Shroud:	Good	Cab Doors:	Good
Engine Enclosure:	Good	Bumper:	Good
Hood:	Good	Differential supports:	Good
Stack:	Good	Counterweight:	Good
Right front fender:	Good	Cab:	Good
Left front fender:	Good	Steps:	Good
Right rear fender:	Good	Grab Irons/Handrails:	Good
Left rear fender:	Good	Paint:	Fair
Main Frame:	Good	Oil Sample Taken:	No
Precleaner bowl:	Good		
NOTES:			

2017 Volvo L110H

(Continued)

Serial #: 1282

Interior Section

SAFETY ITEMS:			
Glass:	Good	Neutral Start Switch:	Good
Mirrors:	Good	Fire Suppression System:	Good
Seat Belt:	Good	Horn:	Good
Back Up Alarm:	Good	Roll Over Protection:	ROPS
Fan Guards:	Good		
NOTES:			
OPERATOR AREA:			
Dash Console:	Good	Seat Cushion:	Good
Meter:	Good	Arm Rests:	Good
Gauges:	Good	Floor Boards/Mats:	Good
Control Pattern Decals:	Good	EMS Panel:	Good
Switches:	Good	Warnings:	Good
Windshield Wipers:	Good	Door Latches:	Good
Heater:	Good	Current Parts Manual:	No
A/C:	Good	Current Safety Manual:	Yes
Interior Lights:	Good	Current O&M Manual:	Yes
NOTES:			

Power Systems

ENGINE:			
Engine Make Model:	Volvo D8J	Oil Pressure:	Normal
Engine S/N:	-	Smoke:	No
Engine Hours:	2262	Smoke Color:	Not Applicable
Oil Leaks:	No	TurboCharger:	Good
Blow-by:	No	Fuel Injection System:	Good
Knocking:	No	Governor:	Good
Compression in Radiator:	No	Engine Supports:	Good
Water in Oil:	No	Air Cleaners:	Poor
Fluid Level OK?:	No	+Last Scheduled Oil Sample:	-
Anit-Freeze Color:	Orange	-	
+Last Preventive Maintenance:		-	
NOTES:			
COOLING SYSTEM:			
Radiator:	Good	Fan:	Good
Coolers:	Good	Fan Drive:	Good
Hoses:	Good	Belts:	Good
Water Pump:	Good	Pulleys:	Good
NOTES:			
ELECTRICAL SYSTEM:			
Batteries:	Good	Wiring:	Good
Battery Cables:	Good	Pre-Heater:	Good
Starter:	Good	Lighting:	Good
Alternator:	Good		
NOTES:			

Power Systems - Continued

TRANSMISSION:			
Serial #:	HTE206C	Controls:	Good
Type:	Power Shift	Seals:	Good
Speeds:	Excellent	Torque Converter:	Good
Transmission Forward:	Good	Temp/Pressure Gauges:	Good
Transmission Reverse:	Good	Is the Transmission Noisy?:	No
Case:	Good		
NOTES:			
STEERING:			
Front axle:	Good	Articulation P & B:	Good
Steering Linkage:	Good	Steering cylinder:	Good
Steering Valve:	Good	Tie rods/ rod ends:	Good
Steering Pump:	Good		
NOTES:			
BRAKE:			
Mechanism:	Wet	Lines:	Good
Brake Type:	Pedal	Compressor:	Good
Performance:	Good	Brake linkage:	Good
Brake drums:	Good	Master cylinder:	Good
Rotors:	Good	Parking brake:	Good
Control Valve:	Good		
NOTES:			
FINAL DRIVE:			
Front Planataries:	Good	Rear Wheel lugs & rims:	Good
Front Differential:	Good	Front Axle bolts:	Good
Rear Planataries:	Good	Rear Axle bolts:	Good
Rear Differential:	Good	Front axle housings:	Good
Front Wheel lugs & rims:	Good	Rear axle housings:	Good
NOTES:			

2017 Volvo L110H

(Continued)

Serial #: 1282

Hydraulics

HYDRAULICS:			
Right lift cylinder:	Good	Pumps:	Good
Left lift cylinder:	Good	Valves:	Good
Bucket cylinder:	Good	Control linkage:	Good
Hose lines:	Good	Bucket & hoist kickout:	Good
NOTES:			

2017 Volvo L110H

(Continued)

Serial #: 1282

Front Bucket

FRONT BUCKET:			
Bucket Type:	General Purpose	Bucket adapters:	Good
Width:	118"	Bucket teeth:	Good
Capacity:	4.3yd	Arms & cranks:	Good
Bucket bottom:	Good	Loader frame:	Good
Bucket sides:	Good	Loader P & B:	Good
Bucket linkage:	Good	Quick coupler:	Good
Bucket mounts:	Good		
NOTES:			

2017 Volvo L110H

(Continued)

Serial #: 1282

Tires

TIRES:					
Front Tire Size:	Left: 23.5R25 37%	Right: 23.5R25 - 40%	Rear Tire Size:	Left: 23.5R25 46%	Right: 23.5R25 - 46%
Front Tire Brand:	Left: Brawler	Right: Bridgestone	Rear Tire Brand:	Left: Bridgestone	Right: Bridgestone
Front Tire Measurement:	Left: 17/32	Right: 18/32	Rear Tire Measurement:	Left: 21/32	Right: 21/32
NOTES: Tread Depth Wear Based On 45/32nds New					

2017 Volvo L110H

(Continued)

Serial #: 1282

Comments

COMMENTS:
Creditor Comments:
Public Comments:

2017 Volvo L110H

(Continued)

Serial #: 1282

Deficiency Review

DEFICIENCY REVIEW:			
	ITEM	QTY	PRICE
2.	+ Air Cleaner Dirty		\$0.00
3.	+ Tires Cut/Gouged/All Past 50%		\$0.00
5.	+ Front Mudflaps Torn		\$0.00
6.	+ CB Antenna Held on With Vice Grips		\$0.00
7.	+ Clean Machine		\$0.00
8.	clean machine inside out engine undercarriage		\$0.00
9.	dealer to determine if service is due		\$0.00
10.	dealer to verify tire cuts are cosmetic only		\$0.00
Total			\$0.00

2017 Volvo L110H

(Continued)


Serial #: 1282



2017 Volvo L110H

(Continued)

Serial #: 1282



2017 Volvo L110H

(Continued)

Serial #: 1282



2017 Volvo L110H

(Continued)

Serial #: 1282







2017 Volvo L110H

(Continued)



Serial #: 1282



2017 Volvo L110H

(Continued)

Serial #: 1282



2017 Volvo L110H

(Continued)

Serial #: 1282



UNA, SWEDEN	No	
er	No	
	No	
n		
ity	kg/lb	/
year/month	m ² /ft ²	/
sure	MPa/psi	/

VOLVO

16293707

2017 Volvo L110H

(Continued)

Serial #: 1282

Volvo Construction Equipment			
SE-631 85 ESKILSTUNA, SWEDEN			
MODEL	No	86307	
SUPPLIER	No	85007	
SERIAL	No	SHP 1068	
MADE IN		CANADA	
MANUFACTURING YEAR		2017	
ADAPTER	KIT No		
POINT	KIT No		
SEGMENT	KIT No		
BOLT ON EDGE	KIT No	80577	
CUTTING EDGE	PART No	11156764	
WEIGHT, wear parts excl.	kg/lb	1365 / 3003	
CAPACITY, wear parts excl.	m ³ /yd ³	3.3 / 4.32	
MAX WORKING PRESSURE	MPa/psi	/	



2017 Volvo L110H

(Continued)

Serial #: 1282



2017 Volvo L110H

(Continued)

Serial #: 1282

