Lessee: Downrite Engineering Corp
Contract: 502-7551850-010
Unit: 2016 Volvo L60H
Location: Flagler Construction
Equipment, Davie FL



VIN 621283 621283 LeaseInspector ID # 2016 Year Model Volvo L60H Location City Davie Location State FL **General Specifications** New Hours 3890 Old Hours 3888

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes Overall: Fair

ITEM	QTY PRICE
1. Clean Machine Inside, Out, Engine, Undercarriage- Done	\$0.00
2. Deidentify- Repaired	\$0.00
3. Counterweight Pin Missing- Replaced	\$0.00
4. Dealer to Determine if Service is Due- Serviced	\$0.00
5. Dealer to Verify Tire Cuts are Cosmetic Only- Replaced	\$0.00
6. Left Steering Cylinder Collection- Not Repaired	\$0.00
7. Right Steering Cylinder Collection- Not Repaired	\$0.00
8. Fluid Seep at Access Panel for Bucket Quick Connect- Repaired	\$0.00
9. Aux Hoses Cut to Braids- Repaired	\$0.00
10. Left Bucket Quick Connect Hose Cut to Braids- Replaced	\$0.00
11. Tires Cut- Not Replaced	\$0.00
Total	\$0.00





















