2017 Volvo A40G

Atlantic Waste Landfill Waverly, VA 301-395-0291

- Rear vision system
- Air ride seat
- Air conditioning
- Rotating beacon
- Body exhaust heating kit
- Engine jake brake
- SMU/Hours: 2316
- Overall: Fair

- Radio
- Differential locks
- Computer display

Serial #: 341641

- Mudflaps
- Tailgate

Start Run: Yes

Insp Date: 6/5/2019









General Appearance

GENER	AL:			
Radiator G	Grille:	Good	Precleaner bowl:	Good
Radiator Shroud: Good		Fuel Tank:	Good	
Engine Enclosure: Good		Good	Cab Doors:	Good
Hood:		Good	Bumper:	Good
Stack:		Good	Cab:	Good
Right fron	t fender:	Good	Steps:	Good
Left front f	fender:	Good	Grab Irons/Handrails:	Good
Rear frame	e:	Good	Paint:	Good
Front frame:		Good	Oil Sample Taken:	No
LEGEND O	F CONDITION	IS:	<u> </u>	
Excellent -	New conditi	on. No Repairs Necessary.	Poor - Obvious necessar	wear and/or damage. Repairs y.
Good -	Good - No apparent wear or damage, Functions/Operates correctly. No Repairs Necessary.		Not Applicable - Does not	apply to this unit
Fair - Wear and/or damage apparent. Functions, but not correctly. Repairs recommended.				
NOTES:				

Interior Section

Glass:	Good	Neutral Start Switch:	Good
Mirrors:	Good	Fire Suppression System:	Not Available
Seat Belt:	Good	Horn:	Good
Back Up Alarm:	Good		
Fan Guards:	Good		
NOTES:		•	
OPERATOR AREA:			
Dash Console:	Good	Seat Cushion:	Good
Meter:	Good	Arm Rests:	Good
Gauges:	Good	Floor Boards/Mats:	Good
Control Pattern Decals:	Good	EMS Panel:	Good
Switches:	Good	Warnings:	Good
Windshield Wipers:	Good	Door Latches:	Good
Heater:	Good	Current Parts Manual:	No
A/C:	Good	Current Safety Manual:	No
	Good	Current O&M Manual:	Yes

Power Systems

ENGINE:			
Engine Make Model:	Volvo D16J	Oil Pressure:	Normal
Engine S/N:	100849	Smoke:	No
Engine Hours:	2316	Smoke Color:	Not Applicable
Oil Leaks:	No	TurboCharger:	Good
Blow-by:	No	Fuel Injection System:	Good
Knocking:	No	Governor:	Good
Compression in Radiator:	No	Engine Supports:	Good
Water in Oil:	No	Air Cleaners:	Poor
Fluid Level OK?:	Yes		
Anit-Freeze Color:	Yellow		
NOTES:			
COOLING SYSTEM:			
Radiator:	Fair	Fan:	Good
Coolers:	Fair	Fan Drive:	Good
Hoses:	Good	Belts:	Good
Water Pump:	Good	Pulleys:	Good
NOTES:			
ELECTRICAL SYSTEM:			
Batteries:	Poor	Wiring:	Good
Battery Cables:	Good	Pre-Heater:	Good
Starter:	Good	Lighting:	Fair
Alternator:	Good		
NOTES:			

Power Systems - Continued

TRANSMISSION:			
Transmission Serial #:	-	Seals:	Good
Transmission Type:	Auto	Torque Converter:	Good
Transmission Speeds:	9	Temp/Pressure Gauges:	Good
Transmission Forward:	Good	Transmission Fluid:	Good
Transmission Reverse:	Good	Is the Transmission Noisy?:	No
Case:	Good	Transmission Retarder:	Yes
Controls:	Good		
NOTES:			
OTEEDING.			
STEERING:			
Steering Linkage:	Good	Left steering cylinder:	Good
Steering Valve:	Good	Right steering cylinder:	Good
Steering Pump:	Good	Steering joints:	Good
Articulation P & B:	Good		
NOTES:			
BRAKE:			
Mechanism:	Wet	Lines:	Good
Type:	Pedal	Compressor:	Good
Perfomance:	Good	Brake linkage:	Good
Brake drums:	Good	Master cylinder:	Good
Rotors:	Good	Parking brake:	Good
Control Valve:	Good		
NOTES:			
DRIVE TRAIN:			
Front axle:	Good	Rear axle housing:	Good
Front differential:	Good	U-Joints:	Good
Rear axles:	Good	Front suspension:	Good
Rear differentials:	Good	Rear suspension:	Good
Front wheel lugs & rims:	Good	Front a-stay:	Good
Rear wheel lugs & rims:	Good	Rear a-stay:	Good
Front axle bolts:	Good		
Rear axle bolts:	Good		
Front axle housing:	Good		
NOTES:			

(Continued)

Serial #: 341641

Hydraulics

HYDRAULICS:				
Right dump cylinder:	Good	Valves:	Good	
Left dump cylinder:	Good	Control linkage:	Good	
Hose lines:	Good	Reservoir:	Good	
Pumps:	Good	Dump cycle test:	Good	
NOTES:		•		

Dump Body

Body type:	Bulk	Body pins and bushings:	Good
Body bottom:	Good	Body liner:	Not Available
Body sides:	Good	Tail gate adapter:	Good
Rubber pads:	Good	Tail gate:	Good
Body mounts:	Good	Front spill guard:	Good

Tires

TIRES:									
Front Tire Size:	Left: 29.5R25 81%	- Right: 29.5R25 - 78%	Rear	Tire	Size 1:		Left: 29.5R25 80%	- Right: 2 - 92%	9.5R25
Front Tire Brand: Left:	Bridgestone Ri g	ght: Bridgestone	Rear	Tire	Brand 1:	Left:	Bridgestone Ri g	ght: Bridg	jestone
Front Tire Radial or Bias:	Left: Radial	Right: Radial	Rear	Tire	Radial or Bias	:	Left: Radial	Right: R	Radial
Front Tire Measurement:	Left: 45/32	Right: 43/32	Rear	Tire	Measurement	1:	Left: 44/32	Right: 5	1/32
			Rear	Tire	Size 2:		Left: 29.5R25 92%	-Right: 29 - 70%	9.5R25
			Rear	Tire	Brand 2:	L	.eft: MichelinRi	ght: Bridg	jestone
			Rear	Tire	Radial or Bias	:	Left: Radial	Right: R	Radial
			Rear	Tire	Measurement	2:	Left: 51/32	Right: 3	9/32
NOTES: Tread Depth Wear Based O	n 55/32nds New	ı							

Comments

COMMENTS:						
Public Comments:						

Reconditioning

	DEFICIENCY REVIEW:						
	ITEM	QTY PRICE					
1.	+ Clean Machine	\$0.00					
2.	+ Body Exhaust Kit Disconnected- Waiting on Parts	\$0.00					
3.	+ Right Front, Left Front, Left Rear Front, Right Rear Rear Tires Sidewall Cuts	\$0.00					
4.	+ Right Rear Front Tire Tread Repair Coming Off	\$0.00					
5.	+ Batteries Dead	\$0.00					
6.	+ Coolers Leaking- Dirt Collecting	\$0.00					
7.	+ Radiator Dirty	\$0.00					
8.	+ Air Cleaner Dirty	\$0.00					
T	otal	\$0.00					









