

**Lessee: Superior Construction
Company
Contract: 502-7674819-011**

Unit: 2015 Volvo A40G

**UNIT # 0781
Location: Flagler Construction,
Jacksonville FL**



SPECIFICATIONS

VIN	0781
LeaseInspector ID #	0781
Year	2015
Model	Volvo A40G
Location City	Jacksonville
Location State	FL
General Specifications	
New Hours	4809
Old Hours	4803

**Lessee: Superior Construction
Company
Contract: 502-7674819-011**

Unit: 2015 Volvo A40G

**UNIT # 0781
Location: Flagler Construction,
Jacksonville FL**

**ADDITIONAL FEATURES OF THIS
VEHICLE
COMMENTS**

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes

Overall: Fair

**Lessee: Superior Construction
Company
Contract: 502-7674819-011**

Unit: 2015 Volvo A40G

**UNIT # 0781
Location: Flagler Construction,
Jacksonville FL**


DEFICIENCY REVIEW

ITEM	QTY	PRICE
1. Belly Pan Dented		\$0.00
2. Engine Oil Leak Harness Plug		\$0.00
3. Engine Oil leak Left Side of Engine		\$0.00
4. Right Front Mudflap Torn- Replaced		\$0.00
5. Hoom Emblem and Chrome Trim Missing- Replaced		\$0.00
6. Clean Machine- Not Repaired		\$0.00
7. Hydraulic Oil Level Low- Repaired		\$0.00
8. Clean Machine Inside, Out, Engine, Undercarriage- Not Repaired		\$0.00
9. Service Machine - Up to Date		\$0.00
10. Dealer to Verify Tire Cuts are Cosmetic Only- Verified		\$0.00
11. Tires Cut- Verified		\$0.00
Total		\$0.00

Lessee: Superior Construction
Company
Contract: 502-7674819-011

Unit: 2015 Volvo A40G

UNIT # 0781
Location: Flagler Construction,
Jacksonville FL



**Lessee: Superior Construction
Company
Contract: 502-7674819-011**

Unit: 2015 Volvo A40G

**UNIT # 0781
Location: Flagler Construction,
Jacksonville FL**

