Serial #: 342083

Outside PCS Phosphate Mine Aurora, NC 336-420-7221

- Rear vision system
- Air ride seat
- Air conditioning
- Rotating beacon
- Tailgate
- SMU/Hours: 6439
- Overall: Fair

- Radio
- Differential locks
- Computer display
- Mudflaps
- Engine jake brake
- Start Run: Yes
- Insp Date: 8/15/2019



(Continued)

General Appearance

Radiator G	rille:	Good	Precleaner bowl:	Good
Radiator SI	nroud:	Good	Fuel Tank:	Good
Engine End	losure:	Good	Cab Doors:	Good
Hood:		Fair	Bumper:	Fair
Stack:		Good	Cab:	Good
Right front	fender:	Good	Steps:	Good
Left front fe	ender:	Good	Grab Irons/Handrails:	Good
Rear frame	:	Good	Paint:	Fair
Front frame	e:	Good	Oil Sample Taken:	No
LEGEND OF	CONDITIONS:		'	
Excellent -	New condition.	No Repairs Necessary.	Poor - Obvious necessa	s wear and/or damage. Repairs ary.
Good -		ear or damage, Functions/Opera epairs Necessary.	ites Not Applicable - Does no	ot apply to this unit
Fair -		amage apparent. Functions, but lepairs recommended.		

(Continued)

Interior Section

Glass:	Fair	Neutral Start Switch:	Good	
Mirrors:	Good	Fire Suppression System:	Good	
Seat Belt:	Good	Horn:	Good	
Back Up Alarm:	Good			
Fan Guards:	Good			
NOTES:		,		
OPERATOR AREA:				
Dash Console:	Good	Seat Cushion:	Good	
Meter:	Good	Arm Rests:	Good	
Gauges:	Good	Floor Boards/Mats:	Good	
Control Pattern Decals:	Good	EMS Panel:	Good	
Switches:	Good	Warnings:	Good	
Windshield Wipers:	Good	Door Latches:	Good	
Heater:	Good	Current Parts Manual:	Yes	
A/C:	Good	Current Safety Manual:	Yes	
Interior Lights:	Fair	Current O&M Manual:	Yes	

(Continued)

Power Systems

Engine Make Model:	Volvo D13J	Oil Pressure:	Normal	
Engine S/N:	696253	Smoke:	No	
Engine Hours:	6439	Smoke Color:	Light	
Oil Leaks:	No	TurboCharger:	Good	
Blow-by:	No	Fuel Injection System:	Good	
Knocking:	No	Governor:	Good	
Compression in Radiator:	No	Engine Supports:	Good	
Water in Oil:	No	Air Cleaners:	Good	
Fluid Level OK?:	Yes			
Anit-Freeze Color:	Red			
NOTES:				
COOLING SYSTEM:				
Radiator:	Good	Fan:	Good	
Coolers:	Good	Fan Drive:	Good	
Hoses:	Good	Belts:	Good	
Water Pump:	Good	Pulleys:	Good	
NOTES:		,		
ELECTRICAL SYSTEM:				
Batteries:	Good	Wiring:	Good	
Battery Cables:	Good	Pre-Heater:	Good	
	Good	Lighting:	Good	
Starter:				

2017 Volvo A40G (Continued)

Power Systems - Continued

Transmission Serial #:	-	Seals:	Good	
Transmission Type:	Auto	Torque Converter:	Good	
Transmission Speeds:	9	Temp/Pressure Gauges:	Good	
Transmission Forward:	Good	Transmission Fluid:	Good	
Transmission Reverse:	Good	Is the Transmission Noisy?:	No	
Case:	Good	Transmission Retarder:	Yes	
Controls:	Good			
NOTES:		·		
STEERING:				
Steering Linkage:	Good	Left steering cylinder:	Good	
Steering Valve:	Good	Right steering cylinder:	Good	
Steering Pump:	Good	Steering joints:	Good	
Articulation P & B:	Good			
NOTES:				
BRAKE:				
Mechanism:	Wet	Lines:	Good	
Type:	Pedal	Compressor:	Good	
Perfomance:	Good	Brake linkage:	Good	
Brake drums:	Not Available	Master cylinder:	Good	
Rotors:	Good	Parking brake:	Good	
Control Valve:	Good			
NOTES:				
DRIVE TRAIN:				
Front axle:	Good	Rear axle housing:	Good	
Front differential:	Good	U-Joints:	Good	
Rear axles:	Good	Front suspension:	Good	
Rear differentials:	Good	Rear suspension:	Good	
Front wheel lugs & rims:	Good	Front a-stay:	Good	
Rear wheel lugs & rims:	Good	Rear a-stay:	Good	
Front axle bolts:	Good			
Rear axle bolts:	Good			
Front axle housing:	Good			

(Continued)

Hydraulics

Right dump cylinder:	Good	Valves:	Good	
Left dump cylinder:	Good	Control linkage:	Good	
Hose lines:	Good	Reservoir:	Good	
Pumps:	Good	Dump cycle test:	Good	

(Continued)

Dump Body

Body type:	Dump	Body pins and bushings:	Good	
Body bottom:	Good	Body liner:	Not Available	
Body sides:	Fair	Tail gate adapter:	Good	
Rubber pads:	Good	Tail gate:	Fair	
Body mounts:	Good	Front spill guard:	Fair	

(Continued)

Tires

TIRES:					
Front Tire Size:	Left: 29.5R25 - 78%	Right: 29.5R25 - 76%	Rear Tire Size 1:	Left: 29.5R25 - 81%	Right: 29.5R25 - 83%
Front Tire Brand:	Left: Michelin	Right: Michelin	Rear Tire Brand 1:	Left: Michelin	Right: Michelin
Front Tire Radial or Bias:	Left: Radial	Right: Radial	Rear Tire Radial or Bias:	Left: Radial	Right: Radial
Front Tire Measurement:	Left: 43/32	Right: 42/32	Rear Tire Measurement 1:	Left: 45/32	Right: 46/32
			Rear Tire Size 2:	Left: 29.5R25 - 80%	Right: 29.5R25 - 76%
			Rear Tire Brand 2:	Left: Michelin	Right: Michelin
			Rear Tire Radial or Bias:	Left: Radial	Right: Radial
			Rear Tire Measurement 2:	Left: 44/32	Right: 42/32
NOTES: Tread Depth Wear Based Or	n 55/32nds New				

(Continued)

Comments

COMMENTS:		
Public Comments:		

(Continued)

Reconditioning

DE	DEFICIENCY REVIEW:				
	ITEM	QTY PRICE			
1.	+ Coolant Low	\$0.00			
2.	+ Rear Main Seal Seep	\$0.00			
3.	+ Both Top Rails Bent, Dented	\$0.00			
7.	+ 1 Light Switch Broken	\$0.00			
8.	+ Left Side Hood Latch Missing	\$0.00			
11.	+ Deidentify	\$0.00			
12.	+ Clean Machine Inside, Out, Engine and Undercarraig	\$0.00			
13.	+ Hyd Oil Low	\$0.00			
14.	dealer to determine if service is due	\$0.00			
To	tal	\$0.00			

(Continued)




11/20/2019

(Continued)

VOLVO

(Continued)



(Continued)



(Continued)

