2018 Volvo A45G

McClung-Logan Glen Allen, VA 804-266-0000

- Rear vision system
- Air ride seat
- Air conditioning
- Rotating beacon
- Body exhaust heating kit

• SMU/Hours: 1189

• Overall: Fair

- Radio
- Differential locks
- Computer display

Serial #: 342400

- Mudflaps
- Tailgate

Start Run: Yes

• Insp Date: 3/11/2020









General Appearance

Radiator 0	Grille:	Good	Precleaner bowl:	Good
Radiator S	Shroud:	Good	Fuel Tank:	Good
Engine En	closure:	Good	Cab Doors:	Good
Hood:		Good	Bumper:	Not Available
Stack:		Good	Cab:	Good
Right fron	t fender:	Good	Steps:	Fair
Left front	fender:	Good	Grab Irons/Handrails:	Good
Rear frame	e:	Good	Paint:	Fair
Front frame:		Good	Oil Sample Taken:	No
LEGEND C	F CONDITIO	NS:	•	
Excellent -	- New conditi	on. No Repairs Necessary.	Poor - Obvious necessa	s wear and/or damage. Repairs ary.
Good -	No apparent wear or damage, Functions/Operates correctly. No Repairs Necessary.		Not Applicable - Does no	ot apply to this unit
Fair - Wear and/or damage apparent. Functions, but not correctly. Repairs recommended.				

Interior Section

Glass:	Good	Neutral Start Switch:	Good
Mirrors:	Good	Fire Suppression System:	Not Available
Seat Belt:	Good	Horn:	Good
Back Up Alarm:	Good		
Fan Guards:	Not Available		
NOTES:			
Dash Console:	Good	Seat Cushion:	Good
Meter:	Good	Arm Rests:	Good
Gauges:	Good	Floor Boards/Mats:	Good
	Good	EMS Panel:	Good
Control Pattern Decals:			
Control Pattern Decals: Switches:	Good	Warnings:	Good
	Good Good	Warnings: Door Latches:	Good Good
Switches:		_	
Switches: Windshield Wipers:	Good	Door Latches:	Good

Power Systems

Engine Make Model:	Volvo D16J	Oil Pressure:	Normal
Engine S/N:	111132	Smoke:	No
Engine Hours:	1189	Smoke Color:	Not Applicable
Oil Leaks:	No	TurboCharger:	Good
Blow-by:	No	Fuel Injection System:	Good
Knocking:	No	Governor:	Good
Compression in Radiator:	No	Engine Supports:	Good
Water in Oil:	No	Air Cleaners:	Good
Fluid Level OK?:	Yes		
Anit-Freeze Color:	Yellow		
Radiator:	Good	Fan:	Good
Radiator: Coolers:	Good Good	Fan: Fan Drive:	Good Good
Coolers:	Good	Fan Drive:	Good
Coolers: Hoses:	Good Good	Fan Drive: Belts:	Good Good
Coolers: Hoses: Water Pump: NOTES:	Good Good Good	Fan Drive: Belts: Pulleys:	Good Good Good
Coolers: Hoses: Water Pump: NOTES: Batteries:	Good Good Good	Fan Drive: Belts: Pulleys: Wiring:	Good Good Good
Coolers: Hoses: Water Pump: NOTES: Batteries: Battery Cables:	Good Good Good Good	Fan Drive: Belts: Pulleys: Wiring: Pre-Heater:	Good Good Good Good
Coolers: Hoses: Water Pump: NOTES: Batteries:	Good Good Good	Fan Drive: Belts: Pulleys: Wiring:	Good Good Good

Power Systems - Continued

Transmission Serial #:	-	Seals:	Good	
Transmission Type:	Auto	Torque Converter:	Good	
Transmission Speeds:	9 F 3 R	Temp/Pressure Gauges:	Good	
Transmission Forward:	Good	Transmission Fluid:	Good	
Transmission Reverse:	Good	Is the Transmission Noisy?:	No	
Case:	Good	Transmission Retarder:	Yes	
Controls:	Good			
NOTES:		•		
Stooring Linkage	Good	Loft atacking audindon	Good	
Steering Linkage:	Good	Left steering cylinder: Right steering cylinder:	Good	
Steering Valve:	Good		Good	
Steering Pump: Articulation P & B:	~	Steering joints:	Good	
	Good			
NOTES:				
Mechanism:	Wet	Lines:	Good	
Туре:	Pedal	Compressor:	Good	
Perfomance:	Good	Brake linkage:	Good	
Brake drums:	Not Available	Master cylinder:	Not Available	
Rotors:	Not Available	Parking brake:	Good	
Control Valve:	Good			
NOTES:		-		
Front axle:	Good	Rear axle housing:	Good	
Front differential:	Good	U-Joints:	Good	
Rear axles:	Good	Front suspension:	Good	
Rear differentials:	Good	Rear suspension:	Fair	
Front wheel lugs & rims:	Good	Front a-stay:	Good	
Rear wheel lugs & rims:	Good	Rear a-stay:	Good	
Front axle bolts:	Good			
Rear axle bolts:	Good			
Front axle housing:	Good			
NOTES:		•		

2018 Volvo A45G (Continued)

Serial #: 342400

Hydraulics

Right dump cylinder:	Good	Valves:	Good	
•				
Left dump cylinder:	Good	Control linkage:	Good	
Hose lines:	Good	Reservoir:	Good	
Pumps:	Good	Dump cycle test:	Good	
NOTES:		*		

Dump Body

Body type:	=	Body pins and bushings:	Good
Body bottom:	Good	Body liner:	Not Available
Body sides:	Good	Tail gate adapter:	Good
Rubber pads:	Good	Tail gate:	Fair
Body mounts:	Good	Front spill guard:	Good

Tires

Front Tire Size:	Left: 29.5R25 96%	- Right: 29.5R25 - 87%	Rear	Tire	Size 1:	Left: 29.5R25 96%	- Right: 29.5R25 - 100%
Front Tire Brand: Left	: Bridgestone Ri	ght: Bridgestone	Rear	Tire	Brand 1: Le	ft: BridgestoneRi	ght: Bridgestone
Front Tire Radial or Bias:	Left: Radial	Right: Radial	Rear	Tire	Radial or Bias:	Left: Radial	Right: Radial
Front Tire Measurement:	Left: 53/32	Right: 48/32	Rear	Tire	Measurement 1:	Left: 53/32	Right: 55/32
			Rear	Tire	Size 2:	Left: 29.5R25 94%	- Right: 29.5R25 - 96%
			Rear	Tire	Brand 2: Le	ft: BridgestoneRi	ght: Bridgestone
			Rear	Tire	Radial or Bias:	Left: Radial	Right: Radial
			Rear	Tire	Measurement 2:	Left: 52/32	Right: 53/32
NOTES:			·				
Tread Depth Wear Based O	n 55/32nds New	1					

Comments

Public Comments:		

Reconditioning

ITEM	QTY PRICE
1. + Rear Suspension Right Boggie Bearings Loose, Frame Scraped	\$0.00
2. + Tail Gate Dented	\$0.00
3. + Tires Cut, Scraped	\$0.00
4. + Left Front Tire has Nail	\$0.00
5. + Left Step Bent	\$0.00
6. + Left Front Fender Scratched	\$0.00
7. + Deidentify	\$0.00
Total	\$0.00











