

**Lessee: Ripa & Associates
Contract: 502-5040598-013**

Unit: 2015 Volvo A40G

**UNIT # 1218
Location: Flagler Construction
Equipment, Fort Myers FL**



SPECIFICATIONS

VIN	1218
LeaseInspector ID #	1218
Year	2015
Model	Volvo A40G
Location City	Fort Myers
Location State	FL
General Specifications	
New Hours	4593
Old Hours	4591

Lessee: Ripa & Associates
Contract: 502-5040598-013

Unit: 2015 Volvo A40G

UNIT # 1218
Location: Flagler Construction
Equipment, Fort Myers FL

**ADDITIONAL FEATURES OF THIS
VEHICLE
COMMENTS**

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes

Overall: Fair

Lessee: Ripa & Associates
Contract: 502-5040598-013

Unit: 2015 Volvo A40G

UNIT # 1218
Location: Flagler Construction
Equipment, Fort Myers FL


DEFICIENCY REVIEW

ITEM	QTY	PRICE
1. Coolant Leak Behind Coolant Reservoir - Repaired		\$0.00
2. Clean Machine Inside, Out, Engine, Undercarriage- Done		\$0.00
3. Dealer to Verify All Tire Cuts are Cosmetic Only- Verified		\$0.00
4. Ashtray Front Missing- Replaced		\$0.00
5. Cigarette Lighter Missing- Replaced		\$0.00
6. Collection Around Hood Opening Hydraulic System- Repaired		\$0.00
7. Engine Oil Seep Driver Side of Engine- Repaired		\$0.00
8. Engine Oil Seep Driver Side Harness Connector- Repaired		\$0.00
9. Brake Fluid Tank Level Low- Repaired		\$0.00
10. Rear Tires cut- Verified		\$0.00
11. Backup Alarm Inoo- Repaired		\$0.00
Total		\$0.00

Lessee: Ripa & Associates
Contract: 502-5040598-013

Unit: 2015 Volvo A40G



UNIT # 1218
Location: Flagler Construction
Equipment, Fort Myers FL



Lessee: Ripa & Associates
Contract: 502-5040598-013

Unit: 2015 Volvo A40G

UNIT # 1218
Location: Flagler Construction
Equipment, Fort Myers FL



Lessee: Ripa & Associates
Contract: 502-5040598-013

Unit: 2015 Volvo A40G

UNIT # 1218
Location: Flagler Construction
Equipment, Fort Myers FL

