

**Lessee: Cash Sand & Gravel  
Contract: 502-7577891-001**

**Unit: 2015 Volvo L120H**

**UNIT # 2016  
Location: Scott Equipment, Baton  
Rouge LA**



**SPECIFICATIONS**

VIN	2016
LeaseInspector ID #	2016
Year	2015
Model	Volvo L120H
Location City	Baton Rouge
Location State	LA
<b>General Specifications</b>	
New Hours	3082
Old Hours	3081

**Lessee: Cash Sand & Gravel**  
**Contract: 502-7577891-001**

**Unit: 2015 Volvo L120H**

**UNIT # 2016**  
**Location: Scott Equipment, Baton Rouge LA**

**ADDITIONAL FEATURES OF THIS VEHICLE**  
**COMMENTS**

**Appraiser Comments:**

**Creditor Comments:**

**Public Comments:**

**Starts/Runs:** Yes

**Overall:** Fair

**Lessee: Cash Sand & Gravel**  
**Contract: 502-7577891-001**

**Unit: 2015 Volvo L120H**

**UNIT # 2016**  
**Location: Scott Equipment, Baton**  
**Rouge LA**

### DEFICIENCY REVIEW

<b>ITEM</b>	<b>QTY</b>	<b>PRICE</b>
1. Clean Machine- Done		\$0.00
2. Dealer to Determine if Machine Service is Due- Done		\$0.00
3. Clean Unit Inside, Out, Engine, Undercarriage- Done		\$0.00
4. Left Center Step Hanger Bent- Repaired		\$0.00
5. Left and Right Lower Grab Bars Bent- Not Repaired		\$0.00
6. Bucket Cutting Edge Worn- Repaired		\$0.00
7. Batteries Dead- Not Repaired		\$0.00
8. Cab Front Top and Front Lower Lights Inop- Repaired		\$0.00
<b>Total</b>		<b>\$0.00</b>

Lessee: Cash Sand & Gravel  
Contract: 502-7577891-001

Unit: 2015 Volvo L120H

UNIT # 2016  
Location: Scott Equipment, Baton  
Rouge LA





Lessee: Cash Sand & Gravel  
Contract: 502-7577891-001

Unit: 2015 Volvo L120H

UNIT # 2016  
Location: Scott Equipment, Baton  
Rouge LA






Lessee: Cash Sand & Gravel  
Contract: 502-7577891-001

Unit: 2015 Volvo L120H

UNIT # 2016  
Location: Scott Equipment, Baton  
Rouge LA



**Lessee: Cash Sand & Gravel  
Contract: 502-7577891-001**

**Unit: 2015 Volvo L120H**

**UNIT # 2016  
Location: Scott Equipment, Baton  
Rouge LA**

