

**Lessee: Junction City Mining  
Contract: 502-7625241-010**

**Unit: 2017 Volvo A40**

**UNIT # 342113  
Location: ASC Construction  
Equipment, Buford GA**



**SPECIFICATIONS**

VIN	342113
LeaseInspector ID #	342113
Year	2017
Model	Volvo A40
Location City	Buford
Location State	GA
<b>General Specifications</b>	
New Hours	5002
Old Hours	5001

**Lessee: Junction City Mining**  
**Contract: 502-7625241-010**

**Unit: 2017 Volvo A40**

**UNIT # 342113**  
**Location: ASC Construction**  
**Equipment, Buford GA**

**ADDITIONAL FEATURES OF THIS VEHICLE**  
**COMMENTS**

**Appraiser Comments:**

**Creditor Comments:**

**Public Comments:**

**Starts/Runs:** Yes

**Overall:** Fair

**Lessee: Junction City Mining**  
**Contract: 502-7625241-010**

**Unit: 2017 Volvo A40**

**UNIT # 342113**  
**Location: ASC Construction**  
**Equipment, Buford GA**

### DEFICIENCY REVIEW

<b>ITEM</b>	<b>QTY PRICE</b>
1. Clean Machine- Done	\$0.00
2. Dealer to Determine is Service is Due- Serviced	\$0.00
3. Remove Welded Bracket from Bumper- Removed	\$0.00
4. Right Front Mudflap Damaged- Replaced	\$0.00
5. Right Front Bumepr has Step Welded On- Removed	\$0.00
6. Coolant Level Low- Repaired	\$0.00
7. Air Cleaner Dirty- Replaced	\$0.00
8. Batteries Jump Started- Did Not Start After Inspection- Replaced	\$0.00
9. Door Glass Damaged- Replaced	\$0.00
10. AC Warm- Repaired	\$0.00
11. Left Side Engine Enclosure Damaged- Replaced	\$0.00
12. Steps by Door Bent- Replaced	\$0.00
<b>Total</b>	<b>\$0.00</b>

Lessee: Junction City Mining  
Contract: 502-7625241-010

Unit: 2017 Volvo A40


UNIT # 342113  
Location: ASC Construction  
Equipment, Buford GA



Lessee: Junction City Mining  
Contract: 502-7625241-010

Unit: 2017 Volvo A40

UNIT # 342113  
Location: ASC Construction  
Equipment, Buford GA



**Lessee: Junction City Mining  
Contract: 502-7625241-010**

**Unit: 2017 Volvo A40**

**UNIT # 342113  
Location: ASC Construction  
Equipment, Buford GA**

