

Lessee: PERRAULT
Contract: 502-5034955-016

Unit: 2015 Volvo EC300EL

UNIT # 0552
Location: Scott Equipment, Baton
Rouge LA



SPECIFICATIONS

VIN	0552
LeaseInspector ID #	0552
Year	2015
Model	Volvo EC300EL
Location City	Baton Rouge
Location State	LA
General Specifications	
New Hours	2864
Old Hours	2875

Lessee: PERRAULT
Contract: 502-5034955-016

Unit: 2015 Volvo EC300EL

UNIT # 0552
Location: Scott Equipment, Baton
Rouge LA

**ADDITIONAL FEATURES OF THIS
VEHICLE
COMMENTS**

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes

Overall: Fair

Lessee: PERRAULT
Contract: 502-5034955-016

Unit: 2015 Volvo EC300EL

UNIT # 0552
Location: Scott Equipment, Baton
Rouge LA


DEFICIENCY REVIEW

ITEM	QTY	PRICE
1. Clean Machine Inside and Out, Engine and Undercarriage- Repaired		\$0.00
2. Service Machine if Due- Repaired		\$0.00
3. Transmission High Speed Inop- Repaired		\$0.00
4. Missing1 Bolt on Side Cutter- Replaced		\$0.00
5. Left Side Mirror Glass Missing- Replaced		\$0.00
Total		\$0.00

Lessee: PERRAULT
Contract: 502-5034955-016

Unit: 2015 Volvo EC300EL

UNIT # 0552
Location: Scott Equipment, Baton
Rouge LA



Lessee: PERRAULT
Contract: 502-5034955-016

Unit: 2015 Volvo EC300EL

UNIT # 0552
Location: Scott Equipment, Baton
Rouge LA

