# **VOLVO - INSPECTION REPORT**

# Volvo, Ec250e - Track Excavators

#### **Images**

















Comment:

Country: US Date: 03/26/2019 Make: Volvo

Serial number: 310102

Dealer: Arnold Machinery Company

Inspector: Mike seifert Model: Ec250e Engine S/N: 11706975 Location: Las vegas Year: 2015 Hours: 2828 Matris hours: 2828

Comment:

## **Equipped Configuration**

[X]Yes EROPS

[X] Yes Air conditioning [ ] Yes Stick short

Yes Stick medium

] Yes 2 Piece boom

Yes Long reach arrangement

] Yes Drill arrangement

Yes Recycling arrangement

Yes Demolition arrangement

] Yes Mass excavator arrangement

[ ] Yes Forestry arrangement

[ ] Yes Cab risers

[ ] Yes Cab riser hydraulic

[X]Yes Standard car body

] Yes Hydraulic retractable UC

[X] Yes Auxiliary hydraulics

1 Yes Hose rupture valves

[X] Yes Boom float

1 Yes Attachment circuits

] Yes Leveling blade

] Yes Cushion boom cylinder

[X] Yes Proportional joystick controls

[X] Yes Joystick controls

] Yes Thumb - Manual

] Yes Thumb hydraulic

] Yes Counterweight removal sys.

] Yes Long undercarriage

] Yes Quick coupler manual

[X] Yes Quick coupler hydraulic

] Yes Auto Lube

[X] Yes Travel pedal

## **Operators Station**

Comment:

Seat and armrest [X] Good

Dash and console [X] Good

Floor Board/Mat [X] Good

Cab glass [X] Good

Mirrors [X] Good

Interior light [X] Good

Switches	[X] Good
Wipers	[X] Good
Gauges	[X] Good
Hydraulic controls	[X] Good
Powertrain controls	[X] Good
AC cooling	[X] Good
CAB Interior	[ X] Fair Remarks: Needs cleaned
Operators station condition summary	
Comment:	
Outside appearanc	ee
Steps	[X] Good
Hand rails	[X] Good
Counterweight /	[ ] Good [ ] Fair [ ] Poor Remarks:
Bumper	
Grill	[X] Good
Hood	[X] Good
Exhaust stack	[X] Fair Remarks: Needs paint
Pre-cleaner bowl	[X] Good
Front fenders	[X] Good
Hyd tank	[X] Good
Fuel tank	[X] Good
Car body	[X] Fair Remarks: Needs paint
Fenders	[X] Good
OEM Welds	[X] Good
Sheet metal	[X] Good [X] Fair Remarks: Rear pump door severely bent needs hinge as well
Sneet metal	[X] Fall Remarks. Indea pump door severely bent needs fillinge as well
Paint	[ X] Fair Remarks: Needs paint high gloss paint peeling off
Outside appearance condition summary	
Comment:	
Safety condition	
Safety decals in place	[X]Yes
Operators manual	[X]Yes
Safety handles	[X] Good
Seat belt	[X] Good
Horn	[X] Good
Back up alarm	[X] Good

Brake hold	[X] Good
ROPS Structure	[X] Good
Guarding	[X] Good
CAB	[X] Good
Safety condition summary	
Comment:	
Electrical condition	
Computer	[X] Good
ECM'S	[X] Good
Monitor / Display	[X] Good
Wiring harness's	[X] Good
Key switch	[X] Good
Switches	[X] Good
Lighting	[X] Good
Engine preheater	[X] Good
Batteries / Connections	
Battery disconnect	[X] Good
switch Electrical condition summary	
Comment:	
Engine condition	
Oil level OK	[X]Yes
Water in oil	
Compression	[X]No
	[X] No [X] Yes
Blow by	
Blow by Engine knocking	[X]Yes
	[X]Yes [X]No
Engine knocking	[X] Yes [X] No [X] No
Engine knocking CE PLATE	[X] Yes [X] No [X] No [X] Yes
Engine knocking CE PLATE Oil pressure	[X] Yes [X] No [X] No [X] Yes [X] Good
Engine knocking CE PLATE Oil pressure Oil leaks	[X] Yes [X] No [X] No [X] Yes [X] Good [X] No
Engine knocking CE PLATE Oil pressure Oil leaks EPA DECAL	[X]Yes [X]No [X]No [X]Yes [X]Good [X]No [X]Yes
Engine knocking CE PLATE Oil pressure Oil leaks EPA DECAL Turbo charger	[X]Yes [X]No [X]No [X]Yes [X]Good [X]No [X]Yes [X]Good
Engine knocking CE PLATE Oil pressure Oil leaks EPA DECAL Turbo charger Exhaust manifold	[X]Yes [X]No [X]No [X]Yes [X]Good [X]No [X]Yes [X]Good [X]Good
Engine knocking CE PLATE Oil pressure Oil leaks EPA DECAL Turbo charger Exhaust manifold Muffler	[X] Yes [X] No [X] No [X] Yes [X] Good [X] No [X] Yes [X] Good [X] Good [X] Good

Fan guard	[X] Good	
Belts & pulleys	[X] Good	
Wiring harness	[X] Good	
Starter	[X] Good	
Alternator	[X] Good	
Seals & gaskets	[X] Good	
Engine mounts	[X] Good	
Brackets	[X] Good	
AC Compressor	[X] Good	
Air filters	[X] Good	
Engine condition summary		
Comment:		
Cooling system		
Coolant color		
Radiator	[X] Good	
Water pump	[X] Good	
Oil cooler	[X] Good	
Fan	[X] Good	
Fan drive	[X] Good	
Hoses	[X] Good	
Cooling system summary		
Comment:		
Hydraulics condit	ion	_
Boom cylinders	[X] Good	
Stick cylinders	[X] Good	
Bucket cylinders	[X] Good	
Blade cylinders	[X] Good	
Thumb cylinders	[ ] Good [ ] Fair [ ] Poor Remarks:	
Pumps	[X] Good	
Valves	[X] Good	
Hoses	[X] Good	
Fittings	[X] Good	
Tank	[X] Good	
Swing bearing	[X] Good	
Swing bearing Swing gear	[X] Good	
Cming godi	[7] 5000	

Swing motor	[X] Good
Hydraulic swivel	[X] Good
Travel motors	[X] Good
Pump drive	[X] Good
Planetaries left	[X] Good
Planetaries right	[X] Good
Controls	[X] Good
Overall condition	[X] Good
Summary	
Comment:	
Comment.	
Boom & arm cond	dition
Lower stick pins	[X] Good
Lower stick pins	[ \( \) \( \) \( \)
Upper stick pins	[X] Good
Chiale aanditian	[VICeed
Stick condition	[X] Good
Stick length	2.97 meters
Boom length	6.0 meters
Boomichgai	o.u meters
Lower boom pins	[X] Good
Upper boom pins	[X] Good
Boom condition	[X] Good
Summary	
Comment:	
Bucket & other at	ttachments
Bucket & Other at	
Bucket type / Size	Volvo 23inch
Coupler type	Volvo
	VOIVO
Bucket serial	Missing
Coupler serial	25629
Bucket W / Teeth	[X]Yes
Addtl attachments	
Bolt on smooth	[X] No
Bolt on edge	[X] Good
Bucket mounts	[X] Good
Bucket teeth /	[X] Good
Segments	[7,] 5000
20351110	
Bucket sides	[X] Good
Bucket floor	[X] Good

Bucket bottom	[X] Fair Remarks: Small dent
Coupler	[X] Good
Boom / Frame	[X] Good
Boom / Bucket pins & bushings	[X] Fair Remarks: Pins a little long
Summary	
Comment:	
Undercarriage con	dition
Roller frame right	[X] Good
Roller frame left	[X] Good
Track adjusters	[X] Good
Overall condition	[X] Good
Links left	
Links left	
Internal pin wear left	
Internal pin wear left	
External pin wear left	
External pin wear left	
Trackshoe/ Grouser left	
Trackshoe/ Grouser left	
Front Idler left	
Front Idler left	
Sprockets left	
Sprockets left	20%
Front Carrier Rollers left	
Front Carrier Rollers left	20%
Center Carrier Rollers left	
Center Carrier Rollers left	20%
Poor Carrior Pollors	

left

Rear Carrier Rollers left	20%			
Links right				
Links right	20%			
Internal pin wear right				
Internal pin wear right	20%			
External pin wear right				
External pin wear right	20%			
Trackshoe/ Grouser right				
Trackshoe/ Grouser right	20%			
Front Idler right				
Front Idler right	20%			
Sprockets right				
Sprockets right	20%			
Front Carrier Rollers right				
Front Carrier Rollers right	20%			
Center Carrier Rollers right				
Center Carrier Rollers right	20%			
Rear Carrier Rollers right				
Rear Carrier Rollers right	20%			
Bottom rollers S or D				
Undercarriage brand				
Link part number				
Pins & bushings turned	ı			
Comment:				
Bottom rollers S or	r D			
Bottom rollers S		Bottom rollers S or D left (%)	Bottom rollers S or D right (mm)	
Bottom rollers S	mm	30% Bottom rollers S or D left (mm)	mm Bottom rollers S or D left (%)	
30%		mm	30%	
Bottom rollers S  Bottom rollers	mm	Bottom rollers S or D right (%)  Bottom rollers S or D right (mm)	Bottom rollers S or D left (mm)  mm  Bottom rollers S or D right (%)	
30%		mm	30%	
Bottom rollers S	or D left (mm)	Bottom rollers S or D left (%)	Bottom rollers S or D right (mm) mm	
Bottom rollers S		Bottom rollers S or D left (mm)	Bottom rollers S or D left (%) 30%	

Bottom rollers S or D right (mm)	Bottom rollers S or D right (%)	Bottom rollers S or D left (mm)
mm	30%	mm
Bottom rollers S or D left (%)	Bottom rollers S or D right (mm)	Bottom rollers S or D right (%)
30%	mm	30%
Bottom rollers S or D left (mm)	Bottom rollers S or D left (%)	Bottom rollers S or D right (mm)
mm	30%	mm
Bottom rollers S or D right (%)	Bottom rollers S or D left (mm)	Bottom rollers S or D left (%)
30%	mm	30%
Bottom rollers S or D right (mm)	Bottom rollers S or D right (%)	Bottom rollers S or D left (mm)
mm	30%	mm
Bottom rollers S or D left (%)	Bottom rollers S or D right (mm)	Bottom rollers S or D right (%)
30%	mm	30%
Bottom rollers S or D left (mm)	Bottom rollers S or D left (%)	Bottom rollers S or D right (mm)
mm	30%	mm
Bottom rollers S or D right (%)		
30%		
Comment: Rail sprocket and	roller replace possibly needed 1 groused needed	bent
Odminant.		
0		
General Comments		
Legend (5 star rating) [ ] 5 [ ] 4 [ ]	3 [ ]2 [ ]1	
Paint general [ ] Good [ ] Fa	air [ ] Poor Remarks:	
Comment:		