Serial #: 342062

Outside PCS Phosphate Mine Aurora, NC 336-420-7221

- Rear vision system
- Air ride seat
- Air conditioning
- Rotating beacon
- Tailgate
- SMU/Hours: 6039
- Overall: Fair

- Radio
- Differential locks
- Computer display
- Mudflaps
- Engine jake brake
- Start Run: Yes
- Insp Date: 8/15/2019



(Continued)

General Appearance

Radiator G	rille:	Good	Precleaner I	bowl:	Good
Radiator Si	hroud:	Good	Fuel Tank:		Good
Engine End	closure:	Good	Cab Doors:		Good
Hood:		Good	Bumper:		Fair
Stack:		Good	Cab:		Good
Right front	fender:	Good	Steps:		Good
Left front fo	ender:	Good	Grab Irons/I	Handrails:	Good
Rear frame	:	Good	Paint:		Good
Front frame	e:	Good	Oil Sample	Taken:	No
LEGEND OF	CONDITIONS:		,		
Excellent -	New condition.	No Repairs Necessary.	Poor -	Obvious we necessary.	ar and/or damage. Repairs
Good -		ear or damage, Functions/Opera epairs Necessary.	ates Not Applicable	e - Does not ap	pply to this unit
Fair -		amage apparent. Functions, but Repairs recommended.			

(Continued)

Interior Section

Glass:	Good	Neutral Start Switch:	Good	
Mirrors:	Good	Fire Suppression System:	Good	
Seat Belt:	Good	Horn:	Good	
Back Up Alarm:	Good			
Fan Guards:	Good			
NOTES:		•		
OPERATOR AREA:				
Dash Console:	Good	Seat Cushion:	Good	
Meter:	Good	Arm Rests:	Good	
Gauges:	Good	Floor Boards/Mats:	Good	
Control Pattern Decals:	Good	EMS Panel:	Good	
Switches:	Good	Warnings:	Good	
Windshield Wipers:	Good	Door Latches:	Good	
Heater:	Good	Current Parts Manual:	No	
A/C:	Good	Current Safety Manual:	No	
Interior Lights:	Good	Current O&M Manual:	No	

(Continued)

Power Systems

Engine Make Model:	Volvo D13J	Oil Pressure:	Normal	
Engine S/N:	693489	Smoke:	No	
Engine Hours:	6039	Smoke Color:	Light	
Oil Leaks:	No	TurboCharger:	Good	
Blow-by:	No	Fuel Injection System:	Good	
Knocking:	No	Governor:	Good	
Compression in Radiator:	No	Engine Supports:	Good	
Water in Oil:	No	Air Cleaners:	Good	
Fluid Level OK?:	Yes			
Anit-Freeze Color:	Red			
NOTES:		•		
COOLING SYSTEM:				
Radiator:	Good	Fan:	Good	
Coolers:	Good	Fan Drive:	Good	
Hoses:	Good	Belts:	Good	
Water Pump:	Good	Pulleys:	Good	
NOTES:				
ELECTRICAL SYSTEM:				
Batteries:	Good	Wiring:	Good	
Battery Cables:	Good	Pre-Heater:	Good	
Starter:	Good	Lighting:	Good	
Alternator:	Good			

(Continued)

Power Systems - Continued

Transmission Serial #:	-	Seals:	Good	
Transmission Type:	Auto	Torque Converter:	Good	
Transmission Speeds:	9	Temp/Pressure Gauges:	Good	
Transmission Forward:	Good	Transmission Fluid:	Good	
Transmission Reverse:	Good	Is the Transmission Noisy?:	No	
Case:	Good	Transmission Retarder:	Yes	
Controls:	Good			
NOTES:		•		
STEERING:				
Steering Linkage:	Good	Left steering cylinder:	Good	
Steering Valve:	Good	Right steering cylinder:	Good	
Steering Pump:	Good	Steering joints:	Good	
Articulation P & B:	Good			
NOTES:				
BRAKE:				
Mechanism:	Wet	Lines:	Good	
Туре:	Pedal	Compressor:	Good	
Perfomance:	Good	Brake linkage:	Good	
Brake drums:	Not Available	Master cylinder:	Good	
Rotors:	Good	Parking brake:	Good	
Control Valve:	Good			
NOTES:				
DRIVE TRAIN:				
Front axle:	Good	Rear axle housing:	Good	
Front differential:	Good	U-Joints:	Good	
Rear axles:	Good	Front suspension:	Good	
Rear differentials:	Good	Rear suspension:	Good	
Front wheel lugs & rims:	Good	Front a-stay:	Good	
Rear wheel lugs & rims:	Good	Rear a-stay:	Good	
Front axle bolts:	Good			
Rear axle bolts:	Good			
Front axle housing:	Good			

(Continued)

Hydraulics

Right dump cylinder:	Good	Valves:	Good	
Left dump cylinder:	Good	Control linkage:	Good	
Hose lines:	Good	Reservoir:	Good	
Pumps:	Good	Dump cycle test:	Good	

(Continued)

Dump Body

Body type:	Dump	Body pins and bushings:	Good	
Body bottom:	Good	Body liner:	Not Available	
Body sides:	Fair	Tail gate adapter:	Good	
Rubber pads:	Good	Tail gate:	Fair	
Body mounts:	Good	Front spill guard:	Good	

(Continued)

Tires

TIRES:					
Front Tire Size:	Left: 29.5R25 - 74%	Right: 29.5R25 - 74%	Rear Tire Size 1:	Left: 29.5R25 - 74%	Right: 29.5R25 - 78%
Front Tire Brand:	Left: Michelin	Right: Michelin	Rear Tire Brand 1:	Left: Michelin	Right: Michelin
Front Tire Radial or Bias:	Left: Radial	Right: Radial	Rear Tire Radial or Bias:	Left: Radial	Right: Radial
Front Tire Measurement:	Left: 41/32	Right: 41/32	Rear Tire Measurement 1:	Left: 41/32	Right: 43/32
			Rear Tire Size 2:	Left: 29.5R25 - 74%	Right: 29.5R25 - 72%
			Rear Tire Brand 2:	Left: Michelin	Right: Michelin
			Rear Tire Radial or Bias:	Left: Radial	Right: Radial
			Rear Tire Measurement 2:	Left: 41/32	Right: 40/32
NOTES: Tread Depth Wear Based Or	n 55/32nds New				

(Continued)

Comments


COMMENTS:			
Public Comments:			

(Continued)

Reconditioning

DE	FICIENCY REVIEW:	
	ITEM	QTY PRICE
1.	+ Rear Main Seal Seeping	\$0.00
2.	+ Both Top Rails Bent	\$0.00
4.	+ Right Front Steering Tire Cut, Gouged, Rubber Missing	\$0.00
5.	+ Manuals Missing	\$0.00
8.	+ Deidentify	\$0.00
10.	dealer to determine if service is due	\$0.00
To	tal	\$0.00


(Continued)



(Continued)



(Continued)



(Continued)



(Continued)

